School Assessment Report



District: Southgate Ind

School: Southgate ES MS

Report: Nov 20, 2011

Condition Assessment: May 16, 2011

Suitability/Technology Assessment: Sep 02, 2011

Table of Contents

Executive Summary	3
Condition Budget Summary	3
Suitability and Technology Summary	5
Capacity and Utilization	7
Enrollment Projection	8
Buildings	9
Building: Main	9
Building Condition Budget Summary	9
Building Condition Budget Detail	9
Building Deficiency Priority	11
Building Condition Deficiencies	12
Building Condition Deficiencies Narrative	13
Building: Add-1995	27
Building Deficiency Condition Budget Summary	27
Building Deficiency Condition Budget Detail	27
Building Deficiency Priority	28
Building Deficiencies Budget Detail	29
Building Deficiencies Budget Narrative	30
Appendix 1 - Assessment Criteria	38
Glossary	42

Executive Summary

School Name: Southgate ES MS

_	
Number of Buildings:	1
Gross Area (SF):	27,783
Replacement Value:	\$5,839,545
Condition Budget:	\$3,877,508
Total FCI:	66.40%
Suitability Budget:	\$1,447,215
Technology Budget:	\$30,964
Total RSLI:	10%
Total KFI:	91.71%
Condition Score:	33.60
Technology Score:	70.00
Suitability Score:	29.19
School Score:	34.54



Summary:

Southgate Publid School was constructed in 1903, and additions to the main school building were constructed in 1930, 1980 (890 sq.ft.), and 1995. A new addition of 4 classrooms broke ground in May 2011. This report contains condition and adequacy data collected during the 2011 KDE Facility Inventory and Classification System. The detailed condition and deficiency statements are contained in this report for each building and site improvements on the campus.

Condition Budget Summary

Condition Narrative:

Southgate Publid School was constructed in 1903, and additions to the main school building were constructed in 1930, 1980 (890 sq.ft.), and 1995. A new addition of 4 classrooms broke ground in May 2011. This report contains condition and adequacy data collected during the 2011 KDE Facility Inventory and Classification System. The detailed condition and deficiency statements are contained in this report for each building and site improvements on the campus.

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted useful life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.


Following are the cost model's system details for this facility. The Remaining Service Life Index (RSLI), also known as the Condition Index (CI), is calculated as the sum of a renewable system's Remaining Service Life (RSL) divided by the sum of a system's Replacement Value (both values exclude softcost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new system) to 0.00% (system expired). The System Condition Index (SCI) is the ratio of a system's current condition deficiency costs to its replacement value - also known as "percent used" ranging from 0 percent to 100 percent or greater due to the addition of the system's renewal premium, the additional costs to prepare for the system's renewal such as demolition costs. The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the cortrective actions due to packaging the work.

Uniformat Classification RSLI SCI Condition Budget

Uniformat Classification	RSLI	SCI	Condition Budget
A10 Foundations	0%	0.00%	\$0
A20 Basement Construction	0%	0.00%	\$0
B10 Superstructure	0%	0.00%	\$0
B20 Exterior Enclosure	10%	43.14%	\$263,524
B30 Roofing	0%	110.00%	\$366,077
C10 Interior Construction	9%	40.89%	\$125,599
C20 Stairs	0%	0.00%	\$0
C30 Interior Finishes	8%	95.47%	\$623,596
D10 Conveying	0%	110.00%	\$75,831
D20 Plumbing	22%	92.59%	\$247,504
D30 HVAC	11%	101.02%	\$1,120,627
D40 Fire Protection	0%	108.24%	\$144,598
D50 Electrical	22%	75.87%	\$503,740
E10 Equipment	55%	30.63%	\$7,724
E20 Furnishings	10%	92.05%	\$58,098
G20 Site Improvements	24%	87.86%	\$197,527
G30 Site Mechanical Utilities	34%	92.13%	\$57,091
G40 Site Electrical Utilities	23%	92.07%	\$85,972
		Total:	\$3,877,508

Condition Deficiency Priority

Building					Condition	n Budget		
/Site	GSF	FCI	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
Main	23,314	74.8%	\$0	\$17,463	\$3,479,796	\$0	\$165,562	\$3,662,821
Add-1995	4,469	22.7%	\$0	\$0	\$182,435	\$0	\$32,251	\$214,686
Total:	27.783	66.4%	\$0	\$17,463	\$3,662,231	\$0	\$197.814	\$3,877,508



School Condition Budget: \$3,877,508

Suitability and Technology Summary

The educational suitability assessment of a school facility is a measure of how well the building(s) and grounds support and enhance the educational programs being offered. The assessment evaluates multiple systems or categories. Some of these are school-wide, like learning environment, while others are focused on specific space types such as art rooms. Some systems or categories are found in all types of schools, such as general classrooms, while others are specific to certain grade configurations, like preschool classrooms. Each school receives an educational suitability score based on a 100 point scale developed as a percentage of possible points for all scored suitability categories.

The educational suitability assessment team evaluated the adequacy of the specific space types in each school model, e.g., general classrooms, science rooms, support spaces, etc. The possible score for each space type was weighted based on that space type's proportion of the total area of the school model. Consequently, general classrooms in an elementary school receive more possible points than general classrooms in a high school, since they represent a greater proportion of the total space.

Suitability Scoring

The suitability scoring system includes additional educational suitability categories that cannot always be weighted based on simple square footage. Some examples of these categories include ease of supervision, learning environment, pedestrian traffic, and others. The weightings of these categories were determined through field work by experienced educators and architects and reflect each category's relative importance in that particular model. The points assigned a specific educational suitability category in one model may differ from another model. A comparison of the points assigned to a specific educational suitability category across models is not appropriate because the size and proportion of spaces will be different based on the type of school. For example, an auditorium is typical at a high school, but elementary and middle schools may have multi-purpose spaces (e.g., "cafegymtoriums"). The points assigned to these spaces are likely to be different.

Another aspect of the suitability scoring system is that the weights assigned to the categories are expressed in numbers to two decimal points. This is due to several factors. Using a 100 point scale to review numerous educational suitability systems and categories, many of the point assignments are a fraction of a whole number. Expanding point assignments to two decimals allows the system to reflect the original logic of basing the suitability scoring on square footage and relative importance, and facilitates consistent sums when adding to arrive at a total suitability score.

Suitability Budget

The budget for correcting educational suitability deficiencies is intended to be used as an estimate for correcting the overall educational suitability needs of a facility and not as a means to develop cost estimates for individual deficiencies. Experience has shown that it is difficult to calculate the cost of correcting items such as classrooms that are sized incorrectly, spaces with inappropriate adjacencies, lack of a variety of teaching and learning spaces, etc. The remediation of these deficiencies can take a variety of forms and requires a design study before accurate cost calculations can be made. A budget was developed for suitability improvements based on the overall suitability score of a particular school and team experience in correcting the overall deficiencies based on that score. Suitability Budget needs for each facility are included in the report and should be used as a starting place for long range planning.

Much like a facility condition index, the inverse of the suitability score is a measure of the value of the building which should be reinvested to remediate the deficiencies. The Kentucky Facilities Inventory and Classification System (KFICS) includes a model which is adequate to develop budget projections for remediating educational suitability deficiencies. The model is as follows:

Kentucky Suitability Index (KSI) = (1.0 - Suitability Score (%))

KSI x .35 x School Current Replacement Value (CRV) =Total Suitability Budget Needs

The KSI budget projection of 35% of the Current Replacement Value is based on several factors:

First, the remediation of educational suitability deficiencies may be accomplished in a number of ways. For instance, remediating a classroom which does not meet the size standard for a given number of students can be "fixed" by, on one extreme, lowering the class size which costs no capital dollars, and on the other extreme, by building a new classroom, which would cost 100% of the replacement cost. Most often, the solution is to carve out some additional space, or combine three classrooms into two by removing the internal walls. Consequently, the cost of remediation is most often less than 100% of the replacement cost and our experience has shown that the 35% factor is an effective planning parameter.

Second, the fact that these deficiencies are typically remediated along with building condition deficiencies and often overlap in scope of work and cost. Budgets for both assessments at 100% of the replacement cost would likely result in excessive budgets.

The report below provides information about the Educational Suitability of this school, based on the Criteria in Appendix 1. Each area was scored 1 through 5, or "NA" with 1 being the high score. Items are scored "NA" if they are not appropriate to that school program (e.g., football fields at an elementary school or preschool at a high school) or are not needed at a school (e.g., no computer lab at a school where every student has a laptop). All scores are shown. However, the suitability deficiency budget reflects only the deficiencies identified with scores of 2 or lower.

Suitability Narrative:

Southgate Public Schools houses grades preschool through 8. The building is a two-story structure that was constructed during four different time periods. The school is currently undergoing construction to add additional classrooms.

Suitability Category Scoring Summary

Task No	Task Description	Score
5110	Support Spaces	10.26
5111	Learning Environment	50.00
5115	General Classrooms	31.75
5120	Kindergarten	71.75
5125	ECE	29.50
5130	Self-Contained Special Ed	0.00
5135	Instructional Resource Rooms	71.75
5140	Science	0.00
5145	Music	0.00
5150	Art	31.76
5155	Career Tech Ed	0.00
5160	Computer Labs	80.00
5165	P.E.	35.50
5170	Performing Arts	0.00
5175	Media Center	22.00
5188	Outside	7.15
5193	Safety and Security	44.59

Southgate ES MS Suitability Budget Total: \$1,447,215

Technology Narrative:

Some of the technology infrastructure is designed and implemented using current KIDS or industry standards but there may be aged equipment which impedes system functionality. Wireless networks are available but there may be insufficient access points to provide connectivity to all administrative and instructional areas. Technology spaces may lack appropriate electricity, ventilation and cooling. High speed bandwidth may be limited and /or intermittent and may not provide the necessary capacity for administrative or educational functions. Administrative and educational programs are somewhat impacted because of the current technology infrastructure.

Technology Category Scoring Summary

Task No	Task Description	Score
5514	Technology Readiness ES	70.00

Southgate ES MS Technology Budget Total: \$30,964

Capacity and Utilization

The capacity of a facility is defined as the number of students the facility can accommodate. The capacity is calculated using the Kentucky Department of Education's (KDE) capacity model which totals the number of general classrooms contained in the school, and then multiplies this total by the number of students in each classroom to arrive at a net capacity. The number of students per classroom is set at 25 for all grade levels. The net capacity is then divided by a scheduling factor to arrive at the functional capacity. The scheduling factors are 100% for elementary schools, and 75% for middle and high schools. Utilization is calculated by dividing the number of students enrolled at the school by its capacity.

Southgate ES MS

Capacity

Room Type	# of Units	Students/Room	Capacity
PreSchool	1	0	0
Elementary Classroom (K-3)	4	25	100
Elementary Classroom (4)	0	25	0
Classroom (5-6)	2.5	25	62.5
Secondary Classroom (7-12)	2.5	25	62.5
Art (Secondary)	1	0	0
Music (Secondary)	0	0	0
Science Lab (Secondary)	0	0	0
Career Tech Ed Voc Foods Etc.	0	0	0
PE (Secondary)	1	0	0
Computer Lab (Secondary)	1	0	0
Spec. Ed Self Contained	0	0	0
Resource	4	0	0
Alternative HS	0	25	0
Portable	2	0	0

Total Capacity (w/o scheduling factor) = 225

÷ Scheduling/Grouping Factor = 100%

Functional Capacity = 225

Enrollment Projection

Enrollment projections are merely an *estimate* of future activity based on the historical data and information provided. These numbers can be highly accurate, but it must be remembered that the numbers are still a projection or estimate. During the implementation of any of the recommendations provided, it is critical that the school reassess these numbers on a regular basis and adjust plans accordingly.

Southgate ES MS


Historical Enrollment

Grade	2005-06	2006-07	2007-08	2008-09	2009-10	2010-11
Kindergarten	25	20	9	23	36	33
1	14	15	20	10	29	22
2	14	15	17	22	19	26
3	14	15	13	18	36	11
4	20	14	17	14	24	35
5	20	20	16	16	18	23
6	15	17	22	15	21	22
7	18	17	16	19	16	21
8	16	17	18	16	25	17
Subtotal	156	150	148	153	224	210

Projected Enrollment

Grade	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	2020-21
Kindergarten	36	39	68	95	104	117	143	174	213	262
1	28	41	73	87	110	139	178	228	294	381
2	31	36	34	39	44	48	54	60	66	74
3	7	8	13	23	26	29	31	34	36	40
4	51	73	92	106	118	130	150	175	204	237
5	28	33	36	36	33	32	33	34	35	36
6	25	29	34	31	34	38	41	45	48	53
7	25	28	25	27	27	27	28	29	30	31
8	14	11	22	23	25	26	26	27	29	30
Subtotal	245	298	397	467	521	586	684	806	955	1144

School Projected PK-8 Enrollment



^{**} EC Students are not used in the development of the projections.

Buildings

Building Name: Main

Year Built: 1903 Gross Area (SF): 23,314

Building Condition Budget Summary

Building condition is evaluated based on the constructed physical elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is used to construct a building cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and predicted next renewal date. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on a system's or component's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the systems detail for this facility.

Uniformat Classification	RSLI	SCI	Condition Budget
A10 Foundations	0%	0.00%	\$0
A20 Basement Construction	0%	0.00%	\$0
B10 Superstructure	0%	0.00%	\$0
B20 Exterior Enclosure	0%	51.56%	\$263,524
B30 Roofing	0%	110.00%	\$306,274
C10 Interior Construction	0%	48.86%	\$125,599
C20 Stairs	0%	0.00%	\$0
C30 Interior Finishes	0%	110.00%	\$601,129
D10 Conveying	0%	110.00%	\$63,471
D20 Plumbing	0%	110.00%	\$247,504
D30 HVAC	0%	110.00%	\$1,020,913
D40 Fire Protection	0%	107.96%	\$124,256
D50 Electrical	3%	90.66%	\$503,740
E10 Equipment	66%	32.44%	\$7,724
E20 Furnishings	0%	110.00%	\$58,098
G20 Site Improvements	0%	105.03%	\$197,527
G30 Site Mechanical Utilities	0%	110.00%	\$57,091
G40 Site Electrical Utilities	0%	110.00%	\$85,972
		Total:	\$3,662,821


Building Condition Budget Detail

		Unit		Install	Calc Next				Condition
Uniformat	System Description	Price	Life	Year	Renewal	Replacement	RSLI	SCI	Budget
A1010	Standard Foundations	\$5.68	100	1903	2003	\$173,409	-	0.00%	\$0
A1030	Slab on Grade	\$4.58	100	1903	2003	\$139,826	-	0.00%	\$0
A2010	Basement Excavation	\$0.14	100	1903	2003	\$4,274	-	0.00%	\$0
A2020	Basement Walls	\$2.09	100	1903	2003	\$63,807	-	0.00%	\$0
B1010	Floor Construction	\$10.50	100	1903	2003	\$320,562	-	0.00%	\$0
B1020	Roof Construction	\$8.02	100	1903	2003	\$244,848	-	0.00%	\$0
B2010	Exterior Walls	\$9.68	100	1903	2003	\$295,527	-	8.94%	\$26,431
B2020	Exterior Windows	\$6.50	30	1980	2010	\$198,443	0%	110%	\$218,287
B2030	Exterior Doors	\$0.56	30	1903	1933	\$17,097	0%	110%	\$18,806
B3010	Roof Coverings	\$9.12	20	1980	2000	\$278,431	0%	110%	\$306,274
C1010	Partitions	\$3.96	40	1903	1943	\$120,898	-	0.00%	\$0
C1020	Interior Doors	\$2.64	40	1903	1943	\$80,598	0%	80.00%	\$64,479
C1030	Fittings	\$1.82	20	1980	2000	\$55,564	0%	110%	\$61,120

			Unit		Install	Calc Next				Condition
C2010 Stair Construction \$2.54 40 1903 1943 \$77.545 - 0.00% \$0.000 \$0.000 \$104.412 0% 110% \$114.835 \$0.000 \$106.714 \$0.00 \$114.843 \$0.000 \$110.841 \$1.000 \$114.843 \$0.000 \$106.841 \$106.841 \$106.	Uniformat	System Description		Lifo			Ponlacomont	Dell	SCI	
C3010 Wall Friishes \$3.42 10 2000 2010 \$104.412 0% 110% \$114.853 C3020 Floor Finishes \$8.36 20 1980 2000 \$255.228 0% 110% \$205.526 D1010 Elevators and Lifts \$1.99 30 \$57.701 0% 110% \$205.526 D1010 Elevators and Lifts \$1.99 30 \$57.701 0% 110% \$205.526 D1010 Elevators and Lifts \$1.99 30 1980 2010 \$140.131 0% 110% \$63.471 D2010 Dylmbing Fixtures \$4.59 30 1980 2010 \$140.131 0% 110% \$154.144 D2020 Domestic Water Distribution \$0.45 30 1903 1933 \$13.738 0% 110% \$155.172 D2030 Sanitary Waste \$1.64 30 1903 1933 \$50.669 0% 110% \$55.076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$50.669 0% 110% \$55.076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$50.669 0% 110% \$55.076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$50.069 0% 110% \$55.076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$50.069 0% 110% \$59.067 D3040 Distribution Systems \$6.58 30 1900 2000 \$12.822 0% 110% \$214.105 D3020 Heat Generating Systems \$6.58 30 1980 2010 \$200.885 0% 110% \$220.974 D3040 Distribution Systems \$6.58 30 1980 2010 \$200.885 0% 110% \$221.925 D3050 Terminal & Package Units \$15.21 15 1980 1995 \$464.356 0% 110% \$510.792 D3060 Controls & Instrumentation \$16.11 20 1980 2000 \$49.153 0% 110% \$54.988 D3070 Systems Testing & Balance \$0.47 30 1980 2010 \$14.349 0% 110% \$54.784 D4010 Sprinklers \$5.077 30 \$5.190 0% 110% \$55.794 D4020 Standpipes \$0.17 30 \$5.190 0% 110% \$52.157 D4030 Fire Protection Specialties \$0.07 15 2000 2015 \$2.137 27% 0.00% \$0.00% \$0.00 D407 Fire Protection Specialties \$0.07 15 2000 2015 \$2.137 27% 0.00% \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0								KOLI		
C3020 Floor Finishes \$8.36 20 1980 2000 \$255,228 0% 110% \$280,751 C3030 Ceiling Finishes \$6.12 20 1980 2000 \$186,842 0% 110% \$205,526 D1010 Elevators and Lifts \$1.89 30 \$57,701 0% 110% \$53,471 D2010 Plumbing Fixtures \$4.59 30 1980 2010 \$140,131 0% 110% \$15,414 D2020 Domestic Water Distribution \$0.45 30 1903 1933 \$35,069 0% 110% \$55,076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$50,069 0% 110% \$95,076 D2090 Nat Gas \$0.27 30 1903 1933 \$8,243 0% 110% \$920,074 D3040 Distribution Systems \$6.58 30 1990 2010 \$200,885 0% 110% \$220,974 D3040 <td></td>										
C3030 Celling Finishes \$6.12 20 1980 2000 \$186,842 0% 110% \$205,526		11000								
Dilion Elevators and Lifts \$1.89 30 \$57,701 0% 110% \$53,471 D2010 Plumbing Fixtures \$4.59 30 1980 2010 \$140,131 0% 110% \$154,144 D2020 Domestic Water Distribution \$0.45 30 1903 1933 \$13,738 0% 110% \$55,176 D2040 Sanitary Waste \$1.64 30 1903 1933 \$50,069 0% 110% \$55,076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$8,243 0% 110% \$55,076 D2040 Rain Water Drainage \$0.27 30 1903 1933 \$8,243 0% 110% \$9,067 D2090 Nat Gas \$0.42 20 1980 2000 \$12,822 0% 110% \$14,105 D3020 Heat Generating Systems \$6.58 30 1980 2010 \$200,885 0% 110% \$220,974 D3040 Distribution Systems \$6.53 30 1903 1933 \$199,359 0% 110% \$221,9795 D3050 Terminal & Package Units \$15,21 15 1980 1995 \$464,356 0% 110% \$212,929 D3060 Controls & Instrumentation \$1.61 20 1980 2000 \$49,153 0% 110% \$54,088 D3070 Systems Testing & Balance \$0.47 30 1980 2010 \$14,349 0% 110% \$54,088 D4020 Standpipes \$2.87 30 \$87,620 0% 110% \$5,794 D4020 Standpipes \$0.17 30 \$87,663 0% 110% \$5,709 D4030 Fire Protection \$0.66 15 1980 1995 \$20,150 0% 110% \$5,709 D5020 Lighting and Branch Wiring \$1.24 9 30 1903 1933 \$381,316 0% 110% \$84,292 D5020 Lighting and Branch Wiring \$1.24 9 30 1903 1933 \$381,316 0% 110% \$84,292 D5020 Lighting and Branch Wiring \$1.24 9 30 1903 1933 \$381,316 0% 110% \$37,724 E1090 Other Equipment \$0.23 20 1995 2015 \$97,695 20% 0.00% \$0.00%							+,			
D2010 Plumbing Fixtures		,			1960	2000				+,
December					1000	2010				
D2030 Sanitary Waste \$1.64 30 1903 1933 \$50.069 0% 110% \$55.076										
D2040 Rain Water Drainage \$0.27 30 1903 1933 \$8,243 0% 110% \$9,067										
D2090 Other Plumbing Systems-D2090 \$0.42 bits 20 bits 1980 bits 2000 bits \$12,822 bits 0% bits 110% bits \$14,105 bits D3020 Heat Generating Systems \$6.58 30 1980 2010 \$200,885 0% 110% \$220,974 D3040 Distribution Systems \$6.53 30 1993 1933 \$199,359 0% 110% \$220,974 D3050 Terminal & Package Units \$15.21 15 1980 1995 \$464,356 0% 110% \$510,792 D3060 Controls & Instrumentation \$1.61 20 1980 2000 \$49,153 0% 110% \$54,068 D3070 Systems Testing & Balance \$0.47 30 1980 2010 \$14,349 0% 110% \$54,068 D4010 Sprinklers \$2.87 30 \$87,620 0% 110% \$96,382 D4020 Standpipes \$0.17 30 \$51,90 0% 110% \$96,382 D4030 Fire Protection \$0.07 15 2000 2015 \$2,137 27% 0.00% \$10 D4090 Systems \$0.66 15 1980 1995 \$20,150 0% 110% \$2,165 Electrical \$0.66 15 1980 1995 \$20,150 0% 110% \$449,47 D5010 Service/Distribution \$2.51 30 1903 1933 \$381,316 0% 110% \$449,47										
December	D2040	7	φυ.27	30	1903	1933	\$0,243	0%	110%	φ9,067
D3020 Heat Generating Systems \$6.58 30 1980 2010 \$200.885 0% 110% \$220.974	D0000		фо 40	20	4000	2000	¢40,000	00/	4400/	Ф4.4.40 г
D3040 Distribution Systems \$6.53 30 1903 1933 \$199,359 0% 110% \$219,295							7 /-			
D3050 Terminal & Package Units \$15.21 15 1980 1995 \$464,356 0% 110% \$510,792										
D3060 Controls & Instrumentation \$1.61 20 1980 2000 \$49,153 0% 110% \$54,068 D3070 Systems Testing & Balance \$0.47 30 1980 2010 \$14,349 0% 110% \$15,784 D4010 Sprinklers \$2.87 30 \$87,620 0% 110% \$96,382 D4020 Standpipes \$0.17 30 \$5,190 0% 110% \$5,709 D4030 Fire Protection D00 2015 \$2,137 27% 0.00% \$0 D4090 Systems \$0.66 15 1980 1995 \$20,150 0% 110% \$22,165 Electrical B0501 Service/Distribution \$2.51 30 1903 1933 \$76,630 0% 110% \$419,447 Communications and B0502 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and B0503<										
D3070 Systems Testing & Balance \$0.47 30 1980 2010 \$14,349 0% 110% \$15,784 D4010 Sprinklers \$2.87 30 \$87,620 0% 110% \$96,382 D4020 Standpipes \$0.17 30 \$5,190 0% 110% \$5,709 D4030 Fire Protection Specialties \$0.07 15 2000 2015 \$2,137 27% 0.00% \$0 D4090 Systems \$0.66 15 1980 1995 \$20,150 0% 110% \$22,165 Electrical Service/Distribution \$2.51 30 1903 1933 \$76,630 0% 110% \$419,447 Communications and Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$58,098 E2010 Fixed Furnishings \$1										
D4010 Sprinklers \$2.87 30 \$87,620 0% 110% \$96,382 D4020 Standpipes \$0.17 30 \$5,190 0% 110% \$5,709 D4030 Fire Protection Specialties \$0.07 15 2000 2015 \$2,137 27% 0.00% \$0 D4090 Systems \$0.66 15 1980 1995 \$20,150 0% 110% \$22,165 Electrical D5010 Service/Distribution \$2,51 30 1903 1933 \$76,630 0% 110% \$84,292 D5020 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and D5030 Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1995 2015 \$97,695 20% 0										
D4020 Standpipes \$0.17 30 \$5,190 0% 110% \$5,709 D4030 Fire Protection Specialties \$0.07 15 2000 2015 \$2,137 27% 0.00% \$0 D4090 Systems \$0.66 15 1980 1995 \$20,150 0% 110% \$22,165 Electrical Service/Distribution \$2,51 30 1903 1933 \$76,630 0% 110% \$84,292 D5020 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$57,724 E1020 Institutional Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E20					1980	2010				
D4030 Fire Protection Specialties \$0.07 15 2000 2015 \$2,137 27% 0.00% \$0										
D4090 Cystems \$0.66 15 1980 1995 \$20,150 0% 110% \$22,165 Electrical Belectrical Service/Distribution \$2.51 30 1903 1933 \$76,630 0% 110% \$84,292 D5020 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and Communications and Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888										
D4090 Systems \$0.66 15 1980 1995 \$20,150 0% 110% \$22,165 Belectrical Service/Distribution \$2.51 30 1903 1933 \$76,630 0% 110% \$84,292 D5010 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and Communications and D5030 Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888	D4030		\$0.07	15	2000	2015	\$2,137	27%	0.00%	\$0
Electrical Service/Distribution \$2.51 30 1903 1933 \$76,630 0% 110% \$84,292										
D5010 Service/Distribution \$2.51 30 1903 1933 \$76,630 0% 110% \$84,292 D5020 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and D5030 Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% <td>D4090</td> <td></td> <td>\$0.66</td> <td>15</td> <td>1980</td> <td>1995</td> <td>\$20,150</td> <td>0%</td> <td>110%</td> <td>\$22,165</td>	D4090		\$0.66	15	1980	1995	\$20,150	0%	110%	\$22,165
D5020 Lighting and Branch Wiring \$12.49 30 1903 1933 \$381,316 0% 110% \$419,447 Communications and Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1,73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1,11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2,77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463										
Communications and D5030 Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 11										
D5030 Security \$3.20 20 1995 2015 \$97,695 20% 0.00% \$0 E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G20	D5020		\$12.49	30	1903	1933	\$381,316	0%	110%	\$419,447
E1020 Institutional Equipment \$0.23 20 1980 2000 \$7,022 0% 110% \$7,724 E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851										
E1090 Other Equipment \$0.55 20 2010 2030 \$16,791 95% 0.00% \$0 E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020										
E2010 Fixed Furnishings \$1.73 20 1980 2000 \$52,816 0% 110% \$58,098 G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G30		Institutional Equipment								
G2010 Roadways \$1.11 50 1903 1953 \$33,888 0% 110% \$37,277 G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 <td></td>										
G2020 Parking Lots \$2.77 30 1903 1933 \$84,567 0% 110% \$93,024 G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575	E2010	Fixed Furnishings	\$1.73	20	1980	2000	\$52,816	0%	110%	\$58,098
G2030 Pedestrian Paving \$0.52 50 1903 1953 \$15,875 0% 110% \$17,463 G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G2010		\$1.11	50	1903	1953	\$33,888	0%	110%	\$37,277
G2040 Site Development \$0.74 30 1980 2010 \$22,592 0% 110% \$24,851 G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G2020	Parking Lots	\$2.77	30	1903	1933	\$84,567	0%	110%	\$93,024
G2050 Landscaping \$1.02 20 1980 2000 \$31,140 0% 80.00% \$24,912 G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G2030	Pedestrian Paving	\$0.52	50	1903	1953	\$15,875	0%	110%	\$17,463
G3010 Water Supply \$0.30 50 1903 1953 \$9,159 0% 110% \$10,075 G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G2040	Site Development	\$0.74	30	1980	2010	\$22,592	0%	110%	\$24,851
G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396		Landscaping								
G3020 Sanitary Sewer \$0.82 50 1903 1953 \$25,034 0% 110% \$27,538 G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G3010	Water Supply	\$0.30	50	1903	1953	\$9,159	0%	110%	\$10,075
G3030 Storm Sewer \$0.58 50 1903 1953 \$17,707 0% 110% \$19,478 G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G3020	Sanitary Sewer	\$0.82	50	1903			0%	110%	\$27,538
G4010 Electrical Distribution \$0.97 30 1903 1933 \$29,614 0% 110% \$32,575 G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396	G3030		\$0.58	50	1903				110%	
G4020 Site Lighting \$1.59 30 1903 1933 \$48,542 0% 110% \$53,396										\$32,575
							7 - / -			
	Total		\$160.29				\$4.893.603	1%	74.85%	\$3,662,821

Building Deficiency Priority


Deficiencies by Priority:



Main Condition Budget: \$3,662,821

Building Condition Deficiencies

Current deficiencies included systems or components that have reached or exceeded their intrinsic useful life or components of the systems that are in need of repair. Systems that have reached the end their intrinsic useful life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart includes all current condition deficiencies associated with this facility.



Main Condition Budget: \$3,662,821

Building Condition Deficiencies Narrative



System: B2020 - Exterior Windows

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was

installed in 1980. It has a 30-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$218,287

System: B2030 - Exterior Doors

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$18,806

System: B3010 - Roof Coverings

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.









Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$306,274

System: C1020 - Interior Doors

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 40-year service life

which expired in 1943.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs
Correction: Renew System

Correction: Renew System Qty: 1-Ea.

Condition Budget: \$64,479

System: C1030 - Fittings

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency


Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$61,120





System: C3010 - Wall Finishes

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 2000. It has a 10-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$114,853

System: C3020 - Floor Finishes

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$280,751

System: C3030 - Ceiling Finishes

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition

budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.









Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$205,526

System: D1010 - Elevators and Lifts
Analysis: The system is missing.

Recommendation: The system should be installed.

Deficiency

Location: Main
Distress: Missing
Category: Compliance

Priority: 5 - Does Not Meet Current Code and/or Guidelines

Notes: There is no Elevator in the school

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$63,471

System: D2010 - Plumbing Fixtures

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 30-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$154,144

System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1903. It has a 30-year service life

which expired in 1933.





Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$15,112

System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$55,076

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1903. It has a 30-year service life

which expired in 1933.

Recommendation: The system should be replaced.


Deficiency


Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.







System: D2090 - Other Plumbing Systems-Nat Gas

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

> components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$14,105

System: D3020 - Heat Generating Systems

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 30-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qtv: 1-Ea.

Condition Budget: \$220,974

System: D3040 - Distribution Systems

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition

budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.







Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$219,295

System: D3050 - Terminal & Package Units

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 15-year service life

which expired in 1995.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$510,792

System: D3060 - Controls & Instrumentation

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Condition Budget: \$54,068

Qty: 1-Ea.





System: D3070 - Systems Testing & Balance

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 30-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$15,784

System: D4010 - Sprinklers
Analysis: The system is missing.

Recommendation: The system should be installed.

Deficiency

Location: Main
Distress: Missing
Category: Compliance

Priority: 5 - Does Not Meet Current Code and/or Guidelines Notes: The school does not have a sprinkler system

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$96,382

System: D4020 - Standpipes
Analysis: The system is missing.

Recommendation: The system should be installed.

Deficiency

Location: Main
Distress: Missing
Category: Compliance

Priority: 5 - Does Not Meet Current Code and/or Guidelines Notes: The school does not have a sprinkler system

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$5,709

System: <u>D4030 - Fire Protection Specialties</u>

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015.







System: D4090 - Other Fire Protection Systems

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance

Guidelines for this system. The system was installed in 1980. It has a 15-year service life

which expired in 1995.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$22,165

System: D5010 - Electrical Service/Distribution

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qtv: 1-Ea. Condition Budget: \$84,292

System: D5020 - Lighting and Branch Wiring

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition

budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.





Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$419,447

System: D5030 - Communications and Security

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1980. It has a 20-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs Correction: Renew System

Qty: 1-Ea. Condition Budget: \$7,724

System: E1090 - Other Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2030.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1980. It has a 20-year service life

which expired in 2000.









Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$58,098

System: <u>G2010 - Roadways</u>
Analysis: The system is missing.

Recommendation: The system should be installed.

Deficiency

Location: Main Distress: Missing

Category: Capital Renewal
Priority: 3 - Necessary- 2-5 Yrs

Notes: There is no on-site parking or roadways. School is

land-locked, no place for parking facilities

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$37,277

System: G2020 - Parking Lots
Analysis: The system is missing.

Recommendation: The system should be installed.

Deficiency

Location: Main Distress: Missing

Category: Capital Renewal Priority: 3 - Necessary- 2-5 Yrs

Notes: There is no on-site parking or roadways. School is

land-locked, no place for parking facilities

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$93,024

System: G2030 - Pedestrian Paving

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 50-year service life

which expired in 1953.





Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance

Priority: 2 - Potentially Critical-12 months

Notes: Significant settlement and sidewalk cracks. Safety

Issue at the entrance to the Gym where the public

enters/exits.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$17,463

System: G2040 - Site Development

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 30-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$24,851

System: G2050 - Landscaping

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1980. It has a 20-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$24,912



System: G3010 - Water Supply

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 50-year service life

which expired in 1953.

Recommendation: The system should be replaced.

Photo is not available.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$10,075



System: G3020 - Sanitary Sewer

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance

Guidelines for this system. The system was installed in 1903. It has a 50-year service life

which expired in 1953.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qtv: 1-Ea. Condition Budget: \$27,538

System: G3030 - Storm Sewer

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition

budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 50-year service life

which expired in 1953.









Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$19,478

System: G4010 - Electrical Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$32,575

System: G4020 - Site Lighting

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1903. It has a 30-year service life

which expired in 1933.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$53,396



Building Name: Add-1995

Year Built: 1995 Gross Area (SF): 4,469

Building Deficiency Condition Budget Summary

Uniformat Classification	RSLI	SCI	Condition Budget
A10 Foundations	0%	0.00%	\$0
A20 Basement Construction	0%	0.00%	\$0
B10 Superstructure	0%	0.00%	\$0
B20 Exterior Enclosure	20%	0.00%	\$0
B30 Roofing	0%	110.00%	\$59,803
C10 Interior Construction	19%	0.00%	\$0
C20 Stairs	0%	0.00%	\$0
C30 Interior Finishes	16%	21.06%	\$22,466
D10 Conveying	0%	110.00%	\$12,360
D20 Plumbing	45%	0.00%	\$0
D30 HVAC	21%	55.04%	\$99,715
D40 Fire Protection	0%	110.00%	\$20,342
D50 Electrical	41%	0.00%	\$0
E10 Equipment	20%	0.00%	\$0
E20 Furnishings	19%	0.00%	\$0
G20 Site Improvements	49%	0.00%	\$0
G30 Site Mechanical Utilities	68%	0.00%	\$0
G40 Site Electrical Utilities	46%	0.00%	\$0
		Total:	\$214,686


Building Deficiency Condition Budget Detail

		Unit		Install	Calc Next				Condition
Uniformat	System Description	Price	Life	Year	Renewal	Replacement	RSLI	SCI	Budget
A1010	Standard Foundations	\$5.78	100	1995	2095	\$33,825	-	0.00%	\$0
A1030	Slab on Grade	\$4.66	100	1995	2095	\$27,271	-	0.00%	\$0
A2010	Basement Excavation	\$0.14	100	1995	2095	\$819	-	0.00%	\$0
A2020	Basement Walls	\$2.13	100	1995	2095	\$12,465	-	0.00%	\$0
B1010	Floor Construction	\$10.68	100	1995	2095	\$62,501	-	0.00%	\$0
B1020	Roof Construction	\$8.17	100	1995	2095	\$47,812	-	0.00%	\$0
B2010	Exterior Walls	\$9.86	100	1995	2095	\$57,702	-	0.00%	\$0
B2020	Exterior Windows	\$6.62	30	1995	2025	\$38,741	47%	0.00%	\$0
B2030	Exterior Doors	\$0.57	30	1995	2025	\$3,336	47%	0.00%	\$0
B3010	Roof Coverings	\$9.29	20	1995	2015	\$54,367	20%	110%	\$59,803
C1010	Partitions	\$4.02	40	1995	2035	\$23,526	-	0.00%	\$0
C1020	Interior Doors	\$2.68	40	1995	2035	\$15,684	60%	0.00%	\$0
C1030	Fittings	\$1.86	20	1995	2015	\$10,885	20%	0.00%	\$0
C2010	Stair Construction	\$2.57	40	1995	2035	\$15,040	-	0.00%	\$0
C3010	Wall Finishes	\$3.49	10	1995	2005	\$20,424	0%	110%	\$22,466
C3020	Floor Finishes	\$8.51	20	1995	2015	\$49,802	20%	0.00%	\$0
C3030	Ceiling Finishes	\$6.23	20	1995	2015	\$36,459	20%	0.00%	\$0
D1010	Elevators and Lifts	\$1.92	30			\$11,236	0%	110%	\$12,360
D2010	Plumbing Fixtures	\$4.67	30	1995	2025	\$27,330	47%	0.00%	\$0
D2020	Domestic Water Distribution	\$0.46	30	1995	2025	\$2,692	47%	0.00%	\$0
D2030	Sanitary Waste	\$1.67	30	1995	2025	\$9,773	47%	0.00%	\$0
	Other Plumbing Systems-								
D2090	Nat Gas	\$0.43	20	1995	2015	\$2,516	20%	0.00%	\$0

		Unit		Install	Calc Next				Condition
Uniformat	System Description	Price	Life	Year	Renewal	Replacement	RSLI	SCI	Budget
D3020	Heat Generating Systems	\$6.70	30	1995	2025	\$39,209	47%	0.00%	\$0
D3040	Distribution Systems	\$6.65	30	1995	2025	\$38,917	47%	0.00%	\$0
D3050	Terminal & Package Units	\$15.49	15	1995	2010	\$90,650	0%	110%	\$99,715
D3060	Controls & Instrumentation	\$1.64	20	1995	2015	\$9,598	20%	0.00%	\$0
D3070	Systems Testing & Balance	\$0.48	30	1995	2025	\$2,809	47%	0.00%	\$0
D4010	Sprinklers	\$2.92	30			\$17,088	0%	110%	\$18,797
D4020	Standpipes	\$0.17	30			\$995	0%	110%	\$1,094
D4030	Fire Protection Specialties	\$0.07	15	1995	2010	\$410	0%	110%	\$451
	Electrical								
D5010	Service/Distribution	\$2.54	30	1995	2025	\$14,864	47%	0.00%	\$0
D5020	Lighting and Branch Wiring	\$12.71	30	1995	2025	\$74,381	47%	0.00%	\$0
	Communications and								
D5030	Security	\$3.26	20	1995	2015	\$19,078	20%	0.00%	\$0
E1020	Institutional Equipment	\$0.24	20	1995	2015	\$1,405	20%	0.00%	\$0
E2010	Fixed Furnishings	\$1.76	20	1995	2015	\$10,300	20%	0.00%	\$0
G2010	Roadways	\$1.13	50	1995	2045	\$6,613	68%	0.00%	\$0
G2020	Parking Lots	\$2.81	30	1995	2025	\$16,445	47%	0.00%	\$0
G2030	Pedestrian Paving	\$0.53	50	1995	2045	\$3,102	68%	0.00%	\$0
G2040	Site Development	\$0.76	30	1995	2025	\$4,448	47%	0.00%	\$0
G2050	Landscaping	\$1.05	20	1995	2015	\$6,145	20%	0.00%	\$0
G3010	Water Supply	\$0.31	50	1995	2045	\$1,814	68%	0.00%	\$0
G3020	Sanitary Sewer	\$0.82	50	1995	2045	\$4,799	68%	0.00%	\$0
G3030	Storm Sewer	\$0.59	50	1995	2045	\$3,453	68%	0.00%	\$0
G4010	Electrical Distribution	\$0.98	30	1995	2025	\$5,735	47%	0.00%	\$0
G4020	Site Lighting	\$1.62	30	1995	2025	\$9,480	47%	0.00%	\$0
Total		\$161.64				\$945,942	30%	22.70%	\$214,686


Building Deficiency Priority

Deficiencies by Priority:



Add-1995 Condition Budget: \$214,686

Building Deficiencies Budget Detail



Add-1995 Condition Budget: \$214,686

Building Deficiencies Budget Narrative

System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: B3010 - Roof Coverings

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition

budget needs, the potential failure of its components, or in order to meet the performance

Guidelines for this system. The system was installed in 1995. It has a 20-year service life. However, in the assessment, it was found to be

currently deficient.

Recommendation: The system should be replaced.

Deficiency

Location: Add-1995

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Notes: Numerous roof leaks observed and reported

during assessment visit.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$59,803

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2035.



System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1995. It has a 10-year service life

which expired in 2005.

Recommendation: The system should be replaced.

Deficiency

Location: Add-1995

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$22,466

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.


Recommendation: No action is required.

System: D1010 - Elevators and Lifts

Analysis: The system is missing.

Recommendation: The system should be installed.





Deficiency

Location: Add-1995
Distress: Missing
Category: Compliance

Priority: 5 - Does Not Meet Current Code and/or Guidelines

Notes: There is no elevator in the 2-story school

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$12,360

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D2020 - Domestic Water Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D2030 - Sanitary Waste

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D2090 - Other Plumbing Systems-Nat Gas

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: D3020 - Heat Generating Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D3050 - Terminal & Package Units

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1995. It has a 15-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Add-1995

Distress: Beyond Useful Life Category: Deferred Maintenance Priority: 3 - Necessary- 2-5 Yrs

Correction: Renew System

Qtv: 1-Ea.

Condition Budget: \$99,715

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D4010 - Sprinklers

Analysis: The system is missing.

Recommendation: The system should be installed.









Deficiency

Location: Add-1995 Distress: Missing Category: Compliance

Priority: 5 - Does Not Meet Current Code and/or Guidelines Notes: The school does not have a sprinkler system

Correction: Renew System

Qty: 1-Ea.
Condition Budget: \$18,797

System: <u>D4020 - Standpipes</u>
Analysis: The system is missing.

Recommendation: The system should be installed.

Deficiency

Location: Add-1995 Distress: Missing Category: Compliance

Priority: 5 - Does Not Meet Current Code and/or Guidelines Notes: The school does not have a sprinkler system

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$1,094

System: D4030 - Fire Protection Specialties

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1995. It has a 15-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Add-1995

Distress: Beyond Useful Life
Category: Deferred Maintenance
Priority: 3 - Necessary- 2-5 Yrs
Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$451

<u>System:</u> <u>D5010 - Electrical Service/Distribution</u>

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

System: D5020 - Lighting and Branch Wiring

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D5030 - Communications and Security

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: G2010 - Roadways

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 50-year service life. Based on the

assessment, it is expected to expire in 2045.

Recommendation: No action is required.

System: G2020 - Parking Lots

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

System: G2030 - Pedestrian Paving

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 50-year service life. Based on the

assessment, it is expected to expire in 2045.

Recommendation: No action is required.

System: G2040 - Site Development

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: G2050 - Landscaping

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: G3010 - Water Supply

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 50-year service life. Based on the

assessment, it is expected to expire in 2045.

Recommendation: No action is required.

System: G3020 - Sanitary Sewer

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 50-year service life. Based on the

assessment, it is expected to expire in 2045.

Recommendation: No action is required.

System: G3030 - Storm Sewer

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 50-year service life. Based on the

assessment, it is expected to expire in 2045.

System: G4010 - Electrical Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: G4020 - Site Lighting

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1995. It has a 30-year service life. Based on the assessment, it is expected to expire in 2025.

Appendix 1 - Assessment Criteria

Assessment Criteria

Task No	Task Description	Score	Comments
	Facility Condition	-00010	- Comments
	What is the Building's facility condition based	N/A	
	on its facility condition index?		
	Support Spaces		
	Restrooms (Student)	4	There is an inadequate number of student
	,		restrooms available for the two-story building.
			The building also has four different additions
			which makes access more difficult.
5110.5399 A	Administration	5	The office area is very small.
5110.5402	Counseling	2	·
5110.5405		4	There is no restroom or sink available.
5110.5408	Staff Work Room	2	
5110.5411	Cafeteria	5	The cafeteria is only 1/3 the size of what is required.
5110.5414 F	Food Service and Prep	5	The kitchen area is very small.
	Custodial and Maintenance	5	There are an insufficient number of custodial
			closets in the school.
5111 L	Learning Environment		
5111.5112 L	Learning Style Variety	4	There are no flexible learning spaces available for the building.
5111.5113 I	Interior Environment	4	The interior circulation of the building is a
			challenge. The school consists of four different
			buildings built during four different time periods,
			making it difficult to navigate and supervise.
5111.5114 E	Exterior Environment	4	There are no outdoor learning opportunities
			available for students.
	General Classrooms		
5115.5116 E	Environment	4	Given the age and condition of the general
			classrooms, the rooms are not inviting or
			stimulating. Natural lighting is not available in
			every classroom. Air quality is poor.
5115.5117	Size	5	Classrooms are less than 500 square feet with
			only two exceptions. The classrooms do not meet
			Kentucky size standards.
5115.5118 L		2	
5115.5119	Storage/Fixed Equip	3	Some of the classrooms have adequate storage;
			others do not. The primary classrooms all lack
5400 H	Via de vere ete e		proper storage.
	Kindergarten Environment	Λ	The kindergarten elegeroom deed not provide an
3120.3121	Environment	4	The kindergarten classroom does not provide an inviting and stimulating environment. Air quality is
			poor; the thick glass walls do not permit adequate natural lighting.
5120.5122	Size	2	natural lightning.
5120.5122 C		2	
	Storage/Fixed Equip	3	Storage is limited.
	ECE	J	otorago lo limitoa.
	Environment	4	The size and age of the preschool classroom
			does not create an inviting and stimulating
			environment. Air quality is poor; the overall
			aesthetics are poor.

Took No	Took Description	Cooro	Comments
Task No	Task Description	Score	Comments
5125.5127	Size	5	The room measures 494 square feet and does
		_	not meet Kentucky size standards.
5125.5128		2	
5125.5129	Storage/Fixed Equip	4	The storage in the preschool room is not
			adequate. There is a sink but no bubbler system.
			There is no wet area flooring nor a restroom.
5130	Self-Contained Special Ed		
5130.5131	Environment	N/A	
5130.5132		N/A	
5130.5133		N/A	
5130.5134		N/A	
5135	Instructional Resource Rooms	14,7 (
5135.5136		4	Given the age and condition of the resource
3133.3130		4	
			classrooms, the rooms are not inviting or
5405 5407			stimulating. Air quality is poor.
5135.5137		2	
5135.5138		2	
	Storage/Fixed Equip	3	Storage is limited in the resource rooms.
5140	Science		
5140.5141	Environment	5	There is no dedicated science space for grades 7-
			8 and 5th/6th grade general classrooms do not
			have demo tables with hot/cold water for science
			instruction.
5140.5142	Size	5	There is no dedicated science space for grades 7-
3140.3142	GIZE		8 and 5th/6th grade general classrooms do not
			have demo tables with hot/cold water for science
E4.40 E4.40	Lagation		instruction.
5140.5143	Location	5	There is no dedicated science space for grades 7-
			8 and 5th/6th grade general classrooms do not
			have demo tables with hot/cold water for science
			instruction.
5140.5144	Storage/Fixed Equip	5	There is no dedicated science space for grades 7-
			8 and 5th/6th grade general classrooms do not
			have demo tables with hot/cold water for science
			instruction.
5145	Music		
5145.5146	Environment	5	There is no music room available for the facility.
			Music is taught in the auditorium.
5145.5147	Size	5	There is no music room available for the facility.
0140.0147	0120		Music is taught in the auditorium.
5145.5148	Location	5	There is no music room available for the facility.
3143.3146	Location	5	
54.45.54.40	Otana and /Fire at Farmin	_	Music is taught in the auditorium.
5145.5149	Storage/Fixed Equip	5	There is no music room available for the facility.
	•		Music is taught in the auditorium.
5150	Art		
5150.5151	Environment	4	Given the age and condition of the art classroom,
			it is not inviting or stimulating. Air quality is poor;
			natural lighting is limited, and the overall
			aesthetics are not conducive to the program.
5150.5152	Size	5	The art room measures 571 square feet and does
			not meet Kentucky size standards.
5150.5153	Location	2	
5150.5154		3	Storage is limited.
5155	Career Tech Ed	J	otorago io mintoa.
		NI/A	
5155.5156	Environment	N/A	

Task No	5155.5157 Size N/A 5155.5158 Location N/A 5155.5159 Storage/Fixed Equip N/A 5160 Computer Labs 1560.5161 5160.5161 Environment 2 5160.5162 Size 2 5160.5163 Location 2 5165.5164 Storage/Fixed Equip 2 5165.5165 P.E. 5 5165.5168 Location 2 5165.5169 Storage/Fixed Equip 4 The gymnasium does not meet Kentucky standards. 5165.5169 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. 5170 Performing Arts N/A 5170.5171 Environment N/A 5170.5172 Size N/A 5170.5173 Location N/A 5170.5174 Storage/Fixed Equip N/A 5175 Media Center The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting or stimulating environment for library activities 5175.5177 <	size
S155.5158 Location	5155.5158 Location N/A 5155.5159 Storage/Fixed Equip N/A 5160 Computer Labs 5160.5161 Environment 2 5160.5162 Size 2 5160.5163 Location 2 5160.5164 Storage/Fixed Equip 2 5165.5165 P.E. 5 5165.5167 Size 5 The gymnasium does not meet Kentucky standards. 5165.5168 Location 2 The gymnasium lacks adequate storage. 5165.5169 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. 5170.5171 Environment N/A N/A 5170.5172 Size N/A The facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system. 5170.5173 Location N/A 5175 Media Center A 5175 Media Center 4 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting or stimulating environ	size
StorageFixed Equip N/A	5155.5159 Storage/Fixed Equip N/A 5160 Computer Labs 2 5160.5161 Environment 2 5160.5162 Size 2 5160.5163 Location 2 5165.5164 Storage/Fixed Equip 2 5165.5165 P.E. 5 5165.5167 Size 5 5165.5168 Location 2 5165.5169 Storage/Fixed Equip 4 5170 Performing Arts 9 5170.5171 Environment N/A 5170.5172 Size N/A 5170.5173 Location N/A 5170.5174 Storage/Fixed Equip N/A 5175.5175 Media Center N/A 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting on stimulating environment for library activities 5175.5177 Size 5 The media center measures 834 squared does not meet Kentucky size standards. 5175.5178 Location	size
Section Sect	5160 Computer Labs 5160.5161 Environment 2 5160.5162 Size 2 5160.5163 Location 2 5160.5164 Storage/Fixed Equip 2 5165 P.E. 2 5165.5166 Environment 2 5165.5167 Size 5 The gymnasium does not meet Kentucky standards. 5165.5168 Location 2 5165.5169 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. 5170.5171 Environment N/A 5170.5172 Size N/A The facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system. 5170.5173 Location N/A 5175 Media Center ADA access. There is no sound system. 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting of stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards.	size
Secondary Seco	5160.5161 Environment 2 5160.5162 Size 2 5160.5163 Location 2 5160.5164 Storage/Fixed Equip 2 5165.5165 P.E. 5 5165.5166 Environment 2 5165.5167 Size 5 The gymnasium does not meet Kentucky standards. 5165.5168 Location 2 The gymnasium lacks adequate storage. 5170 Performing Arts N/A The facility has an auditorium. There is no stadium seating. There is a stage area weare weare. 5170.5171 Environment N/A N/A 5170.5173 Location N/A 5170.5174 Storage/Fixed Equip N/A 5175.5176 Media Center 4 5175.5176 Environment 4 The media space is small and is located to the computer lab with no wall separating programs The space is not an inviting on stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 squared does not meet Kentucky size standards. 5175.5178 Location 2	size
S160.5162 Size 2 S160.5163 Location 2 S160.5164 Storage/Fixed Equip 2 S165.5166 Environment 2 Storage/Fixed Equip 2 S165.5167 Size 5 The gymnasium does not meet Kentucky size standards. Storage/Fixed Equip 4 The gymnasium does not meet Kentucky size standards. Storage/Fixed Equip 4 The gymnasium lacks adequate storage. S170.5171 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. S170.5171 Environment NI/A S170.5171 Size NI/A The facility has an auditorium. There is no standium seating. There is a stage area with no ADA access. There is no sound system. S170.5173 Storage/Fixed Equip NI/A S175.5176 Media Center NI/A S175.5176 Size Storage/Fixed Equip S175.5176 Size Storage/Fixed Equip S175.5177 Size Storage/Fixed Equip S175.5178 Storage/Fixed Equip S175.5178 Storage/Fixed Equip S175.5178 Storage/Fixed Equip S175.5178 Storage/Fixed Equip S188.5189 Vehicular Traffic Storage/Fixed Equip S188.5189 Storage/Fixed Equip S188.5189 Pedestrian Traffic S188.5190 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. S188.5191 Parking S188.5192 Athletic Courts and Fields S188.5192 Athletic Courts and Fields S188.5194 Athletic Courts and Fields S189.5194 The reare no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. S189.5194 Safety and Security S189.5194 The reare no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. S189.5194 Safety and Security S189.5194 Safety	5160.5162 Size 2 5160.5163 Location 2 5165 P.E. 2 5165.5166 Environment 2 5165.5167 Size 5 5165.5168 Location 2 5165.5169 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. 5170 Performing Arts 2 5170.5171 Environment N/A 5170.5172 Size N/A The facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system. 5170.5173 Location N/A 5170.5174 Storage/Fixed Equip N/A 5175 Media Center N/A 5175 Media Center 4 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting of stimulating environment for library activitis. 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards. 5175.5178 Location 2	size
Section 2 5160-5163 Location 2 5160-5164 Storage/Fixed Equip 2 5165-5165 F.E. 5 5165-5165 Size 5 5 5 5 5 5 5 5 5	5160.5163 Location 5160.5164 Storage/Fixed Equip 5165 P.E. 5165.5166 Environment 5165.5167 Size 5165.5168 Location 5165.5169 Storage/Fixed Equip 5170 Performing Arts 5170.5171 Environment 5170.5172 Size N/A The facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system. 5170.5173 Location 5170.5174 Storage/Fixed Equip 5175 Media Center 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting of stimulating environment for library activities does not meet Kentucky size standards. 5175.5178 Location	size
Storage/Fixed Equip 2 5165.5166 Environment 2 5165.5166 Environment 2 5165.5167 Size 5 The gymnasium does not meet Kentucky size standards. 5165.5168 Location 2 5165.5168 Location 2 5165.5168 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. 5170.5171 Environment N/A 5170.5172 Size N/A The facility has an auditorium. There is no stadium seating. There is a stage area with no ADA access. There is no sound system. S170.5173 Location N/A S170.5174 Storage/Fixed Equip N/A The media space is small and is located next to the computer lab with no wall separating the two programs. The space is not an inviting or stimulating environment for library activities. 5175.5176 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 2 Media center storage is inadequate. 5188.5189 Vehicular Traffic 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.5191 Parking 5 There are no palyground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. There is no fencing anywhere on the property. The property is located on a city block downtown.	5160.5164Storage/Fixed Equip25165P.E.5165.5166Environment25165.5167Size5The gymnasium does not meet Kentucky standards.5165.5168Location25165.5169Storage/Fixed Equip4The gymnasium lacks adequate storage.5170Performing ArtsN/A5170.5171EnvironmentN/A5170.5172SizeN/AThe facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system.5170.5173LocationN/A5175.5174Storage/Fixed EquipN/A5175.5175Media Center4The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting on stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	size
S165 P.E.	5165P.E.5165.5166Environment25165.5167Size5The gymnasium does not meet Kentucky standards.5165.5168Location25165.5169Storage/Fixed Equip4The gymnasium lacks adequate storage.5170Performing ArtsN/A5170.5171EnvironmentN/A5170.5172SizeN/AThe facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system.5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media CenterADA access. There is no sound system.5175.5176Environment4The media space is small and is located in the computer lab with no wall separating or programs The space is not an inviting on stimulating environment for library activitic functions.5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	size
S165.5166 Environment 2 5 The gymnasium does not meet Kentucky size standards. 5 The gymnasium does not meet Kentucky size standards. 5 S165.5168 Storage/Fixed Equip 4 The gymnasium lacks adequate storage. 5 S170.5171 Performing Arts N/A S170.5172 Size N/A The facility has an auditorium. There is no stadium seating. There is a stage area with no ADA access. There is no sound system. S170.5173 Location N/A S170.5174 Storage/Fixed Equip N/A S170.5176 Environment 4 The media space is small and is located next to the computer lab with no wall separating the two programs. The space is not an inviting or stimulating environment for library activities. 5 The media center means easily again for the computer lab with no wall separating the two programs. The space is not an inviting or stimulating environment for library activities. 5 The media center media center means easily againer feet and does not meet Kentucky size standards. 5 The media center media center means easily againer feet and does not meet Kentucky size standards. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is not an inviting or stimulating environment for library activities. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate. 5 Storage/Fixed Equip 5 Media center storage is inadequate	5165.5166Environment25165.5167Size5The gymnasium does not meet Kentucky standards.5165.5168Location25165.5169Storage/Fixed Equip4The gymnasium lacks adequate storage.5170Performing ArtsN/A5170.5171EnvironmentN/A5170.5172SizeN/AThe facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system.5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media Center4The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting on stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	size
Size	5165.5167 Size 5 The gymnasium does not meet Kentucky standards.	size
Standards Stan	standards. 5165.5168 Location 5165.5169 Storage/Fixed Equip 5170 Performing Arts 5170.5171 Environment 5170.5172 Size N/A The facility has an auditorium. There is n stadium seating. There is a stage area w ADA access. There is no sound system. 5170.5173 Location 5170.5174 Storage/Fixed Equip 5175.5176 Environment A The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting of stimulating environment for library activities 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards.	SIZE
S165.5169 Storage/Fixed Equip 4 The gymnasium lacks adequate storage.	5165.5169Storage/Fixed Equip4The gymnasium lacks adequate storage.5170Performing ArtsN/A5170.5171EnvironmentN/A5170.5172SizeN/AThe facility has an auditorium. There is no stadium seating. There is a stage area wearea wearea wearea.5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media CenterN/A5175.5176Environment4The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting on stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	
S170 Performing Arts S170.5171 Environment S170.5172 Size N/A	5170Performing Arts5170.5171EnvironmentN/A5170.5172SizeN/AThe facility has an auditorium. There is no stadium seating. There is a stage area wearea wearea wearea. There is no sound system.5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media CenterMedia Center5175.5176Environment4The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting of stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	
Si70.5171 Environment Size N/A The facility has an auditorium. There is no stadium seating. There is a stage area with no ADA access. There is no sound system.	5170.5171EnvironmentN/A5170.5172SizeN/AThe facility has an auditorium. There is no stadium seating. There is a stage area wearea weareasted. There is no sound system.5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media CenterMedia Center5175.5176Environment4The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting of stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	
Size	5170.5172SizeN/AThe facility has an auditorium. There is no stadium seating. There is a stage area we ADA access. There is no sound system.5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media CenterMedia Center5175.5176Environment4The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting on stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	
stadium seating. There is a stage area with no ADA access. There is no sound system. 5170.5173 Location N/A 5170.5174 Storage/Fixed Equip N/A 5175 Media Center 5175.5176 Environment 4 The media space is small and is located next to the computer lab with no wall separating the two programs. The space is not an inviting or stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 2 5175.5179 Storage/Fixed Equip 5 Media center storage is inadequate. 5188.5189 Vehicular Traffic 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground spaces available. The school uses a playground spaces available. The school uses a playground because of its condition, it is not used by the school. 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	stadium seating. There is a stage area w ADA access. There is no sound system. 5170.5173 Location 5170.5174 Storage/Fixed Equip 5175 Media Center 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting or stimulating environment for library activities 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards. 5175.5178 Location 2	
ADA access. There is no sound system. 5170.5173 Location 5170.5174 Storage/Fixed Equip 5175.5176 Media Center 5175.5176 Environment 4 The media space is small and is located next to the computer lab with no wall separating the two programs The space is not an inviting or stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 2 Storage/Fixed Equip 5 Media center storage is inadequate. 5188.5189 Vehicular Traffic 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	ADA access. There is no sound system. 5170.5173 Location 5170.5174 Storage/Fixed Equip 5175 Media Center 5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting on stimulating environment for library activitien to stimulating environment for library	
S170.5173 Location N/A	5170.5173LocationN/A5170.5174Storage/Fixed EquipN/A5175Media Center5175.5176Environment4The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting or stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	ith no
Storage/Fixed Equip Storage/Fixed Equip Storage/Fixed Equip Environment 4 The media space is small and is located next to the computer lab with no wall separating the two programs The space is not an inviting or stimulating environment for library activities.	5170.5174Storage/Fixed EquipN/A5175Media Center5175.5176Environment4The media space is small and is located in the computer lab with no wall separating in programs. The space is not an inviting or stimulating environment for library activities5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	
S175 Media Center S175.5176 Environment S175.5176 Environment S175.5176 Environment S175.5177 Size State S175.5177 Size S175.5177 Size S175.5178 Storage/Fixed Equip S188.5189 S188.5189 S188.5199 S188.5191 Parking S188.5191 Parking S188.5192 Athletic Courts and Fields S188.5192 S188.5192 S188.5192 Safety and Security S188.5194 Safety and Security S188.5194 Safety and Security S188.5194 Safety and Security S188.5195 S188.5192 S188.5192 S188.5192 S188.5192 Safety and Security Safety and Security S188.5192 Safety and Security S188.5194 Safety and Security S188.5195 S188.5195 S188.5195 S188.5196 Safety and Security S198.5196 S198.5	5175Media Center5175.5176Environment4The media space is small and is located in the computer lab with no wall separating programs The space is not an inviting on stimulating environment for library activitien.5175.5177Size5The media center measures 834 square for does not meet Kentucky size standards.5175.5178Location2	
The media space is small and is located next to the computer lab with no wall separating the two programs. The space is not an inviting or stimulating environment for library activities.	5175.5176 Environment 4 The media space is small and is located in the computer lab with no wall separating programs. The space is not an inviting or stimulating environment for library activitien. 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards. 5175.5178 Location 2	
the computer lab with no wall separating the two programs. The space is not an inviting or stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 5 Media center storage is inadequate. 5188.5199 Vehicular Traffic 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	the computer lab with no wall separating programs The space is not an inviting or stimulating environment for library activitien 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards. 5175.5178 Location 2	
programs The space is not an inviting or stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 2 2	programs The space is not an inviting of stimulating environment for library activitien 5175.5177 Size 5 The media center measures 834 square for does not meet Kentucky size standards. 5175.5178 Location 2	next to
stimulating environment for library activities. 5175.5177 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 5175.5179 Storage/Fixed Equip 5 Media center storage is inadequate. 5188.5189 Vehicular Traffic 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	5175.5177Size5The media center measures 834 square f does not meet Kentucky size standards.5175.5178Location2	
5175.5177 Size 5 The media center measures 834 square feet and does not meet Kentucky size standards. 5175.5178 Location 5175.5179 Storage/Fixed Equip 5 Media center storage is inadequate. 5188.5189 Vehicular Traffic 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	5175.5177 Size 5 The media center measures 834 square f does not meet Kentucky size standards. 5175.5178 Location 2	,
does not meet Kentucky size standards.	does not meet Kentucky size standards. 5175.5178 Location 2) S.
5175.5178 Location 2 5175.5179 Storage/Fixed Equip 5 Media center storage is inadequate. 5188 Outside 5 All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school 5193 Safety and Security 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	5175.5178 Location 2	eet and
5175.5179Storage/Fixed Equip5Media center storage is inadequate.5188Outside35188.5189Vehicular Traffic5All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns.5188.519Pedestrian Traffic4Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration.5188.5191Parking5There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners.5188.5192Athletic Courts and Fields5There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school.5193Safety and Security5There is no fencing anywhere on the property. The property is located on a city block downtown.		
5188Outside5188.5189Vehicular Traffic5All vehicular traffic must drop off students on Blatt street. There is no area that allows for parents to park. The drop-off zone creates safety concerns.5188.519Pedestrian Traffic4Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration.5188.5191Parking5There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners.5188.5192Athletic Courts and Fields5There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school.5193Safety and Security5193.5194Fencing5There is no fencing anywhere on the property. The property is located on a city block downtown.		
Safety and Security Safety and service in the property. The property is located on a city block downtown.	5175.5179 Storage/Fixed Equip 5 Media center storage is inadequate.	
street. There is no area that allows for parents to park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	5188 Outside	
park. The drop-off zone creates safety concerns. 5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	5188.5189 Vehicular Traffic 5 All vehicular traffic must drop off students	on Blatt
5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from Blatt street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	street. There is no area that allows for pa	rents to
street, the same area for the parent drop-off zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	park. The drop-off zone creates safety co	ncerns.
zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	5188.519 Pedestrian Traffic 4 Bikers and walkers enter the building from	n Blatt
zone. There are safety concerns because of this configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	street, the same area for the parent drop-	off
configuration. 5188.5191 Parking 5 There are no parking lots available for faculty, staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.		
staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	configuration.	
staff, and parents. Parking is all on-street and is shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.		ulty,
shared with homeowners. 5188.5192 Athletic Courts and Fields 5 There are no playground spaces available. The school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. 5193 Safety and Security 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.		
school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. Safety and Security There is no fencing anywhere on the property. The property is located on a city block downtown.		
school uses a playground that is owned by the Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. Safety and Security There is no fencing anywhere on the property. The property is located on a city block downtown.	5188.5192 Athletic Courts and Fields 5 There are no playground spaces available	e. The
Optimist Club. There is a small grassy area that used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. Safety and Security There is no fencing anywhere on the property. The property is located on a city block downtown.		
used to be a softball field but the area is difficult to access, small, and because of its condition, it is not used by the school. Safety and Security 5 There is no fencing anywhere on the property. The property is located on a city block downtown.		
is not used by the school 5193 Safety and Security 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.		
is not used by the school 5193 Safety and Security 5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.	to access, small, and because of its cond	:4:00 :4
5193Safety and Security5193.5194Fencing5There is no fencing anywhere on the property. The property is located on a city block downtown.		iuon, It 🗀
5193.5194 Fencing 5 There is no fencing anywhere on the property. The property is located on a city block downtown.		iuon, it
The property is located on a city block downtown.		iuon, it
	5193.5195 Signage & Way Finding 3 Signage both inside and outside the build	erty.
very limited.		perty.

		_	-
Task No	Task Description	Score	Comments
5193.5196	Ease of Supervision	4	Supervision is not enhanced through proper
			sightlines. The two-story building, the four
			different additions to the school, and the location
			of the school site make supervision difficult.
5193.5197	Controlled Entrances	2	The building has a controlled entrance into the
			main office area. There is a buzzer system
			available. Other doors have a keyless entry card.
5514	Technology Readiness ES		
5514.5515	Comm\IT Equipment Environment	3	The hub is located in the clinic. The space is not
			properly climate controlled nor easily accessible.
5514.5516	Electrical Power	3	There are insufficient electrical outlets in all the
			classrooms, typically one outlet per room. Power
			cords are used extensively. The mobile unit and
			the computer lab cannot be used at the same
			time due to electrical capacity limitations.
5514.5517	Cooling	1	The computer lab has an individual wall unit that
			keeps the room adequately cooled.
5514.5518	_ ' '	1	
5514.5519	LAN Connectivity	1	
5514.552	WAN Backbone	1	
5514.5521	LAN-WAN Performance	4	The connectivity for the network is usually slow.
5514.5522	Video Distribution	1	
5514.5523		1	
5514.5524	Intelligent Classroom-21st Century Learning	1	
	Tools		

Glossary

Abandoned A facility owned by a district that is not occupied and not maintained. See Vacant.

Building A fully enclosed and roofed structure that can be traversed internally without exiting to the

exterior.

Building addition An area, space or component of a building added to a building after the original building's

year built date. NOTE: As a convention in KFICS, "Main" was used to designate the original building. Additions built prior to 1980 were included in the Main building area calculations to reflect their predicted system depreciation characteristics and remaining

useful life.

Calculated Next Renewal Calculated Next Renewal refers to the year a system or building element completes its

useful life based on its installed date and its expected useful or design life.

Capacity refers to the number of students the facility can accommodate. The capacity is

calculated using the Kentucky Department of Education's (KDE) capacity model which totals the number of general classrooms contained in the school, and then multiplies this total by the number of students in each classroom to arrive at a net capacity. The number of students per classroom is set at 25 for all grade levels. The net capacity is then divided by a scheduling factor to arrive at the functional capacity. The scheduling factors are 100%

for elementary schools, and 75% for middle and high schools.

Capital Renewal Capital Renewal refers to physical facility condition work (excluding suitability and

technology work) that includes the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life that is not normally included in an annual

operating maintenance budget.

Category Category refers to the type or class of a user defined deficiency grouping with shared or

similar characteristics. Category descriptions are:

ADA / Accessibility Capital Renewal Compliance Critical Repair

Deferred Maintenance

Environmental Functional Adequacy

Condition Condition refers to the state of physical fitness or readiness of a facility system or system

element for its intended use.

Condition Budget The Condition Budget, also known as Condition Needs, represents the budgeted

contractor installed costs plus owner's soft costs for the repair, replacement or renewal for

a component or system level deficiency. It excludes contributing costs for other

components or systems that might also be associated with the cortrective actions due to

polloging the work

packaging the work.

Condition Score Condition Score is a factor used in the calculation of School Score expressed as

Condition Score = (1- FCI) where FCI represents the Facility Condition Index.

See School Score.

Correction Correction refers to an assessor's recommended deficiency repair or replacement action.

For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a material defined in a Uniformat II element, or system it is intended to address. It excludes other peripheral costs

that may also be included in the pacakaging of repair, replacement or renewal

improvements that may also be triggered by the deficiency correction.

Criteria Criteria refers to the set of requirements, guidelines or standards that are assessed and

rated to develop a score. KFICS Criteria includes Condition, Educational Suitability

(Suitability) and Technology Readiness (Technology).

Current Period The Current Period is the curent year plus a user defined number of forward years.

Current Replacement Value

(CRV)

Current Replacement Value (CRV), also known as Replacement Value represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to an optimal state-of-the-art condition under current codes and construction standards and

techniques.

Deferred maintenance

Deferred maintenance is condition work (excluding suitability and technology readiness needs) deferred on a planned or unplanned basis to a future budget cycle or postponed

until funds are available.

Deficiency

A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an

intended purpose.

Distress

Distress refers to a user defined root cause of a deficiency. Distress descriptions are:

Abandoned Beyond Useful Life

Damaged Failing Inadequate Missing

Element

Elements are the major components that comprise building systems as defined by

Uniformat.

Energy Audit Budget

Energy Audit Budget, also known as Energy Needs, represents the need for a detailed energy audit for those schools that used more than the average Energy Utilization Index (EUI) as reported by the Department of Energy for US primary and secondary schools.

Energy Utilization Index

(EUI)

EUI is the measure of total energy consumed in the cooling or heating of a building in an annual period expressed as British thermal unit (BTU) per (cooled or heated) gross square

foot.

Enrollment Projection

Enrollment Projection refers to an estimate of a future student population based on historical data and enrollment information provided. Two methods are used and averaged within KFICS to calculate projected enrollment: Annual % Change and Linear Regression.

Extended Facility Condition

Index (EFCI)

Extended Facility Condition Index (EFCI) is calculated as the condition needs for the current year plus facility system renewal for user defined forward years (the Current Period) divided by Current Replacement Value.

Facility

A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose.

Facility Condition Index (FCI)

FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100%(very poor).

Forecast Period

The Forecast Period refers to a user defined number of years after the Current Period. The area of the enclosed floor space of a building or building addition in square feet

Gross square feet (GSF)

measured to the outside face of the enclosing wall.

Install year

The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.

Kentucky Facility Index (KFI)

Kentucky Facility Index (KFI) is the ratio of the sum of a facility's Condition Budget plus Suitability Budget plus Technology Readiness Budget to the facility's Current Replacement Value (CRV) ranging from 0% (new) to 100% (very poor).

Kentucky School Score

The Kentucky School Score is a calculated value derived by the following formula: School Score = (Condition Score * weighting factor) + (Suitability Score * weighting factor)

+ (Technology Score * weighting factor)

Kentucky Suitability Index

(KSI)

KentuckyTechnology Index

(KTI) Life cycle Kentucky Suitability Index (KSI) is a ratio of the sum of Suitability deficiency costs to the facility's Current Replacement Value (CRV) ranging from 0% (new) to 100% (very poor).

Kentucky Technology Index (KTI) is the ratio of the sum of technology deficiency costs to the facility Current Replacement Value ranging from 0% (new) to 100% (very poor).

Life cycle refers to the period of time that a building or or element exists and can serve its intended function. The cycle includes warranty period, intrinsic period, and run to failure

period. (See Useful Life)

Next Renewal

Next Renewal refers to a manually adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately current conditions.

No Educational Program

(NEP)

No Educational Program (NEP) refers to a Tier 1 facility that does not have a current educational program (elementary, middle or high school program) usually due to the facility being vacant, abandoned or used for other temporary function.

Order of Magnitude

Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.

Priority

Priority refers to a deficiency's urgency for repair as determined by the assessment team and does not reflect the priority assigned to proposed project repairs as determined by KDE or by Districts in their funding requests or facility planning.

Five typical industry priority settings were used for the assessment:

Priority Description

Critical / Immediate Need
 Potentially Critical-12 months

Necessary- 2-5 YrsRecommended-3-10 Yrs

5 Does Not Meet Current Code and/or Guidelines

Remaining Service Life %

Remaining Service Life % is a calculated value such that RSL% = RSL divided by its system Design Life (not displayed).

Remaining Service Life (RSL)

Remaining service life is a measure of a system's or element's predicted remaining useful life calculated as RSL = Next Renewal or Calculated Next Renewal Year minus the Current Year.

Remaining Service Life Index (RSLI)

The Remaining Service Life Index (RSLI) also known as the Condition Index (CI) is calculated as the sum of a renewable systems Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude softcost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).

Remaining Service Life Value

Remaining Service Life Value also known as the RSL Weight is a calculated value used to determine the RSLI that is equal to the system Value (Unit Cost * Qty) * RSL (not displayed).

Repair Evaluation (REMR)

Repair Evaluation Maintenance and Rehabilitation (REMR) is a scale used by federal users to objectively rank systems based on its condition:

Minor / Excellent: No noticeable defects. Some aging or wear may be visible.

Minor / Good: Only minor deterioration or defects are evident.

Moderate / Fair: Some deterioration or defects are evident but function is not significantly affected.

Moderate / Marginal: Moderate deterioration. Function is still adequate.

Major / Poor: Serious deterioration in at least some portions of the structure. Functions is inadequate.

Major / Very Poor: Serious deterioration in at least some portions of the structure. Function is inadequate.

Major / Failed: No longer functions. General failure or complete failure of a major structural component.

(Source: ERDC/CERL TR-REMR-OM-26)

Replacement Value

See Current Replacement Value.

Site

A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.

Soft Costs

Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user defined and include architectural, engineering, management, testing, and mitagation fees, and other owner pre- and post-construction expenses.

Suitability

Suitability refers to the measure of how well a facility supports the educational program(s) that it houses based on criteria derived from state laws, guidelines and national educational best practices.

Generated: 11/20/2011 7:58:27 PM FOR OFFICIAL USE ONLY Final 44

Suitability Budget The Suitability Budget, also known as Suitability Needs, represents the budgeted

contractor's installed cost plus soft costs for the corrections required to bring a program's educational suitability item or characteristic into compliance with standards, guidelines or

best practices.

Suitability Score is a calculated value expressed as

Suitability Score = (Sum of scoring for Suitability Criteria issues) * weighted value. See

School Score.

Sustainment Restoration and Modernization (S/RM)

S/RM is currently not used in KFICS. Sustainment Restoration and Modernization (S/RM) refers to the Department of Defense program to keep the Department's inventory of facilities in good working order (i.e. day to day maintenance requirements). In addition it provides resources to restore facilities whose age is excessive or have been damaged by fire accident or natural disasters and alternations of facilities to implement new or higher

standards to accommodate new functions or mission.

System System refers to building and related site work elements as described by ASTM Uniformat

II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.

System Condition Index

(SCI)

Tier 2

System Condition Index (SCI) is the ratio of a system's current condition deficiency costs to its replacement value - also known as "percent used" ranging from 0 percent to 100 percent or greater due to the addition of the system's renewal premium the additional costs to prepare for the system renewal such as demolition costs.

Technology Budget The Technology Budget, also known as Technology Readiness Needs, represents the

budgeted contractor's installed cost plus owner's soft costs for the corrections required to bring a program's technology readiness item or characteristic into compliance with

standards guidelines or best practices.

Technology Score Technology Score, also known as Technology Readiness Score, is calculated as follows:

(Sum of scoring for technology readiness criteria issues) * weighted value.

See School Score.

Tier 1 A Tier 1 facility generally has a teaching-learning purpose and may include the following

Facilities: Sites

Educational buildings

Classrooms

Libraries and media centers Cafeterias and kitchens

Auditoriums gymnasiums and multipurpose rooms Vocational Agricultural buildings and greenhouses

New school facilities built within the past 12 months not in current KDE inventory records

A Tier 2 building is an ancillary building that typically is not occupied or does not have a

teaching-learning purpose or is a temporary structure, including the following Facilities:

Sites

Storage buildings

Temporary modular structures

Other modulars

Teacherages / residences

Storage sheds

Sports bleachers concession stands press boxes

Abandoned buildings
Buildings under construction

Tier 3 A Tier 3 building is an ancillary building that is occupied but typically does not have a

teaching-learning purpose, and includes the following Facilities:

Administration buildings Maintenance buildings Transportation facilities Uniformat, also known as Uniformat II, a publication of the Construction Specification

Institute (CSI), is ASTM Uniformat II Classification for Building Elements (E1557-97). UniFormat is a method of arranging construction information based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or

assemblies.

Useful Life Useful Life refers to the intrinsic period of time a system or element is expected to perform

as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in KFICS are derived from the Building Owners and Managers (BOMA) organization's guidelines,

RSMeans cost data, and from user defined historical experience.

Utilization Utilization, also known as School Utilization, refers to ratio of students to the school's

capacity calculated by dividing the number enrolled at the school by its Program Capacity.

Vacant Vacant refers to a facility that is not occupied but is a maintained facility by a district. See

Abandoned.

Weight (Weighting Factor) Weight, also known as Weighting Factor, is a user defined factor used to apply more or

less emphasis to system or element attributes such as deficiency category, deficiency priority or functional adequacy standard. For example, \$100 of a Priority 1 issue by default has the same cost value (1x) as \$100 of a Priority 5 item. Using weighting factors, the user can establish a priority factor so that for ranking or sorting purposes the facility (District, School, Building, Room, etc.) with a greater weighting (say 2x) thereby elevating it in rank

order over the facility with Priority 1.

Year built The year that a building or addition was originally built based on its date of substantial

completion or occupancy.