## **NELSON COUNTY EARLY LEARNING CENTER PHASE 2** CHANGE ORDER REQUEST

NO.	DESCRIPTION	ADD		DEDUCT	т	OTAL C/O	STATUS	C/O NUMBER	Approval Date
	Credit to remove 5/8" plywood and sleepers over the shingle								
1	roof area and Add to install new wood blocking to the vented nail base	\$ 4,096.53	\$	(8,240.00)	\$	(4,143.47)	ACCEPTED	1&2	8/16/2016
		φ +,000.00	Ψ	(0,2+0.00)	Ψ	(4,140.47)	AGGELITED	102	0/10/2010
	  Hardie plank custom color - 2 Options per Proposal Reques	1 - \$39,213.00							
2	#1	2 - \$45,351.00					DECLINED	DECLINED	N/A
	Relocate power and data for new window Proposal Request								
3	#3	\$ 630.00					RE-ADDRESS		
4	Remove existing gutters, extend the T.P.O. single ply roofing membrane up to the existing metal roof panels.	\$ 4,995.00			\$	4,995.00	ACCEPTED	6	2/22/2017
-		φ +,000.00			Ψ	4,000.00	ACCENTED	0	2/22/2011
_		• • • • • • •			•				
5	Proposal Request #2 Casework changes- Three Option	\$ 345.75			\$	345.75	ACCEPTED	4	1/17/2017
6	New telephone conduit at parking lo	\$ 5,811.74			\$	5,811.74	ACCEPTED	5	1/17/2017
<u> </u>		φ 0,011.71			Ψ	0,011.71	NOOLI TED	Ŭ	
	Install new 3" x 4" downspout from existing downspout out to								
7	corner of the building per Proposal Request #	\$ 1,066.34			\$	1,066.34	ACCEPTED	3	1/17/2017
					Ŧ	.,		-	
8	Credit for removal of VCT per ASI 3	•	M8	&J + CDI		<mark>888.26</mark>	ACCEPTED	<mark>8,9</mark>	
•		\$2,208.75 M&J \$3,038,00 CDI			<b>m</b>				
9	RFP 8 - Demo existing floor tile, install new VCT and bas	\$3,038.00 CDI	1		<mark>\$</mark>	<mark>5,246.75</mark>	ACCEPTED	<mark>8,9</mark>	
		\$581.00 Dixon Electri	ic						
		\$932.00 M&J							
<mark>10</mark>	Work in 3 mechanical closets	\$1,619.00 Landmark S	Sprin	kler		\$3,132.00		7	

Because of discontinuation of VCT colors, the scope of VCT work had to be modified to arrive at patterns that made use of colors available.

In addition to above, removal of existing VCT to reveal slab movement, repair and preparation of slab, and installation of new tile. Replace VCT in one classroom. Building inspector reviewed mechanical closets and was not satisfied with sprinkler conditions. Sprinklers were modified and ceilings added to address inspector's concerns.