

FIELD OBSERVATION REPORT

2018-09 (Scott HS)

■ то:	1055	on County Board of Education Eaton Drive /right, KY 41017	■ DATE:	2018.09.18
ATTENTION	l: Mr. F	Rob Haney		
FROM:	Mark	Perry	PROJECT:	Kenton County School District
	mper	ry@pca-arch.com		Scott High School – Phase IV
	1881	Dixie Highway, Suite 130		
	Fort '	Wright, KY 41011		
	V: 85	59.431.8612 • F: 859.431.8611		
COPIES TO	: Mr. D	David Lloyd, Mr. Danny Mann,	PROJECT NO.	2016-124
	Ms. (Carrie Hooten		
■ WE TRANSMIT THE ATTACHED ITEMS VIA: EMAIL				
PURPOSE		For your use	DISPOSITION [☐ No exceptions noted
		As requested		Exceptions noted,
		For review and comment		Revise as indicated.
		For information		REJECTED:
	\boxtimes	For record		REVISE AND RESUBMIT
		For approval		
COPIES [DATE	DESCRIPTION		PAGES
1	2018-09	Field Observation Report		6

Division 03: Concrete

03.01: 2018.09.11 – Shade structure footings in the courtyard were complete.

03.02: 2018.09.11 – Formwork for the exterior stair retaining walls was being installed. Reinforcing and form installation was approximately 40% complete.

03.06: 2018.09.17 - Formwork had been partly stripped at exterior stair retaining walls.

Division 04: Masonry

04.01: 2018.09.11 - The mason was actively working on the south wall of the monumental stair at the lower level. Walls at the lower level ramp outside the band room were complete.

04.02: 2018.09.17 – The south wall of the monumental stair was complete up to the 2nd floor line.

04.03: 2018.09.17 - Exterior brick was delivered. Some was staged inside the building near the access to the courtyard. The balance of the material was along Lonneman Drive.

04.04: 2018.09.17 – The mason was actively working on the south wall of the south corridor and the east wall of the east corridor at the upper level.

Division 05: Metals

05.01: 2018.09.17 – Tube steel for operable partitions had been installed at the bottom of the existing joists for most upper level locations.

Division 07: Thermal and Moisture Protection

07.01: 2018.09.11 – Spray-applied insulation was actively being installed at the upper level. Lower level installation appeared to be complete.

07.02: 2018.09.11 - The roofer was actively working in the box gutter at the sloped roof.

If enclosures are not as noted, please notify PCA ARCHITECTURE immediately. Scott HS FieldRpt-201809



07.03: 2018.09.17 - Intumescent coating had been applied to spray-applied insulation.

Division 20-28: MEP

20-28.01: 2018.09.11 – Heat pump units were staged in the multi-purpose room for distribution to and installation in the various mechanical rooms.

Division 32: Exterior Improvements

32.01: 2018.09.17 – Stained concrete sample panels were on-site for consideration.

CONSTRUCTION PHOTOS



2018.09.11 - Shade canopy footings.



2018.09.11 – Spray insulation at multi-purpose room.



2018.09.11 - Masonry at multi-purpose room.



2018.09.11 - Staged heat pumps.





2018.09.11 - South wall of monumental stair.



2018.09.11 - Ramp outside band room.



2018.09.11 - Forms at exterior steps.



2018.09.11 - Forms at exterior steps.



2018.09.17 - Delivered brick.



2018.09.17 - Stamped concrete samples.





2018.09.17 - Brick staged for courtyard installation.



2018.09.17 - South wall of monumental stair.



2018.09.17 - South wall of monumental stair.



2018.09.17 – Intumescent coating on spray insulation.



2018.09.17 - Carreer Center entrance.



2018.09.17 - Carreer Center.





2018.09.17 - Brick mock-up panel.



2018.09.17 – South corridor at upper level.




2018.09.17 – North corridor at upper level.



2018.09.17 - Bus duct repair.




2018.09.17 - Bus duct repair.



2018.09.17 - Housekeeping pad at upper level.






2018.09.17 - Heat pumps staged at upper level.



2018.09.17 - East corridor at upper level.



2018.09.17 – South corridor at upper level.



2018.09.17 – Operable partition support framing.

- ☐ Please acknowledge receipt of transmitted items.

END