



REPAIR SEAM IN SADDLE BEHIND  
PARAPET (4 LOCATIONS TOTAL)



DAMAGED BASE FLASHING ALONG  
NORTHEAST PARAPET (SEE AERIAL MAP)



SEAL/CAULK GUTTER HEAD AT BRICK  
COLUMN TERMINATION



DAMAGED BASE FLASHING ALONG  
NORTHEAST PARAPET

REPLACE SMALL SADDLE AT  
SOUTHEAST AND SOUTHWEST  
CORNERS OF AUDITORIUM



SEAL COUNTER FLASHING AND  
MASONRY JOINTS AS NEEDED IN  
AREAS OF CURRENT LEAKS.



CORNER SADDLE

SADDLE BEHIND PARAPET



SMALL SADDLE LOCATION AT  
CORNER AND PARAPET.



SMALL SADDLE AT SOUTHEAST  
CORNER OF AUDITORIUM



SPLIT SEAM AT SADDLE BEHIND  
PARAPET.



REPLACE STRIPPING PLIES AT  
GUTTER EDGE ALONG NORTHWEST  
SIDE OF ROOF (SEE AERIAL PHOTO)



REPLACE SEALANT AT STONE  
COPING / BRICK COLUMN  
INTERSECTION ON AUDITORIUM



INSTALL SEALANT AT EXISTING  
VOIDS NEAR CURRENT LEAK AREAS