



REPAIR SEAM IN SADDLE AS
PREVENTATIVE
MAINTENANCE (3EA.)

REPLACE STRIPPING
PLIES AT GUTTER
EDGE

CURRENT LEAK
REPAIR SEAM IN
SADDLE

REPLACE BASE
FLASHING

REPLACE SMALL
METAL SADDLES
AT CORNERS

MISCELLANEOUS
CAULKING AT COUNTER
FLASHING AND GUTTER
HEAD

Southgate Independent
School District

1

2

3

Google

Google Camera : 258 m 39°04'22"N 84°28'26"W 212 m 100%

4:11 PM
1/16/2019