



FLOYD COUNTY BOARD OF EDUCATION  
Anna Whitaker Shepherd, Superintendent  
442 KY RT 550  
Eastern, KY 41622  
Telephone (606) 886-2354 Fax (606) 886-4550  
www.floyd.kyschools.us

Linda C. Gearheart, Board Chair - District 1  
William Newsome, Jr., Vice-Chair - District 3  
Dr. Chandra Varia, Member - District 2  
Keith Smallwood, Member - District 4  
Steve Stone, Member - District 5

**Consent Agenda Item (Action Item):** Consider/Approve authorizing the surplus of 1995 Eagle Man Lift.

**Applicable State or Regulations:** KRS 45A.365

**Fiscal/Budgetary Impact:** None

**History/Background:** During an inspection of the lift, found the swivel joint leaking oil in the engine compartment. The swivel joint seals that operates the boom were leaking also. The manufacture of the Eagle lift is no longer in business therefore the parts are discontinued and no old stock available. The lift cannot be repaired and is out of service.

**Recommended Action:** To declare the lift surplus and dispose.

**Contact Person(s):** Linda Hackworth, Chief Facilities Officer

N/A  
Principal

Linda Hackworth  
Director

Anna W. Shepherd  
Superintendent


**Date:** June 8, 2022



## Service Report

| Report Header Information |                      |                           |                      |               |                |
|---------------------------|----------------------|---------------------------|----------------------|---------------|----------------|
| Work Order                |                      | Dealer Code               | D487                 | Manufacturer  | EAGLE MAN LIFT |
| Employee ID               | 34355                | Service Date              | 6/7/2022             | Model         |                |
| Customer                  | FLOYD COUNTY SCHOOLS | Customer Equipment Number |                      | Serial Number |                |
| SMU                       | 0 Hours              | Equipment Location        | ALLEN CENTRAL OFFICE |               |                |
| IN Date                   |                      | Promise Date              |                      | OUT Date      |                |
| Instructions              |                      |                           |                      |               |                |

| Repair Background       |                                                                                                                                                                                                                                                                                                                                                                                   |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Segment No: 01          |                                                                                                                                                                                                                                                                                                                                                                                   |
| Customer Complaint      | LEAKING HYDRAULIC OIL IN ENGINE COMPARTMENT                                                                                                                                                                                                                                                                                                                                       |
| Cause of Failure        | LEAKING SEALS IN BOOM SWIVEL JOINT                                                                                                                                                                                                                                                                                                                                                |
| Resultant Damage        | LEAKING HYD OIL                                                                                                                                                                                                                                                                                                                                                                   |
| Repair Process Comments | CHECKED THE LIFT, FOUND THE SWIVEL JOINT LEAKING HYDRAULIC OIL IN ENGINE COMPARTMENT. THE SWIVEL JOINT SEALS THAT OPERATES THE BOOM IS LEAKING. THE MANUFACTURE OF THE EAGLE LIFT WAS OUT OF BUSINESS. THE PARTS FOR THE LIFT IS DISCONTINUED AND NO OLD STOCK AVAILABLE. THE MACHINE CAN NOT BE REPAIRED TO PASS ANNUAL BOOM LIFT INSPECTION AND IS OUT OF SERVICE AT THIS TIME. |

|                                                                                                           |                      |
|-----------------------------------------------------------------------------------------------------------|----------------------|
| Customer Signature<br> | Technician Signature |
|-----------------------------------------------------------------------------------------------------------|----------------------|