

PROJECT:	5056-01 Trans District Sup Fac 5056-01	DATE:	8/16/2023
VISIT NAME:	Construction Progress Site Visit	REPORT NO:	003
AUTHOR:	David Vaught	STATUS:	Final


VISIT DETAILS


WEATHER:	Mostly sunny temperature in the upper 80's	START TIME:	11:30 AM
		END TIME:	1:00 PM

GENERAL COMMENTS: A site visit was conducted on Wednesday August 16 to review earthwork progress at this time.
The following items were noted.

PARTICIPANT NAME	COMPANY	TITLE	EMAIL
Jimmy Piper	GRW	Project Architect	jpiper@grwinc.com
Seth Mittle	GRW		SMittle@grwinc.com
David Vaught	GRW	Project Manager	DVaught@grwinc.com


OBSERVATIONS


ITEM	REMARKS	DISCUSSION	PHOTO
003-001	Dumpster and Equipment on site		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-002	Dumpster and Equipment on site		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-003	Site Cleaning and Grading		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
003-004	Removal of unsatisfactory soils		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
003-005	Site clearing and grading Northwest		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-006	Existing utilities		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
003-007	Existing foundation wall		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
003-008	Site clearing and grading Northwest		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-009	Existing foundation wall		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
003-010	Existing foundation wall		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
003-011	Site clearing and grading northwest at fueling station		
	SPACE:	Exterior Site	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-012	Site clearing and grading south parking lot next to middle school		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-013	Site clearing and grading south parking lot next to middle school		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-014	Site clearing and grading view east from parking area		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-015	Site clearing and grading west edge of site		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-016	Site clearing and grading view toward northeast corner, bus entrance		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-017	Site clearing and grading view toward northeast corner, bus entrance		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-018	Site clearing and grading view toward southwest corner, detention basin		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-019	Site clearing and grading view toward northwest corner, fuel station		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-020	Site clearing and grading view toward northeast corner, bus entrance		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-021	Removal of unsatisfactory soil and large floaters.		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-022	Site clearing and grading view toward east, bus entrance		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-023	Site clearing and grading view toward southeast corner, building pad		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-024	Site clearing and grading view toward north corner, north end of building pad		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-025	Site clearing and grading view toward southwest corner, existing fire hydrant		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-026	Site clearing and grading, removal of unsatisfactory soil and existing asphalt paving		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-027	Site clearing and grading view toward southeast corner		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-028	Site clearing and grading view toward north corner, building pad		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-029	Site clearing and grading view toward south edge of site, standing water needs to be addressed.		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 003


ITEM	REMARKS	DISCUSSION	PHOTO
003-030	Site clearing and grading view toward east site, erosion control fence needs to be repaired.		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	


ITEM	REMARKS	DISCUSSION	PHOTO
003-031	Site clearing and grading view toward east edge of site, check erosion control		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

ITEM	REMARKS	DISCUSSION	PHOTO
003-032	Site clearing and grading view toward north, building pad		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

Site Visit - Construction Observation

DATE: 8/16/2023
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 003

ITEM	REMARKS	DISCUSSION	PHOTO
003-033	Site clearing and grading view toward northwest corner, existing bus lot		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

ITEM	REMARKS	DISCUSSION	PHOTO
003-034	Site clearing and grading view toward northeast corner, bus entrance		
	SPACE: Exterior Site	SUBJECT: Earthwork	
	CATEGORY: Earthwork	REFERENCE: 312000	

TO:

Kevin Pfefferman	Kenton County School District
Matthew Rigg	Kenton County School District

COPIES:

Jimmy Piper	GRW
Seth Mittle	GRW
David Vaught	GRW
Cory Sharrard	GRW
Todd Cantrell	GRW
Jon Marcum	GRW
Mike McReynolds	GRW
Jon Sheppard	GRW
Adolph Zell	Morel Construction
Anthony Berkemeier	Morel Construction