

PROJECT:	5056-01 Trans District Sup Fac 5056-01	DATE:	9/13/2023
VISIT NAME:	Construction Progress Site Visit	REPORT NO:	005
AUTHOR:	David Vaught	STATUS:	Final


VISIT DETAILS

WEATHER:	Mostly sunny, high in the mid 80's.	START TIME:	11:30 AM
		END TIME:	1:00 PM

GENERAL COMMENTS: A progress site visit was performed on September 13, 2023 at 11:30AM. the following items were noted.


PARTICIPANT NAME	COMPANY	TITLE	EMAIL
Seth Mittle	GRW		SMittle@grwinc.com
David Vaught	GRW	Project Manager	DVaught@grwinc.com
Mike McReynolds	GRW		mmcreynolds@grwinc.com


OBSERVATIONS


ITEM	REMARKS	DISCUSSION	PHOTO
005-001	Existing foundations removed and stock piled		
	SPACE:	005 - SITE - NORTH	
	CATEGORY:	Earthwork	
		SUBJECT:	Earthwork
		REFERENCE:	312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-002	Earthwork equipment stored on site		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-003	Existing foundations removed and stock piled		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-004	Earthwork in progress		
	SPACE:	007 - SITE - EAST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-005	Earthwork in progress		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-006	Earthwork in progress		
	SPACE:	007 - SITE - EAST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-007	Earthwork in progress, existing foundation walls removed.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-008	North building pad earthwork close to subgrade		
	SPACE:	007 - SITE - EAST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-009	Existing foundations to be removed		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-010	Earthwork in progress, existing foundation walls removed.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-011	Earthwork in progress, existing foundation walls removed.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-012	Earthwork in progress, existing foundation walls removed.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-013	RAP installation in progress, pier locations flagged.		
	SPACE:	007 - SITE - EAST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-014	RAP installation in progress, pier locations flagged.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-015	RAP installation in progress, pier locations flagged earthwork in progress at building pad.		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-016	RAP installation in progress, pier locations flagged.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-017	RAP installation in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-019	RAP installation in progress, pier locations flagged.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-020	RAP installation in progress		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-021	Erosion control fence installed. Earthwork in progress		
	SPACE:	007 - SITE - EAST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-022	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-023	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-024	RAP equipment stored on site		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-025	Earthwork in progress. Existing catch basin to be removed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-026	RAP drill bits stored at job site.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-027	RAP installation in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-029	Security fencing in place at existing road from middle school.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-030	RAP installation in progress. Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-031	Existing catch basin covered over. Ensure catch basin remains clean.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-032	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-033	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-034	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-035	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-036	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-037	Earthwork in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-038	Unsuitable material on site.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-039	West earthwork complete.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-040	West earthwork complete.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-041	Unsuitable material on site.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-042	West earthwork complete.		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-043	Erosion control fence installed.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-044	Earthwork in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-045	Erosion control fence installed at existing catch basin.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-046	Earthwork in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-047	Earthwork in progress		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-048	Erosion control fence installed		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-049	Earthwork in progress		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-050	Existing bus lot		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-051	Existing bus lot		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-052	Earthwork in progress		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-053	Earthwork in progress. Stock pile of unsuitable materials.		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-054	Earthwork in progress		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-055	Earthwork in progress		
	SPACE:	008 - SITE - WEST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-056	Earthwork in progress		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

ITEM	REMARKS	DISCUSSION	PHOTO
005-057	Earthwork in progress		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation


DATE: 9/13/2023
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 005


ITEM	REMARKS		DISCUSSION		PHOTO
005-058	Existing foundations to be removed				
	SPACE:	005 - SITE - NORTH	SUBJECT:	Earthwork	
	CATEGORY:	Earthwork	REFERENCE:	312000	


ITEM	REMARKS		DISCUSSION		PHOTO
005-059	Existing foundations removed				
	SPACE:	005 - SITE - NORTH	SUBJECT:	Earthwork	
	CATEGORY:	Earthwork	REFERENCE:	312000	

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-060	Existing foundations to be removed		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-061	Existing foundations removed and stock piled		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-062	Existing foundations to be removed		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-063	Existing foundations to be removed		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-064	Existing foundations to be removed		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-065	Earthwork in progress		
	SPACE:	007 - SITE - EAST	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-066	Equipment stored on site		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-067	South elevation building pad.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

ITEM	REMARKS	DISCUSSION	PHOTO
005-068	Existing conduit duct bank removed and stock piled.		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation


DATE: 9/13/2023
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-069	Existing conduit duct bank removed and stock piled.		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-070	Existing conduit duct bank removed and stock piled.		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-071	Existing conduit duct bank removed and stock piled.		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-072	South view building pad. RAP installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-073	South view building pad. RAP installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005


ITEM	REMARKS	DISCUSSION	PHOTO
005-074	Job site parking area entrance		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
005-075	Job site parking area		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

ITEM	REMARKS	DISCUSSION	PHOTO
005-076	Existing fuel tank stored on site		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

Site Visit - Construction Observation

DATE: 9/13/2023
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 005

ITEM	REMARKS	DISCUSSION	PHOTO
005-077	Existing fuel dispenser stored on site		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

ITEM	REMARKS	DISCUSSION	PHOTO
005-078	Materials being stored on site		
	SPACE:	005 - SITE - NORTH	SUBJECT: Earthwork
	CATEGORY:	Earthwork	REFERENCE: 312000

TO:

Kevin Pfefferman	Kenton County School District
Matthew Rigg	Kenton County School District
Brian Vanover	Kenton County School District

COPIES:

Jimmy Piper	GRW
Seth Mittle	GRW
David Vaught	GRW
Jacob Roberts	GRW
Cory Sharrard	GRW
Todd Cantrell	GRW
Jon Marcum	GRW
Mike McReynolds	GRW
Jon Sheppard	GRW
Adolph Zell	Morel Construction
Anthony Berkemeier	Morel Construction