

Progress Report

Report Date: 04/08/2024

Client: Hardin County School District

Facility: Central Hardin High School

Roof Section: Media Center

Report Data

Title Media center smooth cap 04/08

Smooth cap sheet application is now complete over the media center. All end and side laps are adhered nicely. The sheet is laying down nicely around drains and no dry laps were observed. Today the crew was adhering mineral cap sheet around the perimeter of the roof. Flashing bond is being applied to the back of each flashing and on the perimeter.




Photo 1

Overview of the completed cap sheet application.



Photo 2

Additional overview




Photo 3

Additional overview




Photo 4

Additional overview




Photo 5

The end laps are properly staggered.



End laps are free of dry laps.






Photo 7

Proper bleed out was observed at the side laps.




Photo 8

No dry laps were observed around the drains.




Photo 9

Additional view of the cap sheet laying down nicely around the drain.




Photo 10

Flashing bond is being applied to the back of each flashing.




Photo 11

Flashing bond is added to the perimeter as well.



Overview of the adhered flashings.






Photo 13

Additional view of the new flashings.




Photo 14

Additional view of the new flashings.




Photo 15

Additional view of the new flashings.