

# Site Visit - Construction Observation

PROJECT:	5056-01 Trans District Sup Fac 5056-01	DATE:	3/27/2024
VISIT NAME:	Construction Progress Site Visit	REPORT NO:	019
AUTHOR:	David Vaught	STATUS:	Final


## VISIT DETAILS

WEATHER:	Mostly sunny. High in the upper 50's	START TIME:	11:30 AM
		END TIME:	2:00 PM

GENERAL COMMENTS: A construction progress site visit was conducted on March 27, 2024.  
The following items were noted.


PARTICIPANT NAME	COMPANY	TITLE	EMAIL
David Vaught	GRW	Project Manager	DVaught@grwinc.com
Anthony Berkemeier	Morel Construction	Superintendent	aberkemeier@morelconstruction.net


## OBSERVATIONS

ITEM	REMARKS		DISCUSSION		PHOTO
019-001	Sanitary installation in progress				
	SPACE:	006 - SITE - SOUTH	SUBJECT:	3/27/24 at 11:20 AM	
	CATEGORY:	Sanitary	REFERENCE:	333113	

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-002	Sanitary installation in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 11:22 AM
	CATEGORY:	Sanitary	REFERENCE: 333113


ITEM	REMARKS	DISCUSSION	PHOTO
019-003	Sanitary installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 11:26 AM
	CATEGORY:	Sanitary	REFERENCE: 333113

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-004	Sanitary installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 11:30 AM
	CATEGORY:	Sanitary	REFERENCE: 333113


ITEM	REMARKS	DISCUSSION	PHOTO
019-005	Masonry wall installation in progress.		
	SPACE:	182 - PRINT AREA	SUBJECT: 3/27/24 at 11:33 AM
	CATEGORY:	Masonry / Concrete	REFERENCE: 033000 / 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-006	Concrete floor slab installation in progress.		
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT: 3/27/24 at 11:35 AM
	CATEGORY:	Concrete	REFERENCE: 033000

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-007	Concrete floor slab installation in progress.				
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	3/27/24 at 11:36 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-008	Concrete floor slab installation in progress.				
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	3/27/24 at 11:36 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-009	Concrete floor slab installation in progress.				
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	3/27/24 at 11:36 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-010	Concrete floor slab installation in progress.				
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	3/27/24 at 11:36 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	

ITEM	REMARKS		DISCUSSION		PHOTO
019-011	Concrete floor slab installation in progress.				
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	3/27/24 at 11:37 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	

## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-012	Concrete floor slab installation in progress.		
	SPACE: 134 - MAINTENANCE BAY 3	SUBJECT: 3/27/24 at 11:37 AM	
	CATEGORY: Concrete	REFERENCE: 033000	


ITEM	REMARKS	DISCUSSION	PHOTO
019-013	Concrete floor slab installation in progress.		
	SPACE: 136 - MAINTENANCE BAY 5	SUBJECT: 3/27/24 at 11:37 AM	
	CATEGORY: Concrete	REFERENCE: 033000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-014	Concrete floor slab installation in progress.		
	SPACE:	136 - MAINTENANCE BAY 5	SUBJECT: 3/27/24 at 11:38 AM
	CATEGORY:	Concrete	REFERENCE: 033000


ITEM	REMARKS	DISCUSSION	PHOTO
019-015	Concrete floor slab installation in progress.		
	SPACE:	138 - INSPECTION BAY 1	SUBJECT: 3/27/24 at 11:38 AM
	CATEGORY:	Concrete	REFERENCE: 033000

ITEM	REMARKS	DISCUSSION	PHOTO
019-016	Concrete floor slab installation in progress.		
	SPACE:	138 - INSPECTION BAY 1	SUBJECT: 3/27/24 at 11:38 AM
	CATEGORY:	Concrete	REFERENCE: 033000

## Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-017	Concrete floor slab installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:39 AM	
	CATEGORY: Concrete	REFERENCE: 033000	


ITEM	REMARKS	DISCUSSION	PHOTO
019-018	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:39 AM	
	CATEGORY: Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100	



## Site Visit - Construction Observation


DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-019	Masonry veneer and stone masonry veneer installation in progress.				
	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	3/27/24 at 11:40 AM	
	CATEGORY:	Masonry / Stone Masonry	REFERENCE:	042000 / 047323	

ITEM	REMARKS		DISCUSSION		PHOTO
019-020	Masonry veneer and stone masonry veneer installation in progress.				
	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	3/27/24 at 11:40 AM	
	CATEGORY:	Masonry / Stone Masonry	REFERENCE:	042000 / 047323	

## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-021	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:41 AM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	

ITEM	REMARKS	DISCUSSION	PHOTO
019-022	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:41 AM	
	CATEGORY: Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 047323	

## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-023	Masonry installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:41 AM	
	CATEGORY: Masonry	REFERENCE: 042000	

ITEM	REMARKS	DISCUSSION	PHOTO
019-024	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:42 AM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	

## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-025	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:42 AM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	

ITEM	REMARKS	DISCUSSION	PHOTO
019-026	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:43 AM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	

## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-027	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 11:43 AM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323


ITEM	REMARKS	DISCUSSION	PHOTO
019-028	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.		
	SPACE:	145 - CIRCULATION	SUBJECT: 3/27/24 at 11:44 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-029	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.		
	SPACE:	145 - CIRCULATION	SUBJECT: 3/27/24 at 11:44 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-030	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.		
	SPACE:	144 - STORAGE ROOM	SUBJECT: 3/27/24 at 11:45 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-031	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.		
	SPACE:	144 - STORAGE ROOM	SUBJECT: 3/27/24 at 11:46 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-032	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.		
	SPACE:	144 - STORAGE ROOM	SUBJECT: 3/27/24 at 11:46 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-033	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 3/27/24 at 11:47 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-034	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 3/27/24 at 11:47 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

## Site Visit - Construction Observation

DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019

ITEM	REMARKS		DISCUSSION		PHOTO
019-035	Masonry, Steel Joist Framing, and Steel Decking installation in progress.				
	SPACE:	142 - TIRE STORAGE	SUBJECT:	3/27/24 at 11:47 AM	
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100	


ITEM	REMARKS		DISCUSSION		PHOTO
019-036	Masonry, Steel Joist Framing, and Steel Decking installation in progress.				
	SPACE:	142 - TIRE STORAGE	SUBJECT:	3/27/24 at 11:48 AM	
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100	


ITEM	REMARKS		DISCUSSION		PHOTO
019-037	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.				
	SPACE:	145 - CIRCULATION	SUBJECT:	3/27/24 at 11:48 AM	
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE:	042000 / 052100 / 053100	



# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-038	Masonry, Steel Joist Framing, Steel Decking, storm drain installation in progress.		
	SPACE:	145 - CIRCULATION	SUBJECT: 3/27/24 at 11:49 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking / Storm Piping	REFERENCE: 042000 / 052100 / 053100

ITEM	REMARKS	DISCUSSION	PHOTO
019-039	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	146 - CIRCULATION	SUBJECT: 3/27/24 at 11:49 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-040	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	146 - CIRCULATION	SUBJECT: 3/27/24 at 11:49 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-041	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	147 - POL STORAGE ROOM	SUBJECT: 3/27/24 at 11:50 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-042	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	147 - POL STORAGE ROOM	SUBJECT: 3/27/24 at 11:50 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-043	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	147 - POL STORAGE ROOM	SUBJECT: 3/27/24 at 11:50 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-044	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	147 - POL STORAGE ROOM	SUBJECT: 3/27/24 at 11:50 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-045	Masonry installation in progress.				
	SPACE:	147 - POL STORAGE ROOM	SUBJECT:	3/27/24 at 11:51 AM	
	CATEGORY:	Masonry	REFERENCE:	042000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-046	Masonry installation in progress.				
	SPACE:	147 - POL STORAGE ROOM	SUBJECT:	3/27/24 at 11:51 AM	
	CATEGORY:	Masonry	REFERENCE:	042000	

ITEM	REMARKS		DISCUSSION		PHOTO
019-047	Masonry, Steel Joist Framing, and Steel Decking installation in progress.				
	SPACE:	147 - POL STORAGE ROOM	SUBJECT:	3/27/24 at 11:51 AM	
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100	

## Site Visit - Construction Observation


DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-048	Masonry, Steel Joist Framing, and Steel Decking installation in progress.				
	SPACE:	149 - BATTERY STORAGE / CHARGING	SUBJECT:	3/27/24 at 11:52 AM	
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100	

ITEM	REMARKS		DISCUSSION		PHOTO
019-049	Masonry, Steel Joist Framing, and Steel Decking installation in progress.				
	SPACE:	150 - FLAMMABLE STORAGE AREA	SUBJECT:	3/27/24 at 11:52 AM	
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100	

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-050	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	150 - FLAMMABLE STORAGE AREA	SUBJECT: 3/27/24 at 11:52 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

ITEM	REMARKS	DISCUSSION	PHOTO
019-051	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	150 - FLAMMABLE STORAGE AREA	SUBJECT: 3/27/24 at 11:53 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-052	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	146 - CIRCULATION	SUBJECT: 3/27/24 at 11:53 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

ITEM	REMARKS	DISCUSSION	PHOTO
019-053	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	153 - END OF BAY STORAGE	SUBJECT: 3/27/24 at 11:54 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-054	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	153 - END OF BAY STORAGE	SUBJECT: 3/27/24 at 11:54 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


ITEM	REMARKS	DISCUSSION	PHOTO
019-055	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	153 - END OF BAY STORAGE	SUBJECT: 3/27/24 at 11:54 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100



# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-056	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE: 153 - END OF BAY STORAGE	SUBJECT: 3/27/24 at 11:54 AM	
	CATEGORY: Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100	

ITEM	REMARKS	DISCUSSION	PHOTO
019-057	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE: 141 - PARTS / INVENTORY	SUBJECT: 3/27/24 at 11:55 AM	
	CATEGORY: Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100	

## Site Visit - Construction Observation


DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-058	Masonry, Steel Joist Framing, and Steel Decking installation in progress.		
	SPACE:	141 - PARTS / INVENTORY	SUBJECT: 3/27/24 at 11:55 AM
	CATEGORY:	Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

ITEM	REMARKS	DISCUSSION	PHOTO
019-059	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	140 - PARTS STORAGE	SUBJECT: 3/27/24 at 11:55 AM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323

## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-060	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	140 - PARTS STORAGE	SUBJECT: 3/27/24 at 11:56 AM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323


ITEM	REMARKS	DISCUSSION	PHOTO
019-061	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	140 - PARTS STORAGE	SUBJECT: 3/27/24 at 11:56 AM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-062	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 140 - PARTS STORAGE	SUBJECT: 3/27/24 at 11:56 AM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	


ITEM	REMARKS	DISCUSSION	PHOTO
019-063	Concrete floor slab installation in progress.		
	SPACE: 138 - INSPECTION BAY 1	SUBJECT: 3/27/24 at 11:57 AM	
	CATEGORY: Concrete	REFERENCE: 033000	


ITEM	REMARKS	DISCUSSION	PHOTO
019-064	Masonry installation in progress.		
	SPACE: 137 - MAINTENANCE BAY 6	SUBJECT: 3/27/24 at 11:57 AM	
	CATEGORY: Masonry	REFERENCE: 042000	

## Site Visit - Construction Observation

DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-065	Concrete floor slab installation in progress.				
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	3/27/24 at 11:57 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-066	Concrete floor slab installation in progress.				
	SPACE:	136 - MAINTENANCE BAY 5	SUBJECT:	3/27/24 at 11:58 AM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-067	Masonry and hollow metal door frame installation in progress.				
	SPACE:	139 - INSPECTION BAY 2	SUBJECT:	3/27/24 at 11:58 AM	
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE:	042000 / 081113	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-068	Masonry and hollow metal door frame installation in progress.		
	SPACE:	139 - INSPECTION BAY 2	SUBJECT: 3/27/24 at 11:59 AM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113


ITEM	REMARKS	DISCUSSION	PHOTO
019-069	Masonry and hollow metal door frame installation in progress.		
	SPACE:	139 - INSPECTION BAY 2	SUBJECT: 3/27/24 at 11:59 AM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113


ITEM	REMARKS	DISCUSSION	PHOTO
019-070	Masonry installation in progress.		
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT: 3/27/24 at 11:59 AM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-071	Concrete floor slab installation in progress.				
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT:	3/27/24 at 12:00 PM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-072	Masonry installation in progress.				
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT:	3/27/24 at 12:00 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-073	Masonry installation in progress.				
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT:	3/27/24 at 12:02 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019

ITEM	REMARKS	DISCUSSION	PHOTO
019-074	Masonry installation in progress.		
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT: 3/27/24 at 12:03 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-075	Masonry installation in progress.		
	SPACE:	131 - CIRCULATION	SUBJECT: 3/27/24 at 12:03 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-076	Masonry installation in progress.		
	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT: 3/27/24 at 12:04 PM
	CATEGORY:	Masonry	REFERENCE: 042000




# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-077	Masonry installation in progress.		
	SPACE:	103 - CIRCULATION	SUBJECT: 3/27/24 at 12:05 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-078	Masonry installation in progress.		
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT: 3/27/24 at 12:06 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-079	Masonry installation in progress.		
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT: 3/27/24 at 12:06 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-080	Masonry installation in progress.		
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT: 3/27/24 at 12:06 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-081	Masonry installation in progress.		
	SPACE:	103 - CIRCULATION	SUBJECT: 3/27/24 at 12:06 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-082	Masonry installation in progress.		
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT: 3/27/24 at 12:07 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-083	Masonry installation in progress.				
	SPACE:	172 - CIRCULATION	SUBJECT:	3/27/24 at 12:07 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-084	Masonry installation in progress.				
	SPACE:	162 - CIRCULATION	SUBJECT:	3/27/24 at 12:07 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-085	Masonry installation in progress.				
	SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT:	3/27/24 at 12:08 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-086	Masonry installation in progress.		
	SPACE:	182 - PRINT AREA	SUBJECT: 3/27/24 at 12:08 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-087	Concrete floor slab installation in progress.		
	SPACE:	183 - WAREHOUSE	SUBJECT: 3/27/24 at 12:09 PM
	CATEGORY:	Concrete	REFERENCE: 033000


ITEM	REMARKS	DISCUSSION	PHOTO
019-088	Concrete column reinforcing installation in progress.		
	SPACE:	183 - WAREHOUSE	SUBJECT: 3/27/24 at 12:10 PM
	CATEGORY:	Concrete	REFERENCE: 033000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-089	Concrete floor slab installation in progress.		
	SPACE: 184 - COVERED LOADING DOCK	SUBJECT: 3/27/24 at 12:10 PM	
	CATEGORY: Concrete	REFERENCE: 033000	


ITEM	REMARKS	DISCUSSION	PHOTO
019-090	Concrete crack at door threshold. Remove and replace per specification section 033000 3.14 A2.		
	SPACE: 108 - CIRCULATION	SUBJECT: 3/27/24 at 12:11 PM	
	CATEGORY: Concrete	REFERENCE: 033000	


ITEM	REMARKS	DISCUSSION	PHOTO
019-091	Concrete floor slab installation in progress.		
	SPACE: 154 - WORK SPACE PLUMBING	SUBJECT: 3/27/24 at 12:11 PM	
	CATEGORY: Concrete	REFERENCE: 033000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-092	Concrete floor slab installation in progress.				
	SPACE:	155 - WORK SPACE ELECTRICIAN	SUBJECT:	3/27/24 at 12:12 PM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-093	Concrete floor slab installation in progress.				
	SPACE:	156 - WORK SPACE HVAC	SUBJECT:	3/27/24 at 12:12 PM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-094	Concrete floor slab installation in progress.				
	SPACE:	158 - TRAINING ROOM	SUBJECT:	3/27/24 at 12:12 PM	
	CATEGORY:	Concrete	REFERENCE:	033000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-095	Concrete floor slab installation in progress.				
	SPACE:	157 - WORK SPACE CARPENTRY	SUBJECT:	3/27/24 at 12:13 PM	
	CATEGORY:	Concrete	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-096	Concrete floor slab installation in progress.				
	SPACE:	157 - WORK SPACE CARPENTRY	SUBJECT:	3/27/24 at 12:13 PM	
	CATEGORY:	Concrete	REFERENCE:	033000	

ITEM	REMARKS		DISCUSSION		PHOTO
019-097	Masonry installation in progress.				
	SPACE:	107 - CIRCULATION	SUBJECT:	3/27/24 at 12:15 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-098	Masonry installation in progress.				
	SPACE:	128 - GARAGE MANAGER OFFICE	SUBJECT:	3/27/24 at 12:15 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-099	Masonry installation in progress.				
	SPACE:	129 - ADMIN. ASSISTANT OFFICE	SUBJECT:	3/27/24 at 12:15 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	



# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-100	Masonry installation in progress.		
	SPACE:	128 - GARAGE MANAGER OFFICE	SUBJECT: 3/27/24 at 12:16 PM
	CATEGORY:	Masonry	REFERENCE: 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-101	Masonry installation in progress.		
	SPACE:	130 - MECHANIC BREAK ROOM	SUBJECT: 3/27/24 at 12:16 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-102	Masonry / electrical rough in installation in progress.		
	SPACE:	130 - MECHANIC BREAK ROOM	SUBJECT: 3/27/24 at 12:17 PM
	CATEGORY:	Masonry / Electrical Rough In	REFERENCE: 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-103	Masonry installation in progress.		
	SPACE:	109 - SHARED LOADING DOCK	SUBJECT: 3/27/24 at 12:17 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-104	Masonry installation in progress.		
	SPACE:	103 - CIRCULATION	SUBJECT: 3/27/24 at 12:18 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-105	Masonry installation in progress.		
	SPACE:	109 - SHARED LOADING DOCK	SUBJECT: 3/27/24 at 12:18 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-106	Masonry installation in progress.		
	SPACE:	118 - FREEZER STORAGE	SUBJECT: 3/27/24 at 12:18 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-107	Masonry installation in progress.		
	SPACE:	117 - DRY FOOD STORAGE	SUBJECT: 3/27/24 at 12:19 PM
	CATEGORY:	Masonry	REFERENCE: 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-108	Masonry installation in progress.		
	SPACE:	118 - FREEZER STORAGE	SUBJECT: 3/27/24 at 12:19 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-109	Masonry installation in progress.		
	SPACE:	109 - SHARED LOADING DOCK	SUBJECT: 3/27/24 at 12:19 PM
	CATEGORY:	Masonry	REFERENCE: 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-110	Masonry installation in progress.		
	SPACE:	115 - VENDER RECEIVING AREA	SUBJECT: 3/27/24 at 12:20 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-111	Masonry / hollow metal frame installation in progress.		
	SPACE:	114 - SHARED LOADING DOCK	SUBJECT: 3/27/24 at 12:20 PM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113

ITEM	REMARKS	DISCUSSION	PHOTO
019-112	Masonry / fire protection installation in progress.		
	SPACE:	116 - FIRE PROTECTION / DOMESTIC WATER CLOSET	SUBJECT: 3/27/24 at 12:20 PM
	CATEGORY:	Masonry / Fire Protection	REFERENCE: 042000

## Site Visit - Construction Observation


DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-113	Masonry installation in progress.				
	SPACE:	116 - FIRE PROTECTION / DOMESTIC WATER CLOSET	SUBJECT:	3/27/24 at 12:20 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	

ITEM	REMARKS		DISCUSSION		PHOTO
019-114	Hollow metal door frame installation in progress. Ensure hollow metal frame is Fire rated at the elevator machine room.				
	SPACE:	113 - ELEVATOR MECHANICAL	SUBJECT:	3/27/24 at 12:21 PM	
	CATEGORY:	Hollow Metal Door Frame	REFERENCE:	081113	

## Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-115	Masonry / hollow metal frame installation in progress.		
	SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT: 3/27/24 at 12:22 PM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113


ITEM	REMARKS	DISCUSSION	PHOTO
019-116	Masonry / hollow metal frame installation in progress.		
	SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT: 3/27/24 at 12:22 PM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113



# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-117	Masonry installation in progress.		
	SPACE:	121 - MALE RESTROOM	SUBJECT: 3/27/24 at 12:22 PM
	CATEGORY:	Masonry	REFERENCE: 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-118	Masonry installation in progress.		
	SPACE:	113 - ELEVATOR MECHANICAL	SUBJECT: 3/27/24 at 12:23 PM
	CATEGORY:	Masonry	REFERENCE: 042000

# Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-119	Masonry / hollow metal frame installation in progress.		
	SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT: 3/27/24 at 12:23 PM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113

ITEM	REMARKS	DISCUSSION	PHOTO
019-120	Masonry installation in progress.		
	SPACE:	112 - SERVICE ELEVATOR	SUBJECT: 3/27/24 at 12:24 PM
	CATEGORY:	Masonry	REFERENCE: 042000

## Site Visit - Construction Observation


DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-121	Masonry installation in progress.		
	SPACE:	112 - SERVICE ELEVATOR	SUBJECT: 3/27/24 at 12:24 PM
	CATEGORY:	Masonry	REFERENCE: 042000

ITEM	REMARKS	DISCUSSION	PHOTO
019-122	Masonry installation in progress.		
	SPACE:	112 - SERVICE ELEVATOR	SUBJECT: 3/27/24 at 12:25 PM
	CATEGORY:	Masonry	REFERENCE: 042000

## Site Visit - Construction Observation


DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-123	Masonry / hollow metal frame installation in progress.				
	SPACE:	111 - STAIR B	SUBJECT:	3/27/24 at 12:25 PM	
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE:	042000 / 081113	


ITEM	REMARKS		DISCUSSION		PHOTO
019-124	Masonry installation in progress.				
	SPACE:	111 - STAIR B	SUBJECT:	3/27/24 at 12:25 PM	
	CATEGORY:	Masonry	REFERENCE:	042000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-125	Masonry / hollow metal frame installation in progress.		
	SPACE:	111 - STAIR B	SUBJECT: 3/27/24 at 12:25 PM
	CATEGORY:	Masonry / Hollow Metal Frame	REFERENCE: 042000 / 081113


ITEM	REMARKS	DISCUSSION	PHOTO
019-126	Masonry installation in progress.		
	SPACE:	118 - FREEZER STORAGE	SUBJECT: 3/27/24 at 12:27 PM
	CATEGORY:	Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
019-127	Concrete floor slab installation in progress.		
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT: 3/27/24 at 12:29 PM
	CATEGORY:	Concrete	REFERENCE: 033000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-128	Earthwork / Storm Drain installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:29 PM
	CATEGORY:	Earthwork / Storm Drain	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-129	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	001 - NORTH ELEVATION	SUBJECT: 3/27/24 at 12:31 PM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323


ITEM	REMARKS	DISCUSSION	PHOTO
019-130	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 12:31 PM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-131	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 12:32 PM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	


ITEM	REMARKS	DISCUSSION	PHOTO
019-132	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 3/27/24 at 12:32 PM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	


ITEM	REMARKS	DISCUSSION	PHOTO
019-133	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE: 001 - NORTH ELEVATION	SUBJECT: 3/27/24 at 12:33 PM	
	CATEGORY: Masonry / Stone Masonry	REFERENCE: 042000 / 047323	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019

ITEM	REMARKS	DISCUSSION	PHOTO
019-134	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	001 - NORTH ELEVATION	SUBJECT: 3/27/24 at 12:33 PM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323


ITEM	REMARKS	DISCUSSION	PHOTO
019-135	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	001 - NORTH ELEVATION	SUBJECT: 3/27/24 at 12:33 PM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323


ITEM	REMARKS	DISCUSSION	PHOTO
019-136	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	001 - NORTH ELEVATION	SUBJECT: 3/27/24 at 12:34 PM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323




# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-137	Masonry veneer and stone masonry veneer installation in progress.		
	SPACE:	002 - SOUTH ELEVATION	SUBJECT: 3/27/24 at 12:35 PM
	CATEGORY:	Masonry / Stone Masonry	REFERENCE: 042000 / 047323


ITEM	REMARKS	DISCUSSION	PHOTO
019-138	Earthwork / Storm Drain installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:35 PM
	CATEGORY:	Earthwork / Storm Drain	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-139	Earthwork installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:36 PM
	CATEGORY:	Earthwork	REFERENCE: 312000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-140	Earthwork / Storm Drain installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:36 PM
	CATEGORY:	Earthwork / Storm Drain	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-141	Earthwork installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:37 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-142	Earthwork installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:38 PM
	CATEGORY:	Earthwork	REFERENCE: 312000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-143	Earthwork installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:38 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-144	Earthwork installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:38 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-145	Earthwork installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 3/27/24 at 12:39 PM
	CATEGORY:	Earthwork	REFERENCE: 312000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-146	Earthwork installation in progress. Maintain erosion control fencing.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:39 PM
	CATEGORY:	Earthwork / Erosion Control	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-147	Earthwork installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:39 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-148	Earthwork installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:40 PM
	CATEGORY:	Earthwork	REFERENCE: 312000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-149	Modular block retaining wall installation in progress.				
	SPACE:	006 - SITE - SOUTH	SUBJECT:	3/27/24 at 12:40 PM	
	CATEGORY:	Modular Block Retaining Wall	REFERENCE:	323223	


ITEM	REMARKS		DISCUSSION		PHOTO
019-150	Modular block retaining wall installation in progress.				
	SPACE:	006 - SITE - SOUTH	SUBJECT:	3/27/24 at 12:41 PM	
	CATEGORY:	Modular Block Retaining Wall	REFERENCE:	323223	


ITEM	REMARKS		DISCUSSION		PHOTO
019-151	Modular block retaining wall installation in progress.				
	SPACE:	006 - SITE - SOUTH	SUBJECT:	3/27/24 at 12:42 PM	
	CATEGORY:	Modular Block Retaining Wall	REFERENCE:	323223	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-152	Sanitary installation in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:42 PM
	CATEGORY:	Sanitary	REFERENCE: 333113


ITEM	REMARKS	DISCUSSION	PHOTO
019-153	Sanitary installation in progress		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:42 PM
	CATEGORY:	Sanitary	REFERENCE: 333113


ITEM	REMARKS	DISCUSSION	PHOTO
019-154	Modular block retaining wall installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:43 PM
	CATEGORY:	Modular Block Retaining Wall	REFERENCE: 323223

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-155	Earthwork installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:44 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-156	Earthwork installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:44 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-157	Earthwork / detention basin installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:45 PM
	CATEGORY:	Earthwork / Detention Basin	REFERENCE: 312000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019

ITEM	REMARKS		DISCUSSION		PHOTO
019-158	Earthwork / detention basin installation in progress.				
	SPACE:	006 - SITE - SOUTH	SUBJECT:	3/27/24 at 12:45 PM	
	CATEGORY:	Earthwork / Detention Basin	REFERENCE:	312000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-159	Earthwork / detention basin installation in progress.				
	SPACE:	008 - SITE - WEST	SUBJECT:	3/27/24 at 12:45 PM	
	CATEGORY:	Earthwork / Detention Basin	REFERENCE:	312000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-160	Earthwork / detention basin installation in progress.				
	SPACE:	008 - SITE - WEST	SUBJECT:	3/27/24 at 12:45 PM	
	CATEGORY:	Earthwork / Detention Basin	REFERENCE:	312000	




## Site Visit - Construction Observation

DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019


ITEM	REMARKS		DISCUSSION		PHOTO
019-161	Fuel island concrete and bollard installation in progress.				
	SPACE:	008 - SITE - WEST	SUBJECT:	3/27/24 at 12:46 PM	
	CATEGORY:	Fuel Island	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-162	Fuel storage area concrete and bollard installation in progress.				
	SPACE:	008 - SITE - WEST	SUBJECT:	3/27/24 at 12:46 PM	
	CATEGORY:	Fuel Storage Area	REFERENCE:	033000	


ITEM	REMARKS		DISCUSSION		PHOTO
019-163	Fuel storage area concrete and bollard installation in progress.				
	SPACE:	008 - SITE - WEST	SUBJECT:	3/27/24 at 12:47 PM	
	CATEGORY:	Fuel Storage Area	REFERENCE:	033000	

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-164	Earthwork / detention basin installation in progress.		
	SPACE:	008 - SITE - WEST	SUBJECT: 3/27/24 at 12:47 PM
	CATEGORY:	Earthwork / Detention Basin	REFERENCE: 312000 / 334113


ITEM	REMARKS	DISCUSSION	PHOTO
019-165	Earthwork / detention basin installation in progress.		
	SPACE:	008 - SITE - WEST	SUBJECT: 3/27/24 at 12:47 PM
	CATEGORY:	Earthwork / Detention Basin	REFERENCE: 312000 / 334113


ITEM	REMARKS	DISCUSSION	PHOTO
019-166	Earthwork / detention basin installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:48 PM
	CATEGORY:	Earthwork / Detention Basin	REFERENCE: 312000 / 334113

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-167	Earthwork / detention basin installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 3/27/24 at 12:48 PM
	CATEGORY:	Earthwork / Detention Basin	REFERENCE: 312000 / 334113


ITEM	REMARKS	DISCUSSION	PHOTO
019-168	Earthwork installation in progress.		
	SPACE:	008 - SITE - WEST	SUBJECT: 3/27/24 at 12:49 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-169	Fuel storage area concrete and bollard installation in progress.		
	SPACE:	008 - SITE - WEST	SUBJECT: 3/27/24 at 12:49 PM
	CATEGORY:	Fuel Storage Area	REFERENCE: 033000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-170	Materials currently stored on site.		
	SPACE:	008 - SITE - WEST	SUBJECT: 3/27/24 at 12:49 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-171	Earthwork installation in progress.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:50 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-172	Earthwork installation in progress.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:51 PM
	CATEGORY:	Earthwork	REFERENCE: 312000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-173	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:51 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-174	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:52 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-175	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:52 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-176	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:52 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-177	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:53 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-178	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:54 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-179	Earthwork installation in progress.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:54 PM
	CATEGORY:	Earthwork	REFERENCE: 312000


ITEM	REMARKS	DISCUSSION	PHOTO
019-180	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:54 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

ITEM	REMARKS	DISCUSSION	PHOTO
019-181	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:54 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-182	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:55 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-183	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:55 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000



## Site Visit - Construction Observation


DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-184	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:56 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-185	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:56 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-186	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:56 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-187	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:57 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-188	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:57 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019


ITEM	REMARKS	DISCUSSION	PHOTO
019-189	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:57 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-190	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:58 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000


ITEM	REMARKS	DISCUSSION	PHOTO
019-191	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:58 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

# Site Visit - Construction Observation

DATE: 3/27/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 019

ITEM	REMARKS	DISCUSSION	PHOTO
019-192	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:59 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

ITEM	REMARKS	DISCUSSION	PHOTO
019-193	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 12:59 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

ITEM	REMARKS	DISCUSSION	PHOTO
019-194	Materials currently stored on site.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 3/27/24 at 1:00 PM
	CATEGORY:	Site Stored Materials	REFERENCE: 000000

TO:

Carrie Hooten	Kenton County School District
Kevin Pfefferman	Kenton County School District
Matthew Rigg	Kenton County School District
Brian Vanover	Kenton County School District

## Site Visit - Construction Observation

DATE: 3/27/2024  
VISIT NAME: Construction  
Progress Site Visit  
REPORT NO: 019

---

### COPIES:

Seth Mittle	GRW
David Vaught	GRW
Todd Cantrell	GRW
Mike McReynolds	GRW
Jon Sheppard	GRW
Jim Adams	Facility Commissioning Group
Adolph Zell	Morel Construction
Anthony Berkemeier	Morel Construction