

Inspection Report



Prepared For:



Powell County Schools Powell County Middle School 770 W College Ave Stanton, KY 40380





Site Overview

Total Sections: 4
Total Sq/Ft: 68,102



Мар	Section Name	
1	Section 1	
2	Section 2	
3	Section 3	
4	Section 4	

Sq/Ft	Grade
14,365	D
36,964	D-
6,817	D-
9,956	D-





Composition

Section: Section 1 Size: 14,365 Overall Grade: D









Composition

Section: Section 1 Size: 14,365 Overall Grade: D



Core Sample Composition

- -Modified Bitumen
- -Poly ISO
- -Metal Deck





Core Sample Thickness





Section Overview

Section: Section 1

Size: 14,365

Overall Grade: D













Observations

Section: Section 1 Size: 14,365 Overall Grade: D





Metal Deck



Existing Drain Clogged



Small Overflow Scuppers



Existing unit Curbs Not in Use



Deficiencies

Section: Section 1 Size: 14,365

Overall Grade: D

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs





Existing Drainage System Clogged

Quantity: 0 null **Deficiency:**

The clogging of this drain could lead to leaks and unnecessary water buildup. This could lead to weight over burden on the structure.

Corrective Action:

We cleaned the drain while we were on site. However, we recommend putting a maintenance program together that will address the drains.





Summary

Section: Section 1

Size: 14,365

Overall Grade: D

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs



Condition Summary

Membrane: D-Flashings: C-Sheet Metal: C-

Overall:

Estimated Replace: 2027

- A Roof is "New" or in "Like New" condition. Continue to monitor and maintain.
- B Roof is "Good" condition. General repairs may be required and a maintenance program may minimize unnecessary leaks
- C Roof is in "Fair" condition. The roof is beginning to show age-related deficiencies, or is a newer roof that is not performing as expected. A maintenance program may help prevent unnecessary leaks and minimize repair costs.
- D Roof is in "Poor" condition and is nearing the end of its useful life. Repairs could help reduce unexpected leaks, depending on the severity.
- F Roof has failed. The roof has exceeded its expected service life. While it may be possible to address active leaks, it should be assumed that leaks will continue to develop.

Recommendations:

The existing roof system is weathering consistent with its age. This roof would be a good candidate for a membrane overlay. We did not observe any locations that indicated moisture saturation in the system. The existing core samples were dry and free from observable moisture.





Section Overview

Section: Section 2

Size: 36,964

Overall Grade: D-













Observations

Section: Section 2

Size: 36,964


Overall Grade: D-



Scupper & Ventilated Headwall Flashing



Stanard Pitch for all Structures





Improper Repairs





Deficiencies

Section: Section 2

Size: 36,964

Overall Grade: D-

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs





Animal Damage to Lead Pipe Boot (Emergency)

Quantity: -2 null

Deficiency:

The lead pipe boots on the roof show signs of damage.

Squirrels will often chew on boots like this.

Corrective Action:

Replace pipe boots with EPDM boot flashings in lieu of lead.



Masonry Cracking @ Front Parapet (Emergency)

Quantity: 0 null

Deficiency:

This cracking can allow water to penetrate and appear to

come from the roof.

Corrective Action:

Hire a tuckpointing professional to seal masonry cracks.





Deficiencies

Section: Section 2

Size: 36,964

Overall Grade: D-

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs





Missing Shingles (Emergency)

Quantity: 0 null **Deficiency:**

Shingle damage could lead to water infiltration.

Corrective Action:

Replace shingles in this area until roof can be replaced.



Incorrect Boot Installation

Quantity: 0 null **Deficiency:**

The boot at this location it not appropriate for shingle use.

Corrective Action:

Replace pipe boot with appropriate boot and seal until the roof can be replaced.





Summary

Section: Section 2

Size: 36,964

Overall Grade: D-

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs



Condition Summary

Membrane: Flashings:

Sheet Metal:

Overall:

D-

Estimated Replace:

Recommendations:

Replace shingle roof.

- A Roof is "New" or in "Like New" condition. Continue to monitor and maintain.
- B Roof is "Good" condition. General repairs may be required and a maintenance program may minimize unnecessary leaks
- C Roof is in "Fair" condition. The roof is beginning to show age-related deficiencies, or is a newer roof that is not performing as expected. A maintenance program may help prevent unnecessary leaks and minimize repair costs.
- D Roof is in "Poor" condition and is nearing the end of its useful life. Repairs could help reduce unexpected leaks, depending on the severity.
- F Roof has failed. The roof has exceeded its expected service life. While it may be possible to address active leaks, it should be assumed that leaks will continue to develop.



Section Overview

Section: Section 3

Size: 6,817

Overall Grade: D-















Summary

Section: Section 3

Size: 6,817

Overall Grade: D-

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs



Condition Summary

Membrane: D-Flashings: D-Sheet Metal: D-Overall: D-

Estimated Replace: 2026

- A Roof is "New" or in "Like New" condition. Continue to monitor and maintain.
- B Roof is "Good" condition. General repairs may be required and a maintenance program may minimize unnecessary leaks
- C Roof is in "Fair" condition. The roof is beginning to show age-related deficiencies, or is a newer roof that is not performing as expected. A maintenance program may help prevent unnecessary leaks and minimize repair costs.
- D Roof is in "Poor" condition and is nearing the end of its useful life. Repairs could help reduce unexpected leaks, depending on the severity.
- F Roof has failed. The roof has exceeded its expected service life. While it may be possible to address active leaks, it should be assumed that leaks will continue to develop.

Recommendations:

We recommend the full replacement of this roof due to age.





Section Overview

Section: Section 4

Size: 9,956

Overall Grade: D-













Observations

Section: Section 4

Size: 9,956

Overall Grade: D-



Masonry Cracking







Summary

Section: Section 4

Size: 9,956

Overall Grade: D-

Inspection Date: 04/28/2025 **Inspected By:** Lars Griggs



Condition Summary

Membrane: D-Flashings: D-Sheet Metal: D-Overall: D-

Estimated Replace: 2026

Recommendations:

Replace existing shingle roof.

- A Roof is "New" or in "Like New" condition. Continue to monitor and maintain.
- B Roof is "Good" condition. General repairs may be required and a maintenance program may minimize unnecessary leaks
- C Roof is in "Fair" condition. The roof is beginning to show age-related deficiencies, or is a newer roof that is not performing as expected. A maintenance program may help prevent unnecessary leaks and minimize repair costs.
- D Roof is in "Poor" condition and is nearing the end of its useful life. Repairs could help reduce unexpected leaks, depending on the severity.
- F Roof has failed. The roof has exceeded its expected service life. While it may be possible to address active leaks, it should be assumed that leaks will continue to develop.