TO	O:	DR. MICHAEL RAISOR CHIEF OPERATIONS O	FFICER			
FI	ROM:	MICHAEL A. MULHEIR FACILITIES AND ENVI	N, DIRECTOR RONMENTAL SERVICES			
SI	UBJECT:	APPROVAL OF CONST	RUCTION CHANGE ORDERS			
D	ATE:	SEPTEMBER 22, 2014				
BG# 14-085 13-258 13-259 14-107	LET# 14013 13037 13036 14025	CONTRACTOR  Marksbury Cornett E.H. Construction  Morel Construction  Highland Roofing	SCHOOL/PROJECT Ballard HS-Courtyard Modifications Lowe ES-Phase 1 HVAC Renovation Southern HS-Phase 1 HVAC Renovation Fern Creek THS- Roof Replacement	C.O.# 02 02 04 01	AMOUNT 1,463.50 6,879.38 4,322.00 3,912.00	
	Secretary, Board of Education  After full discussion, the Chairman put t		Chairman, Board of Educate the question of the adoption of this resolution be mber 22, 2014 and the following voted:		erson	

VOTING AYE:

VOTING NAY:

PASSED AND APPROVED:

## BOARD OF EDUCATION MEETING SEPTEMBER 22, 2014

Courtyard Modification	ons @ Ballard HS	Change Order # 02			
Original Contract Previous Approved		Current Change Order Total Contract Amount		Total Project Cost to	
Amount	Change Order Amount	Amount	to Date	Date	
79,000.00	13,300.00	1,463.50	93,763.50	94,118.89	

1. Add concrete sidewalks and 2 each additional pipe bollards. Justification: Found Condition. Existing concrete sidewalk had to be adjusted. Bollards were added to protect doors.

Phase 1 HVAC Renov	ation @ Lowe ES	Change Order # 02		
Original Contract Previous Approved		Current Change Order	Total Contract Amount	Total Project Cost to
Amount	Change Order Amount	Amount	to Date	Date
4,523,000.00	-72,557.51	6,879.38	4,457,321.87	3,436,906.78

- 1. Credit for not removing conduit for main service. Justification: Owner requested. Discovered opportunity to save money during construction.
- 2. Replace receptacle for vending machine. Justification: Found condition.
- 3. Remove mailboxes and provide CMU infill. Justification: Owner requested. School requested, no longer using room for mail.
- 4. New CMU half partition at Women's room. Justification: Found condition.
- 5. Install additional rebar for storage tank pad. Justification: Found condition.
- 6. Remove wall board with mastic in the lobby. Justification: Found condition.
- 7. X-ray slabs. Justification: Found condition.
- 8. Remove trench rock at sanitary line. Justification: Found condition.
- 9. Abate VCT hidden below carpet in Room 123. Justification: Found condition.
- 10. Install missing column at new Art room. Justification: Found condition.

Phase 1 HVAC Renov	ation @ Southern HS	Change Order # 04		
Original Contract	Original Contract Previous Approved		<b>Total Contract Amount</b>	Total Project Cost to
Amount	Change Order Amount	Amount	to Date	Date
18,768,000.00	23,548.98	4,322.00	18,795,870.98	9,566,013.39

- 1. Demo plaster ceiling in band area. Justification: Found condition.
- 2. Delete window Type KK at the boiler stack. Justification: Found condition. Cost saving to Jefferson County Public Schools.
- 3. Demo ceiling at the Tool & Die Supply Room. Justification: Found Condition.
- 4. Adjust Substantial Completion date for Phase 1 from August 1, 2014 to August 6, 2014. Justification: Found conditions.
- 5. Add a data drop in the Principals Secretary's office. Justification: Owner requested. School needed additional drop.
- 6. Add Type "AS" light fixture at the intermediate landing of stair 8. Justification: Found condition. Engineer missed location.
- 7. Add transformer for kitchen dishwasher. Justification: Found condition.
- 8. Replace auditorium stage curtain borders with new panels. Justification: Found condition. Old curtains fell apart when removed, needed replaced.
- 9. Add an additional data drop outlet to the new kitchen office. Justification: Found condition.

## BOARD OF EDUCATION MEETING SEPTEMBER 22, 2014

Roof Replacement @ F	ern Creek THS	Change Order # 01			
Original Contract Previous Approved		Current Change Order Total Contract Amount		Total Project Cost to	
Amount	Change Order Amount	Amount	to Date	Date	
398,860.00	0.00	3,912.00	402,772.00	385,259.12	

- 1. Replace 158 square feet of deteriorated cement bound wood fiber decking. Justification: Found condition.
- 2. Remove the existing SBS modified flashing and termination bar from the stone cap, then complete the fabrication and installation of a new 24 gauge Kynar finish painted steel radius cap flashing, set on a continuous cleat. Justification: Found condition.