# KNIGHT'S MECHANICAL

4250 LEITCHFIELD RD. CECILIA, KY 42724 PH (270)-765-4141 FAX (270) - 862-3374

## **PROPOSAL**

HARDIN CO SCHOOL BOARD

WA JENKINS RD. 3/18/15

ELIZABETHTOWN, KY 42701

RE: NORTH HARDIN, NORTH PARK AND JAMES T ALTON COIL

REPLACEMENT

ATTN BRANDON CECIL

WE PROPOSE TO FURNISH ALL LABOR, MATERIALS AND EQUIPMENT FOR THE FOLLOWING.

1. REMOVE EXISTING COILS AT THRRE SCHOOLS AND REPLACE WITH NEW COILS RECONNECT ALL PIPING AND REPAIR INSULATION

PREVAILING WAGE RATES NOT INCLUDED

FIVE WEEK LEAD TIME ON COILS WHICH PUSHES OUT THE SPRING BREAK SCHEDULE

MATERIAL COST \$ 121.791.00 LABOR COST \$ 51.510.00

KNights - 173,301

THANK YOU DARREL MORGAN

Any attention or deviation from above specifications invo an extra charge over and above the estimate. All agreement	obving extra costs will be executed only upon written orders, and will become ents contingent upon strikes, accidents, or delays beyond our control. Owner workers are fully covered by Workers' Compensation Insurance.
Authorized Signature:	Note: This proposal may be withdrawn by us if not accepted within 30 days.
ACCEPTANCE OF PROPOSAL — The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined. Date of Acceptance:	

Signature \_\_\_\_\_ Signature





820 S. Dixie Hwy., Muldraugh, KY 40155 Tel (502) 942-6966 Fax (502) 942-6964

March 20, 2015

Shrout, Tate, Wilson
628 Winchester Road
Lexinton, Ky 40505
Re: James T. Alton School
Fluid Cooler Coil Replacement Scope of Work
Attention Mr. Brandon Cecil

The Lusk Group proposes to furnish and all tools, labor, material and supervision to Remove and replace (2) 10 row, 8x12 heat transfer coils for the above Project

#### Not included are the following:

Overtime: Wages are based on normal working hours. Painting Chemical Treatment Test and Balance

Total Cost \$ 95,176.00

Please advise if additional information is required. Sincerely

Steve Robinson

Estimator/ Project Manager

Stew Rolum

The Lusk Group

Lusk



## The Lusk Group

820 S. Dixie Hwy., Muldraugh, KY 40155 Tel (502) 942-6966 Fax (502) 942-6964

March 20, 2015

Shrout, Tate, Wilson 628 Winchester Road Lexinton, Ky 40505

Re: North Hardin High School

Recold Coil Assembly Replacement Scope of Work

Attention Mr. Brandon Cecil

The Lusk Group proposes to furnish and all tools, labor, material and supervision to Remove and replace (1) Recold replacement coil assembly for the above Project

#### Not included are the following:

Overtime: Wages are based on normal working hours. Painting Chemical Treatment Test and Balance

Total Cost \$ 71,200.00

Please advise if additional information is required. Sincerely

Steve Robinson

Estimator/ Project Manager

Stery Roberson

The Lusk Group



## The Lusk Group

820 S. Dixie Hwy., Muldraugh, KY 40155 Tel (502) 942-6966 Fax (502) 942-6964

March 20, 2015

Shrout, Tate, Wilson 628 Winchester Road Lexinton, Ky 40505

Re: North Park Elementary School

Recold Coil Assembly Replacement Scope of Work

Attention Mr. Brandon Cecil

The Lusk Group proposes to furnish and all tools, labor, material and supervision to Remove and replace (1) Recold replacement coil assembly for the above Project

#### Not included are the following:

Overtime: Wages are based on normal working hours. Painting
Chemical Treatment
Test and Balance

Total Cost \$ 79,000.00

Please advise if additional information is required. Sincerely

Steve Robinson

Estimator/ Project Manager

Stew Rolumo

The Lusk Group



Brandon Cecil <br/>
<br/>
brandon.cecil@stweng.com>

## Cooling Tower Repairs @ 3 Locations

1 message

GBMC, Inc <gbmcinc82@aol.com>
To: brandon.cecil@stweng.com

Thu, Mar 19, 2015 at 10:14 AM

Brandon,

Our price to replace the three (3) cooler bundles is below:

\$251,187.00 (Labor - \$108,887 & Material - \$142,300.00 \*Breakdown for Accounting purposes only)

Thanks C. Gibson

CAMC - \$251,187