



Bullitt County Public Schools

1040 Highway 44 East
Shepherdsville, Kentucky 40165

502-869-8000
Fax 502-543-3608
www.bullittschools.org

MEMO

TO: Keith Davis

FROM: Mark Mitchell 

DATE: June 6, 2018

RE: Agenda Item for June 18, 2018 Board Meeting
Request to Renovate Old Mill Playground by Old Mill PTO

Old Mill Elementary School is requesting permission to allow their PTO to renovate their playground equipment. The PTO is recommending to follow Ms. Birge's recommendations as described in the proposals from Bluegrass Recreation and Dirt Work of Kentucky totaling \$7,206.68.

Much of the equipment is planned to be removed, as it is not salvageable. The swing set can be repaired cost efficiently, along with the stepping pods and one platform along with the multiple slides that can be removed and then reattached to the sides of the platform. The remaining pieces will be removed.


In addition, Ms. Birge recommends replacing the playground timbers and installing 92 cubic yards of playground grade mulch to meet state regulations. As PTO funds grow, the PTO has the intention to add on more pieces of equipment. We realize that this will take several years to complete. When the new Old Mill Elementary School is built, the plan is to move the renovated playground to the new Old Mill site. There will be no cost to the Board of Education.

I recommend the Board approve this request.

Attachments: Memo from Les McIntosh
Quotations for work




Old Mill Academy



11540 Highway 44 East, Mt. Washington, KY 40047
Les McIntosh, Principal - Kim Bleemel, Counselor
<http://ww2.bullittschools.org/OldMillEL>

502-869-3200
502-538-6641 (fax)
@OldMilKY

TO: Mark Mitchell
BCPS Director of Facilities

FROM: Les McIntosh, Principal *Les McIntosh*
Old Mill Elementary School

RE: Request to Renovate Old Mill Playground by Old Mill PTO

DATE: June 5, 2018

Old Mill Elementary School and Old Mill PTO became concerned about our playground equipment after numerous issues with and repairs of the equipment. Jennifer Birge of Bluegrass Recreation was contacted by the Old Mill PTO to do an inspection and recommend next steps. The assessment showed that much of the set-up has major structural weaknesses in the metal and plastic due to age and weathering.

The estimate to completely replace the equipment with code approved equipment is \$60,000 plus which the PTO cannot afford without much more fundraising. At this time, the PTO is recommending to follow Ms. Birge's recommendations as described in the proposals from Bluegrass Recreation and Dirt Work of Kentucky totaling \$7,206.68. Much of the equipment is planned to be removed as it is not salvageable. The swing set can be repaired cost efficiently, along with the stepping pods and one platform along with the multiple slides that can be removed and then reattached to the sides of the platform. The remaining pieces will be removed. In addition, Ms. Birge recommends replacing the playground timbers and installing 92 cubic yards of playground grade mulch to meet state regulations.

As PTO funds grow, the PTO has the intention to add on more pieces of equipment. We realize that this will take several years to complete. When the new Old Mill Elementary School is built, the plan is to move the renovated playground to the new Old Mill site.

There will be no cost to the Board of Education.

Thank you for your consideration in this matter. Please contact me if you have any questions.

**Mission: At Old Mill Academy, we are a community of learners.
We recognize, honor, and celebrate the leaders within us!**

Equal Education and Employment Institution

OK

Proposal



Prepared by:
Bluegrass Recreation Sales
and Installation, LLC
434 Quirks Run Rd
Danville KY 40422
PH: 800-257-5993
FX: 502-585-5265

Date:

May 31, 2018

Proposal number:

053118-3

This proposal is valid for 30 days

Proposal prepared for:

Old Mill Elementary
11540 KY-44
Mt Washington KY 40047
PH: 502-869-3200

Terms:

net 30

Products and Services:	Unit Price:	Qty.:	Ext. Price:
SH-23 Galvanized Ductile Swing Hanger with Clevis Pendulum, 2-3/8" OD Top Rail	\$15.75	10	\$157.50
SH-40 Single Clevis	\$2.84	10	\$28.40
H-40 Galvanized Swing Chain, Priced per Foot	\$1.64	64	\$104.96
SH-41 Clevis Key	\$1.06	1	\$1.06
3% Material Surcharge (due to the rising costs in steel, the manufacturer has implemented a material surcharge)	\$8.76	1	\$8.76
92 Cubic Yards of Hardwood Playground Mulch, Delivered	\$2,440.00	1	\$2,440.00
Installation and Timbers not included			
Freight	\$30.00	1	\$30.00
Total:			\$2,770.68

Notes:

Payment is due within 30 days after receipt of product. Past due amounts will incur finance charges.

Customer

Acceptance: _____

Date: _____

Representative Signature: Jennifer Birge

Installation charges assume no rock that cannot be reasonably removed with common hand tools. If heavy rock is encountered, additional

OK
na

Dirt Work of Kentucky

136 Myrtle Court * Taylorsville, KY 40071
502.649.1491

PROPOSAL

May 31, 2018

Proposal # 180531 -1

Old Mill Elementary School
11540 KY-44
Mt Washington, KY 40047

Project: Playground Repairs

Scope of Work

Removing of unsafe equipment, relocating existing slides and deck, and
replacing swing hardware: \$1,600.00.

Provide and install (42) 12" tall playground timbers (borders) and install (92)
cubic yards of wood mulch (provided by others) at existing swing area and
reduced play area at play structure: \$2,836.00

Notes:

- *relocating of existing play components is intended to be a short term temporary
Solution, full replacement is recommended
- *swing parts and mulch are not included
- *this includes for disposal of existing equipment and concrete footers
- *existing footer holes will be filled

Payment: payment due upon completion of the installation

Authorization to Proceed
(Customer signature here)

Date

OK
m