

Surplus Item

Bus #206

2006 International

Vin#WAAR16A176385

78 passenger bus

Rear Engine Bus

Has a cylinder sleeve leaking antifreeze into crankcase. Could be cracked sleeve but most likely sleeve O ring.