PCA ARCHITECTURE

## FIELD OBSERVATION REPORT

### 2019-06 (Scott HS)

ТО:	1055 Ft. V	on County Board of Education 5 Eaton Drive /right, KY 41017	DATE:		2019.06.17
ATTENTIO	N: Mr. F	Rob Haney			
FROM:	Mark	Perry	PROJECT:		Kenton County School District
	mpe	rry@pca-arch.com			Scott High School – Phase IV
	1881	Dixie Highway, Suite 130			
	Fort	Wright, KY 41011			
	V: 85	59.431.8612 • F: 859.431.8611			
COPIES TO	0: Mr. [	David Lloyd, Mr. Danny Mann,	PROJECT NO .:		2016-124
	Ms.	Carrie Hooten			
WE TRANSMIT THE ATTACHED ITEMS VIA: EMAIL					
PURPOSE		For your use	DISPOSITION		No exceptions noted
		As requested			Exceptions noted,
		For review and comment			Revise as indicated.
		For information			REJECTED:
	$\boxtimes$	For record			REVISE AND RESUBMIT
		For approval			
COPIES	DATE	DESCRIPTION			PAGES
1	2019-06	Field Observation Report			5

#### **Division 01: General Requirements**

01.01: 2019.06.05 – Owner's contractor had installed acoustical wall and ceiling panels in the band room. 01.02: 2019.06.05 – Owner's contractor had installed field turf in the courtyard.

01.03: 2019.06.10 – The design team ran partial upper level interior punch lists.

01.04: 2019.06.14 – The design team ran punch lists at the balance of the upper level and portions of the lower level that were considered complete. Choral, Band, mechanical rooms, the band corridor and the tie-in corridors/rooms connecting to Phase 2B were not yet ready to be punched.

01.05: 2019.06.14 – The video wall had been installed in the Multi-Purpose room.

#### Division 05: Metals

05.01: 2019.06.05 – Decorative guard rail at the exterior stairs was being installed.

#### **Division 06: Woods and Plastics**

06.01: 2019.06.05 – Wood nosings and risers had been installed in the choral and multi-purpose rooms.

#### **Division 07: Thermal and Moisture Protection**

07.01: 2019.06.17 – The subcontractor was on-site installing missing composite metal panel sections.

#### **Division 08: Doors and Windows**

08.01: 2019.06.05 – The last storefront frame and door had been installed in the courtyard.

#### **Division 09: Finishes**

09.01: 2019.06.05 – The existing exterior guard rail was being prepped for prime and paint.

If enclosures are not as noted, please notify PCA ARCHITECTURE immediately. Scott HS FieldRpt-201906

PCA ARCHITECTURE

09.02: 2019.06.05 – Linoleum tile flooring was being installed in band practice rooms and the choral room. Carpet had been installed in lower level offices. 09.03: 2019.06.05 – Precast terrazzo treads and risers were being installed.

09.04: 2019.06.14 – Concrete countertops had been installed, though caulking remained to be performed.

#### **Division 10: Specialties**

10.01: 2019.06.14 – Roller shades had been installed. 10.02: 2019.06.14 – Operable partition installation appeared complete. 10.03: 2019.06.14 – Toilet accessory installation was complete except at work/collaboration rooms.

#### **Division 12: Furnishings**

12.01: 2019.06.14 – Shade sails had been installed at courtyard canopies.

#### **CONSTRUCTION PHOTOS**



2019.06.05 – Prepping guard rail for paint



2019.06.05 – Guard rail installation



2019.06.05 - Guard rail installation



2019.06.05 - Band room





2019.06.05 - Choral room



2019.06.05 - Courtyard





2019.06.05 - Special needs counseling



2019.06.05 - Corridor 2200.



2019.06.05 - Spider crane for installing terrazzo treads and risers





2019.06.14 - Concrete tops Corridor 2200



2019.06.14 - Concrete tops Corridor 2200B



2019.06.14 - Restroom 2201



2019.06.14 - Monumental stair



2019.06.14 - Multi-purpose room

# PCA ARCHITECTURE



Please acknowledge receipt of transmitted items.

Return transmitted items to PCA ARCHITECTURE PSC.

END