

**GARRARD COUNTY SCHOOLS CRITICAL FACT SHEET for the BOARD of
EDUCATION**

Item for Consideration: Kitchen Equipment Surplus

Board Meeting Date: Thursday, July 14, 2022

Action Requested: Review Action/Consent Action/Discussion

Item before the Board: Kitchen Equipment Surplus

Applicable Statute/Regulation: KRS 160.290, KRSW 160.335, KRS 45A.425, 702 KAR 004:090; 704 KAR 003:455, OAG 91-85; OAG 76-291, 34 CFR 80.32

Background:

Existing Policy: Board Policy 04.8, Board Procedure 04.8 AP.1

Summary of Issue: Request permission to sell outdated and non-functioning equipment for scrap metal. Details attached: **CDR** Convection Oven – Double Stack (1), 2 Burner Range Top (1), Hobart Mixer (1); **PLE** Convection Oven – Single Stack (1); **LES** Deep Fryer (1)

Budget Impact: Minimal increase from scrap metal check deposit to Fund 51

Groups Consulted and Brief Summary of Response: Mindy Morrow, Food Service Director, and Brad Abee, Maintenance Director, agree that the equipment is outdated, non-functioning, and should be sold for scrap.

Superintendent's Recommendation:

Contact Person(s): Mindy Morrow, Brad Abee

Superintendent of Garrard County Schools

Please underline the category best describing the item under consideration:

District Innovation	Strengthening Educators	Family/Community Involvement	Student/Family Supports
	Student Interventions	Coursework Completion	Accountability Reporting

Garrard Schools :
Food Service :

Scrap/Surplus

7-7-2022

CDK



→ Garrard Schools Fixed Asset No: 137135
Alto-Shaam Double-Stack Convection Oven
Serial: 1407638-000 Model: ASC-4E

Property Of Garrard
County School District



10159

Vulcan 2 Burner Range Top
Serial: 481111196 Model: VEX1

Property Of Garrard
County School District



10158

Hobart Mixer

Serial: 31-1080-943 Model: D300T

PLE

Property Of Garrard
County School District



10422

Market Forge Single Convection Oven
Equip No. 14632

Property Of Garrard
County School District



10078

LES

Hobart Deep Fryer

Serial: 07-018-278TK











County School District
10075

CAUTION
HOT SURFACES ARE
"HOT"

POWER

OVER TEMP

PROBE FAILED

HEATERS ON

225
160
140
120
100
80
60
40
20
0

CAUTION
IF THIS DEVICE IS NOT CONNECTED
TO A FOUR WIRE SUPPLY, TWO POWER
CIRCUITS MUST TO BE DISCONNECTED
BEFORE SERVICING THIS DEVICE

CAUTION
DISCONNECT SUPPLY
BEFORE CHANGING FUSE

HOBART
(800) 252-6668
In KY: 1-800-269-5081
EQUIPMENT - PARTS - SERVICE

HOBART