

July 29, 2022

Clearfield Elementary School Renovation & Addition BG 21-048 Change Order Request CO 095-02

To: Peter Fischer

From: Bob Rose

Re: Clearfield Elementary

Peter,

Please review and advise upon the recommendation to the Owner to consider or reject this proposal as outlined below and on accompanying information.

Provide and install Gypsum chase as indicated in PR8 Labor = \$900.00 Material = \$300.00

Total this change = Add \$1,200.00

East KY Drywall Inc

84 Industry Drive London, KY 40741 606-862-0202

CHANGE ORDER

No# 000460

то:	JOB SITE INFORMATION: Date 0	04/27/2022
Name Packs + Walker	Job Name Clearfield Elementary	
Address	Job Location Morehead Ky	
City, State and Zip Code Morehead Ky	Job Phone Number	
We hereby agree to the change(s) specified below:		
Material Labor and Clean up for th	ne following:	
Frame and Drywall Column per plan	Material Labor	300.00 900.00
2 men 8 hrs at \$45 per hour per man 1 men 4 hrs at \$45 per hour per man	Haboi	
Material 6 3 5/8 20g 16' \$162.00 2 3 5/8 20G track \$34.00 2 4X12x5/8 \$45.00 3 10' No coat \$14.00 3 Pail of drywall mud \$45.00		
	We agree to make the change(s) specified above at this price:	\$1,200.00
Contractor Signature	Previous contract amount:	
04/27/2022	, 101.020 03.11.001 0.1104110	
Date	Revised contract amount:	\$1,200.00
ACCEPTED - The above prices and specifications of this Change Order are satisfactory and are hereby accepted. All work is to be performed under the same terms and conditions as specified in the original contract, #		
Customer Signature	Date	



PROPOSAL REQUEST

DATE: April 12, 2022 PR #: 08

TO: Packs + Walker Construction Co. RE: Clearfield Elementary Renovations &

75 Baldridge Road Additions

Morehead, KY 40351 Rowan County, Kentucky

BG 21-048 RTA 2037

Please submit an itemized quotation for changes in the Contract Sum and/or Time incidental to proposed modifications to the Contract Documents described therein.

THIS IS NOT A CHANGE ORDER NOR A DIRECTION TO PROCEED WITH THE WORK DESCRIBED HEREIN.

DESCRIPTION:

Refer to sheets A1.1, 2.0, 2.1, A7.1, E3.1, & E4.1 and revise Media 122 as described below and shown on the attached sketch.

Due to an unforeseen condition, provide a detailed pricing breakdown for all labor, material, and equipment costs associated with the following scope:

- 1. Provide a 1-sided gypsum chase to conceal the wall depth discrepancy within Media 122. Gypsum chase shall align with gypsum wrapped columns. Chase shall extend from floor to terminate into gyp ceiling.
- 2. Provide two additional "C" corner guard items from the Equipment List on A2.0
- 3. Install gyp ceiling and resilient base around new wall.

Provide at no additional cost the following scope:

- 1. Modify the width of the two "G" shelves as shown on D/PR8.0.
- 2. Re-locate computer desks (Item "M") on either side of new gyp chase as shown on D/PR8.0.
- 3. Re-locate receptacle shown on E3.1 and E4.1 to be plan east of the proposed gyp chase. Coordinate surface mounted conduit, intent is to use chase to conceal.

This is not a change order nor a direction to proceed with the work described herein.

ATTACHMENTS:

PR 8.0

BY: Jonathan Ruiz AIA, LEED Green Associate, NoMA

c: Peter Fisher – RTA
Katie Cervenec – RTA
Katie Mitchell – RTA

Melinda Robrahn - CMTA File 2037-4b1 PR-08-2037