FACPAC Contract Change Order Supplemental Information Form (Ref# 57711)

Form Status: Saved

Tier 1 Project: Estill Springs ElementaryPhase 2 Renovations & Addition - ESSER IIIBG Number: 22-207District: Estill County (HB678)Status: ActivePhase: Project Initiation (View Checklist)

Contract: Central Kentucky Sheet Metal, Inc, 0011, Plumbing/Mechanical Type: CM Bid Package Proposed

Change Order Number	11-1
Time Extension Required	No
Date Of Change Order	3/24/2023
Change Order Amount To Date	Unchanged

Construction Contingency

Calculations below are project wide. Remaining negative Construction Contingency may require the submission of a revised BG1.

Current Approved Amount\$138,450.00Net Approved COs\$53,717.17Remaining After Approved COs\$84,732.83Net All COs\$192,237.90Remaining After All COs\$-53,787.90This Requested Change Order Amount\$19,773.00+/Change In A/E Fee This Change Order \$1,087.52+/Change In CM Fee This Change Order \$395.46+/Contract Change Requested ByArchitect/EngineerContract Change Requested ByArchitect/EngineerContract Change Reason CodeFound ConditionChange Order Description And JustificationPR #7 - Replace existing grease trap with a new grease trap.Cost Benefit To OwnerImproved conditionContract unit prices have been utilized No to support the cost associated with this change order.No to support the cost associated with this change order.			
Remaining After Approved COs \$84,732.83 Net All COs \$192,237.90 Remaining After All COs \$-53,787.90 This Requested Change Order Amount \$19,773.00 +/- Change In A/E Fee This Change Order \$1,087.52 +/- Change In CM Fee This Change Order \$395.46 +/- Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Reason Code Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No to support the cost associated with this change order. No	Current Approved Amount	\$138,450.00	
Net All COs \$192,237.90 Remaining After All COs \$-53,787.90 This Requested Change Order Amount \$19,773.00 +/- Change In A/E Fee This Change Order \$1,087.52 +/- Change In CM Fee This Change Order \$395.46 +/- Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Requested By Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No to support the cost associated with this change order. No	Net Approved COs	\$53,717.17	
Remaining After All COs\$-53,787.90This Requested Change Order Amount \$19,773.00+/-Change In A/E Fee This Change Order \$1,087.52+/-Change In CM Fee This Change Order \$395.46+/-Remaining Construction ContingencyBalanceContract Change Requested ByArchitect/EngineerContract Change Reason CodeFound ConditionChange Order Description And JustificationPR #7 - Replace existing grease trap with a new grease trap.Cost Benefit To OwnerImproved conditionContract unit prices have been utilized Noto support the cost associated with thischange order.	Remaining After Approved COs	\$84,732.83	
This Requested Change Order Amount \$19,773.00 +/- Change In A/E Fee This Change Order \$1,087.52 +/- Change In CM Fee This Change Order \$395.46 +/- Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Reason Code Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No to support the cost associated with this change order.	Net All COs	\$192,237.90	
 +/- Change In A/E Fee This Change Order \$1,087.52 +/- Change In CM Fee This Change Order \$395.46 +/- Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Reason Code Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No to support the cost associated with this change order. 	Remaining After All COs	\$-53,787.90	
 +/- Change In CM Fee This Change Order \$395.46 +/- Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Reason Code Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No to support the cost associated with this change order. 	1 0	\$19,773.00	
 k/- Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Reason Code Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No o support the cost associated with this change order. 		\$1,087.52	
Remaining Construction Contingency Balance Contract Change Requested By Architect/Engineer Contract Change Reason Code Found Condition Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner Improved condition Contract unit prices have been utilized No o support the cost associated with this change order.	•	\$395.46	
Contract Change Requested By Contract Change Reason CodeArchitect/Engineer Found ConditionChange Order Description And JustificationFound ConditionPR #7 - Replace existing grease trap with a new grease trap.Cost Benefit To Owner mproved conditionContract unit prices have been utilized o support the cost associated with this whange order.No	Remaining Construction Contingency		
Change Order Description And Justification PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner mproved condition Contract unit prices have been utilized No o support the cost associated with this hange order.	Contract Change Requested By	e	
PR #7 - Replace existing grease trap with a new grease trap. Cost Benefit To Owner improved condition Contract unit prices have been utilized No o support the cost associated with this change order.	6		
Improved condition Contract unit prices have been utilized No o support the cost associated with this change order.	•		
Contract unit prices have been utilized No o support the cost associated with this hange order.			
o support the cost associated with this change order.	mproved condition		
ut:blank	o support the cost associated with this	No	
	out:blank		

Detailed Cost Breakdown

Contract unit prices have not been utilized, provide a detailed cost breakdown which separates labor, material, profit and overhead.

Detail Item	Amount	Percent of Total
Labor	\$9,000.00	45.52%
Materials	\$8,975.50	45.39%
Profit and Overhead	\$1,797.50	9.09%
Bond Insurance		0.00%
Cost Breakdown Total:	\$19,773.00	
Cost for this Change Order supported No		
by an alternate bid or competitive price		
quote		
Explain Why		

Change Order Supplemental Info Page (Online Form Ref# 57711)	rmation Form Signature
Peter M. Disk	3/27/2023
Architect	Date
K.D.	3/29/2023
Construction Manager	Date
Finance Officer	Date
Local Board of Education Designee	Date

\mathbf{WAIA}° Document G701/CMa^{$\circ}$ – 1992</sup>

Change Order - Construction Manager-Adviser Edition

OWNER 🖂 CONSTRUCTION MANAGER ARCHITECT CONTRACTOR FIELD OTHER

PROJECT (Name and Address) ESTILL SPRINGS ELEMENTARY SCHOOL **314 MAIN STREET** IRVINE, KY 40336

CHANGE ORDER NUMBER: 11-01 **INITIATION DATE: 3/27/2023**

TO CONTRACTOR (Name and Address) CENTRAL KENTUCKY SHEET METAL, INC

PROJECT NUMBERS: 000778 CONTRACT DATE: 8/15/2022 CONTRACT FOR: BID PACKAGE #11 PLUMBING/MECHANICAL

THE CONTRACT IS CHANGED AS FOLLOWS: PR #7 - Replace existing grease trap with a new grease trap

The original Contract Sum was	429,800.00
Net change by previously authorized Change Orders	0.00
The Contract Sum prior to this Change Order was	429,800.00
The Contract Sum will be Increased by this Change Order in the amount of	19,773.00
The new Contract Sum including this Change Order will be	449,573.00

The Contract Time will be adjusted by 0 days. The date of Substantial Completion as of the date of this Change Order therefore is 6/2/2023.

NOT VALID UNTIL SIGNED BY THE CONSTRUCTION MANAGER, ARCHITECT, CONTRACTOR AND OWNER.

CODELL CONSTRUCTION COMPANY	ROSS-TARRANT ARCHITECTS INC.
CONSTRUCTION MANAGER (Firm Name) 4475 ROCKWELL ROAD WINCHESTER, KY 40391	ARCHITECT (Firm Name) 101 OLD LAFAYETTE AVE LEXINGTON, KY 40502
ADDRESS KOni	ADDRESS Peter A. Dian
BY (Signature)	BY (Signature)
Kenny Davis 3/29/2023	Peter G Fisher
(Typed Name) DATE:	(Typed Name) DATE: 3/27/2023
CENTRAL KENTUCKY SHEET METAL, INC	ESTILL COUNTY BOARD OF EDUCATION
CONTRACTOR (Firm Name) 2672 Carters ile Rol. Parit Lick Ky	OWNER (Firm Name) 253 MAIN STREET IRVINE, KY 40336
ADDRESS Paul & jogs 40461	ADDRESS
BY (Signature)	BY (Signature)
<u>Pan) Sipes</u> 3-27-2023 (Typed Name) DATE:	(Typed Name) DATE:

AIA Document G701/CMaTM - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved, WARNING: This AIA[®] Document is protected by U.S. Copyright Law and International Treaties. Unauthorized reproduction or distribution of this AIA® Document, or any portion of it, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under the law.

(1884033357)



CC: Kenny Davis

PROPOSAL REQUEST PR #7

Date: 11/23/2022
314 Main Street Irvine, KY 40336
•

To: ROSS-TARRANT ARCHITECTS INC.

Attn:

I have reviewed and approved the attachment pricing. Your approval and signature is required in order to process this change order. Please review the pricing and sign below it it is acceptable.

Description	BP	Amount
BABCON, INC.	012	0.00
BASTIN PAINTING, INC.	006	0.00
BROWN SPRINKLER CORPORATION	010	0.00
CDI FLOORING	007	0.00
CENTRAL KENTUCKY SHEET METAL, INC	100	19,773.00
EAST KENTUCKY MASONRY	003	0.00
ELLIOTT CONTRACTING, INC.	005	0.00
RISING SUN DEVELOPING, INC.	002	0.00
SOUTHEASTERN STAFFING, LLC	004	0.00
STANDAFER BUILDERS, INC.	001	0.00

Summary

Total Days 0.00 Total

19,773.00

ROSS-TARRANT ARCHITECTS INC.		
Signature	DATE:	

Codell Construction Company casey cullen 314 Main Street Irvine, KY 40336 ccullen@codellconstruction.com

Estill Springs Elementary PROPOSAL REQUEST PRICING SHEET

	PCO #		7			DATE	12/2/2022
DESCRIPTION	I replace exis	sting greas	se trap with	n new 1500) gallor	n per PR07	
CONTRACTOR	Central Ky.	Sheetmet	al		BID) PACKAGE	
WORK DESCRIPTION	I replace exis	sting greas	se trap with	n new 1500) gallor	n per PR07	
A. UNIT PRICING FROM THE	PROPOSAL	FORM					
1. UNIT PRICING		QTY.		U.P.			TOTAL COST
		QTY.		U.P.			TOTAL COST
		QTY.		U.P.			TOTAL COST
B. MATERIAL 1. Grease trap 1500 gal 2. pipe and fittings 3. gravel 4. 5. 6. LABOR 1. grease trap 48 2. piping 24 3. excavation and backfill 48	_HOURS @	1 lot 25 ton	<u>1</u> QTY. QTY. QTY. QTY. QTY. QTY.	MATERIA 75 75 75	27 L Savi \$/HR \$/HR \$/HR	UNIT UNIT UNIT UNIT ngs TOTAL \$3,600.00 \$1,800 \$3,600	
<u>Excavator</u> , Skidsteer and	I dump truck				LAE	SOR TOTAL	<u>\$9,000.00</u> <u>850</u>
MATERIAL, LABOR & EQUII	PMENT SUB	TOTAL				\$17,975	
10% OVERHEAD/PROFIT M	ARK-UP					1797.5	
DEDUCT DPO (DIRECT PUI	RCHASE OR	DER) MAT	FERIAL	\$			
TOTAL -ADD						\$19.773	



RossTarrant Architects | 101 Old Lafayette Ave Lexington KY 40502 United States

PROJECT:	Estill Springs ES Phase 2 Ren/Add 2148	DATE SENT:	12/15/2022
SUBJECT:	COP for PR 07 Sanitary sewer tie- in @ grease trap	CHANGE ORDER PROPOSAL ID:	COP for PR 07
TYPE:	Change Order Proposal	TRANSMITTAL ID:	00341
PURPOSE:	Reviewed	VIA:	Info Exchange
TOTAL AMOUNT:	\$26,992.00		
TOTAL DAYS:	0		

FROM

NAME	COMPANY	EMAIL	PHONE
Jonathan Ruiz	RossTarrant Architects	jruiz@rosstarrant.com	859-254-4018

ТО

NAME	COMPANY	EMAIL	PHONE
Casey Cullen		ccullen@codellconstructi on.com	

REMARKS: These two prices have been reviewed and appear acceptable for District consideration. NOTE: Only proceed with selection one or the other, not adding to get \$26k. District has the option to either rework the piping and keep the existing make-shift grease trap for the \$7k or provide a new grease trap for \$19k.

DESCRIPTION OF CONTENTS


QTY	DATED	TITLE	NUMBER	SCALE	SIZE	NOTES
1	12/12/2022	Potential Change Order 007 - PR #7 Sanitary Sewer tie-in @ Grease trap.pdf				
1	12/15/2022	COP for PR 07 - Grease Trap - KFI Review.pdf				

Change Order Proposal Transmittal 12/15/2022 DATE: 00341 ID:

COPIES:

Kenny Davis Peter Fisher

(Codell Construction Company) (RossTarrant Architects)



Option 1: Raise 4" sanitary main from grease trap and single restroom into existing bldg to provide proper drainage and allow for new classroom tie-in.


Field coordinate final inverts with existing bldg


Provide length of pipe required for pricing.

Option 2: Replace existing grease trap with new 1500 gal cast concrete grease trap as required per local utility and provide new 4" sanitary main from grease trap and single restroom into existing bldg to provide proper drainage and allow for new classroom tie-in.

Field coordinate final inverts with existing bldg

Provide length of pipe required for pricing.





Option 1: Raise 4" sanitary main from grease trap and single restroom into existing bldg to provide proper drainage and allow for new classroom tie-in.

Field coordinate final inverts with existing bldg

Provide length of pipe required for pricing.

Option 2: Replace existing grease trap with new 1500 gal cast concrete grease trap as required per local utility and provide new 4" sanitary main from grease trap and single restroom into existing bldg to provide proper drainage and allow for new classroom tie-in.

Field coordinate final inverts with existing bldg

Provide length of pipe required for pricing.

