Wehr Constructors Inc - Louisville OFFICE AND YARD 2517 Plantside Dr Louisville, KY 40299



PHONE: 502-491-9250 FAX: 502-493-8653

Date: 9/4/2024

CHANGE ORDER REQUEST

Date:	9/4/2024	Project Name:	West Ha	ardin Middle School	
To:	Hardin County Board of Education 65 W A Jenkins Road Elizabethtown, KY 42701		Early Sitework		
		Architect Project	No.	202280	
Attn:	John Stith	Wehr Project No		24-043	

DESCRIPTION OF CHANGE: PR 1 – Unsuitable Soils at Access Road

Re: Wehr Request No. CO 1

For the above change, we would add the amount of **\$23,513** to the contract.

Days schedule delayed: _____15*

Item	Subcontractor	Subtotal
1	Dirtworks Unlimited	\$23,115
2	Construction Manager Fee	\$398

Grand Total \$23,513

WEHR CONSTRUCTORS, INC.

By _

Justin Van Zile, Project Manager

We have reviewed the above Change	e Order Request and it is \Box Approved; \Box	Rejected; 🗖 to be Revised & Resubmitted.
Architect's Signature	Company Name	Date
We have reviewed the above Change	e Order Request and it is D Approved; D	Rejected; 🗖 to be Revised & Resubmitted.
Owner's Signature	Company Name	Date

*Based on getting approved at 9/5 Board meeting. If not, this will require adjustment to reflect accurate timeline.



Dirt Works Unlimited, LLC

September 3, 2024

- Attn: Justin VanZile Wehr Constructors 2517 Plantside Drive Louisville, KY 40299
- RE: West Hardin Middle School Early Sitework Package 931 E Main St Cecilia, Kentucky 42724 PR 001 Unsuitable Soils

Pricing is based on Proposal Request 001 dated August 28th.

Undercut Areas B and D additional 6" and replace with #3 stone Undercut Areas C additional 12" and replace with #3 stone

Area B (22x200x.5) 82 CY 138 TN Area D (22x115x.5) 47 CY 79 TN

Area C (22x180x1) 146 CY 247 TN

Description of Work	QTY	Unit	Unit Rate	Line Total
Mass Earth Excavation disposed off-site	275	CY	\$ 25.00	\$ 6,875.00
#3 Stone Import	464	TN	\$ 35.00	\$ 16,240.00
			Total	\$ 23,115.00

Should you have any questions with regards to this proposal please don't hesitate to contact me.

Regards,

Aaron Gatlin

Aaron Gatlin Project Manager 270-506-9053 Cell agatlin@dirtworksunlimited.com

AIA Document G709[°] – 2018

Proposal Request

PROJECT: (name and address) West Hardin Middle School Leitchfield Road Cecilia, KY 42724

CONTRACT INFORMATION: Contract For: General Construction Date: 8-22-24

OWNER: (name and address) Hardin County Board of Education 65 W. A. Jenkins Road Elizabethtown, KY 42701

ARCHITECT: (name and address) JRA Architects 301 E. Vine Street Lexington, KY 40507

Architect's Project Number: 202280 Proposal Request Number: 001 Proposal Request Date: 8-28-24

CONTRACTOR: (name and address) Wehr Constructors, Inc. 2517 Plantside Drive Louisville, KY 40299

The Owner requests an itemized proposal for changes to the Contract Sum and Contract Time for proposed modifications to the Contract Documents described herein. The Contractor shall submit this proposal within Zero (0) days or notify the Architect in writing of the anticipated date of submission.

(Insert a detailed description of the proposed modifications to the Contract Documents and, if applicable, attach or reference specific exhibits.)

On site Solid Ground Consulting Engineering, identified 6 distinct areas where unsuitable soils were encountered within 1 foot plus or minus of subgrade elevations. The plans call for a layer of geogrid and 8 inches of #3 stone below the pavement section.

The access drive is a heavy-duty asphalt pavement section, (10:3:2). So that we maintain the full depth heavy-duty asphalt pavement section:

The contractor needs to undercut the cut areas located in Areas A, E, & F, 8-inches below proposed subgrade. This is to allow for the geo-grid and 8-inches of No. 3 stone in the early bid package and to maintain the full depth heavy-duty asphalt pavement section.

The contractor needs to undercut the cut areas located in Areas B & D, 14-inches below proposed subgrade, additional 6inches, (per Solid Grounds's recommendation), and original 8-inches, (per early bid package). The contractor is then to install the geo-grid and 14-inches of No. 3. stone.

The contractor needs to undercut the cut areas located in Area C, 20-inches below proposed subgrade, additional 12-inches, (per Solid Ground's recommendation), and original 8-inches, (per early bid package). The contractor is then to install the geogrid and 20-inhes of No. 3 stone.

THIS IS NOT A CHANGE ORDER, A CONSTRUCTION CHANGE DIRECTIVE, OR A DIRECTION TO PROCEED WITH THE WORK DESCRIBED IN THE PROPOSED MODIFICATIONS.

REQUESTED BY THE ARCHITECT:

D. Robert Deal, AIA, President PRINTED NAME AND TITLE

AIA Document G709 - 2018. Copyright @ 1993, 2001 and 2018. All rights reserved. "The American Institute of Architects," "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are trademarks of The American Institute of Architects. This document was produced at 14:24:53 ET on 08/28/2024 under Order No.2114505082 which expires on 02/15/2025, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail docinfo@aiacontracts.com. User Notes: (3B9ADA4E)



Company:Solid Ground Consulting EngineersEmail:Contact:Shane SmithTitle:Phone:502-338-4173Create

Email:Shanesmith@solidgroundce.comNo. Items: 3Title:West Hardin M.S. 24/08/23 S.V.Created:Fri, 8/23/2024



Summary:

Created: Fri, 8/23/2024

Solid Ground rep was on site today to observe soft soils on the south road entrance, estimated dimensions of unsuitable material listed below.

Section A: 22'x220'x2': 350 cu. yd. Section B: 22'x200'x2.5': 407 cu. yd. Section C: 22'x180'x4': 587 cu. yd. Section D: 22'x115'x2.5': 235 cu. yd. Section E: 22'x175'x1.5': 214 cu. yd. Section F: 22'x180'x2': 367 cu. yd.

(2)

Discrepancy Log

West Hardin Middle School

	Discrepancy	Corrective Action
DISCREPANCY (1) DATE:24/08/23	South road entrance observed with soft and unsuitable material.	Date Resolved:
DISCREPANCY (2) DATE:	N/A	Date Resolved:
DISCREPANCY (3) DATE:	N/A	Date Resolved:
DISCREPANCY (4) d: Mon, 8/26/2024 bancy log.		1.5.1.





Company:Solid Ground Consulting EngineersEmailContact:Shane SmithTitle:Phone:502-338-4173Creat

Email:Shanesmith@solidgroundce.comNo. Items: 3Title:West Hardin M.S. 24/08/23 S.V.Created:Fri, 8/23/2024



Remarks: Created:

Sun, 8/25/2024

Probe rod testing showed material to be soft and unsuitable.

Solid Ground rep will return for more testing and observations, as scheduled weather permitting.