

Site Visit - Construction Observation

PROJECT:	5056-01 Trans District Sup Fac 5056-01	DATE:	1/15/2025
VISIT NAME:	Construction Progress Site Visit	REPORT NO:	031
AUTHOR:	David Vaught	STATUS:	Final


VISIT DETAILS

WEATHER:	Mostly Cloudy High in the upper 20's	START TIME:	11:30 AM
		END TIME:	2:00 PM

GENERAL COMMENTS: A construction progress site visit was conducted on January 15, 2025. The following items were noted.


PARTICIPANT NAME	COMPANY	TITLE	EMAIL
David Vaught	GRW	Project Manager	DVaught@grwinc.com


OBSERVATIONS

ITEM	REMARKS	DISCUSSION	PHOTO
031-001	Roll Over Vehicle Washer installation in progress. Remove stains from concrete floor slab. Install joint sealant perimeter of curtain wall framing and CMU.		
	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT: 1/15/25 at 11:55 AM
	CATEGORY:	Roll Over Vehicle Washer	REFERENCE: 115000

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-002	Roll Over Vehicle Washer installation in progress. Remove stains from concrete floor slab. Sectional door installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 1/15/25 at 11:55 AM	
	CATEGORY: Roll Over Vehicle Washer	REFERENCE: 115000	

ITEM	REMARKS	DISCUSSION	PHOTO
031-003	Roll Over Vehicle Washer installation in progress. Remove stains from concrete floor slab. Sectional door installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 1/15/25 at 11:55 AM	
	CATEGORY: Roll Over Vehicle Washer	REFERENCE: 115000	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-004	Roll Over Vehicle Washer installation in progress. Remove stains from concrete floor slab. Sectional door installation in progress.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 1/15/25 at 11:55 AM	
	CATEGORY: Roll Over Vehicle Washer	REFERENCE: 115000	

ITEM	REMARKS	DISCUSSION	PHOTO
031-005	Hollow metal door and frame installation in progress. Adjust hollow metal door and hardware for smooth operation. Paint hollow metal door frame.		
	SPACE: 143 - AUTOMATIC WASH BAY	SUBJECT: 1/15/25 at 11:57 AM	
	CATEGORY: Hollow Metal Door and Frame / Door Hardware	REFERENCE: 081113 / 087100	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-006	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	144 - STORAGE ROOM	SUBJECT: 1/15/25 at 11:58 AM
	CATEGORY:	Interior Painting	REFERENCE: 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-007	Hollow metal door and frame installation in progress. Adjust hollow metal door and hardware for smooth operation. Paint hollow metal door frame.		
	SPACE:	144 - STORAGE ROOM	SUBJECT: 1/15/25 at 11:58 AM
	CATEGORY:	Hollow Metal Door and Frame / Door Hardware	REFERENCE: 081113 / 087100

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-008	Roll Over Vehicle Washer installation in progress. Remove stains from concrete floor slab. Unit heater installation in progress		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 1/15/25 at 11:59 AM
	CATEGORY:	Roll Over Vehicle Washer / Unit Heaters	REFERENCE: 115000 / 238239

ITEM	REMARKS	DISCUSSION	PHOTO
031-009	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 1/15/25 at 11:59 AM
	CATEGORY:	Interior Painting	REFERENCE: 099123

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-010	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation. Unit heater installation in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 1/15/25 at 11:59 AM
	CATEGORY:	Overhead Coiling Doors / Unit Heaters	REFERENCE: 083323 / 238239

ITEM	REMARKS	DISCUSSION	PHOTO
031-011	Hollow metal door and frame installation in progress. Adjust hollow metal door and hardware for smooth operation. Paint hollow metal door frame.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 1/15/25 at 12:00 PM
	CATEGORY:	Hollow Metal Door and Frame / Door Hardware	REFERENCE: 081113 / 087100

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-012	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	146 - CIRCULATION	SUBJECT: 1/15/25 at 12:00 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-013	Interior painting in progress. Paint exposed conduit. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	146 - CIRCULATION	SUBJECT: 1/15/25 at 12:00 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-014	Interior painting in progress. Paint exposed conduit. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE: 149 - BATTERY STORAGE / CHARGING	SUBJECT: 1/15/25 at 12:01 PM	
	CATEGORY: Interior Painting	REFERENCE: 099123	

ITEM	REMARKS	DISCUSSION	PHOTO
031-015	Vehicle fluid storage tank installation in progress. Install storage tanks per sheet AE423. Provide space for owner provided DEF tote per sheet AE423.		
	SPACE: 147 - POL STORAGE ROOM	SUBJECT: 1/15/25 at 12:01 PM	
	CATEGORY: Vehicle Fluids Piping	REFERENCE: 231113	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-016	Air compressor and air dryer installation in progress. Air compressor and air dryer configuration is acceptable.		
	SPACE:	148 - AIR COMPRESSOR ROOM	SUBJECT: 1/15/25 at 12:02 PM
	CATEGORY:	Vehicle Fluids Piping	REFERENCE: 231113

ITEM	REMARKS	DISCUSSION	PHOTO
031-017	Vehicle fluid storage tank installation in progress. Install storage tanks per sheet AE423. Provide space for owner provided DEF tote per sheet AE423.		
	SPACE:	147 - POL STORAGE ROOM	SUBJECT: 1/15/25 at 12:02 PM
	CATEGORY:	Vehicle Fluids Piping	REFERENCE: 231113

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-018	Vehicle fluid storage tank installation in progress. Install storage tanks per sheet AE423. Provide space for owner provided DEF tote per sheet AE423.		
	SPACE:	147 - POL STORAGE ROOM	SUBJECT: 1/15/25 at 12:04 PM
	CATEGORY:	Vehicle Fluids Piping	REFERENCE: 231113

ITEM	REMARKS	DISCUSSION	PHOTO
031-019	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	145 - CIRCULATION	SUBJECT: 1/15/25 at 12:04 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-020	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Unit heater installation in progress.		
	SPACE: 145 - CIRCULATION	SUBJECT: 1/15/25 at 12:05 PM	
	CATEGORY: Interior Painting / Unit Heaters	REFERENCE: 099123 / 238239	

ITEM	REMARKS	DISCUSSION	PHOTO
031-021	Electrical installation in progress.		
	SPACE: 151 - ELECTRICAL CLOSET	SUBJECT: 1/15/25 at 12:05 PM	
	CATEGORY: Electrical	REFERENCE: 260000	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-022	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation. Unit heater installation in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE: 141 - PARTS / INVENTORY	SUBJECT: 1/15/25 at 12:11 PM	
	CATEGORY: Overhead Coiling Doors / Unit Heaters	REFERENCE: 083323 / 238239	

ITEM	REMARKS	DISCUSSION	PHOTO
031-023	Hollow metal door and frame installation in progress. Adjust hollow metal door and hardware for smooth operation. Paint hollow metal door frame.		
	SPACE: 141 - PARTS / INVENTORY	SUBJECT: 1/15/25 at 12:11 PM	
	CATEGORY: Hollow Metal Door and Frame / Door Hardware	REFERENCE: 081113 / 087100	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-024	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	153 - END OF BAY STORAGE	SUBJECT: 1/15/25 at 12:12 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-025	Hollow metal door and frame installation in progress. Adjust hollow metal door and hardware for smooth operation. Paint hollow metal door frame.		
	SPACE:	153 - END OF BAY STORAGE	SUBJECT: 1/15/25 at 12:12 PM
	CATEGORY:	Hollow Metal Door and Frame / Door Hardware	REFERENCE: 081113 / 087100

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-026	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	131 - CIRCULATION	SUBJECT: 1/15/25 at 12:13 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-027	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	138 - INSPECTION BAY 1	SUBJECT: 1/15/25 at 12:13 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-028	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	139 - INSPECTION BAY 2	SUBJECT: 1/15/25 at 12:14 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-029	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	139 - INSPECTION BAY 2	SUBJECT: 1/15/25 at 12:14 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-030	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	139 - INSPECTION BAY 2	SUBJECT: 1/15/25 at 12:14 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-031	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	137 - MAINTENANCE BAY 6	SUBJECT: 1/15/25 at 12:14 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-032	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE: 135 - MAINTENANCE BAY 4	SUBJECT: 1/15/25 at 12:15 PM	
	CATEGORY: Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523	

ITEM	REMARKS	DISCUSSION	PHOTO
031-033	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE: 133 - MAINTENANCE BAY 2	SUBJECT: 1/15/25 at 12:15 PM	
	CATEGORY: Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523	

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-034	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE: 132 - MAINTENANCE BAY 1	SUBJECT: 1/15/25 at 12:15 PM	
	CATEGORY: Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523	

ITEM	REMARKS	DISCUSSION	PHOTO
031-035	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE: 134 - MAINTENANCE BAY 3	SUBJECT: 1/15/25 at 12:15 PM	
	CATEGORY: Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS		DISCUSSION		PHOTO
031-036	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.				
	SPACE:	136 - MAINTENANCE BAY 5	SUBJECT:	1/15/25 at 12:16 PM	
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE:	083613 / 235523	

ITEM	REMARKS		DISCUSSION		PHOTO
031-037	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.				
	SPACE:	138 - INSPECTION BAY 1	SUBJECT:	1/15/25 at 12:16 PM	
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE:	083613 / 235523	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-038	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Radiant heater installation in progress.		
	SPACE:	138 - INSPECTION BAY 1	SUBJECT: 1/15/25 at 12:16 PM
	CATEGORY:	Interior Painting / Radiant Heaters	REFERENCE: 099123 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-039	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer. Vehicle fluids piping installation in progress.		
	SPACE:	139 - INSPECTION BAY 2	SUBJECT: 1/15/25 at 12:17 PM
	CATEGORY:	Interior Painting / Vehicle Fluids Piping	REFERENCE: 099123 / 231113


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-040	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Light cove ceiling and outer perimeter gypsum board to be painted SW 7620 Seaworthy. Prepare concrete floor for polished concrete finishing.				
	SPACE:	103 - CIRCULATION	SUBJECT:	1/15/25 at 12:20 PM	
	CATEGORY:	Gypsum Board / Interior Painting	REFERENCE:	092900 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-041	<p>Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Light cove ceiling and outer perimeter gypsum board to be painted SW 7620 Seaworthy. Prepare concrete floor for polished concrete finishing.</p>		
	<p>SPACE: 103 - CIRCULATION</p> <p>CATEGORY: Gypsum Board / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:21 PM</p> <p>REFERENCE: 092900 / 099123</p>	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-042	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.				
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	1/15/25 at 12:21 PM	
	CATEGORY:	Gypsum Board / Interior Painting	REFERENCE:	092900 / 099123	


Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-043	Aluminum curtain wall installation in progress. Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.				
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	1/15/25 at 12:21 PM	
	CATEGORY:	Aluminum Curtain Walls / Interior Painting	REFERENCE:	084413 / 099123	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-044	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.		
	SPACE: 101 - RECEPTION / GREETING AREA	SUBJECT: 1/15/25 at 12:21 PM	
	CATEGORY: Gypsum Board / Interior Painting	REFERENCE: 092900 / 099123	

ITEM	REMARKS	DISCUSSION	PHOTO
031-045	Aluminum curtain wall installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.		
	SPACE: 101 - RECEPTION / GREETING AREA	SUBJECT: 1/15/25 at 12:22 PM	
	CATEGORY: Aluminum Curtain Walls / Interior Painting	REFERENCE: 084413 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-046	Aluminum curtain wall installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.				
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	1/15/25 at 12:22 PM	
	CATEGORY:	Aluminum Curtain Walls / Interior Painting	REFERENCE:	084413 / 099123	

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-047	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	172 - CIRCULATION	SUBJECT:	1/15/25 at 12:23 PM
CATEGORY:	Acoustical Panel Ceilings / Tile Carpeting	REFERENCE:	095113 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-048	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

	Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.				
	SPACE:	180 - TECHNICIAN 6	SUBJECT:	1/15/25 at 12:23 PM	
	CATEGORY:	Acoustical Panel Ceilings / Tile Carpeting	REFERENCE:	095113 / 096813	

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-049	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

		Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
		SPACE:	178 - TECHNICIAN 4	SUBJECT:	1/15/25 at 12:24 PM
		CATEGORY:	Acoustical Panel Ceilings / Tile Carpeting	REFERENCE:	095113 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-050	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT:	1/15/25 at 12:25 PM
CATEGORY:	Acoustical Panel Ceilings / Tile Carpeting	REFERENCE:	095113 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-051	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT:	1/15/25 at 12:25 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-052	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	167 - DATA LEADER	SUBJECT:	1/15/25 at 12:28 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-053	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	167 - DATA LEADER	SUBJECT:	1/15/25 at 12:28 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-054	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	166 - NETWORK ADMINISTRATOR	SUBJECT:	1/15/25 at 12:28 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-055	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	166 - NETWORK ADMINISTRATOR	SUBJECT:	1/15/25 at 12:29 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-056	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	165 - WAR ROOM	SUBJECT:	1/15/25 at 12:29 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-057	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	165 - WAR ROOM	SUBJECT:	1/15/25 at 12:29 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-058	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT:	1/15/25 at 12:29 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-059	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT:	1/15/25 at 12:30 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-060	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Linoleum flooring installation in progress. Install linoleum flooring per part 3 execution specification section 096543. Provide cleaning and protection per specification section 096543 3.5.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight. Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

096513 3.5.			
SPACE:	163 - STORAGE	SUBJECT:	1/15/25 at 12:30 PM
CATEGORY:	Acoustical Panel Ceilings / Linoleum	REFERENCE:	095113 / 096543

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-061	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	162 - CIRCULATION	SUBJECT:	1/15/25 at 12:30 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-062	<p>Linoleum flooring installation in progress. Install linoleum flooring per part 3 execution specification section 096543. Provide cleaning and protection per specification section 096543 3.5.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight. Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.</p>		
	SPACE:	168 - BUG ROOM 1	SUBJECT: 1/15/25 at 12:31 PM
	CATEGORY:	Resilient Base / Linoleum	REFERENCE: 096513 / 096543


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-063	<p>Linoleum flooring installation in progress. Install linoleum flooring per part 3 execution specification section 096543. Provide cleaning and protection per specification section 096543 3.5.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight. Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.</p>				
	SPACE:	168 - BUG ROOM 1	SUBJECT:	1/15/25 at 12:31 PM	
	CATEGORY:	Resilient Base / Linoleum	REFERENCE:	096513 / 096543	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO		
031-064	<p>Linoleum flooring installation in progress. Install linoleum flooring per part 3 execution specification section 096543. Provide cleaning and protection per specification section 096543 3.5.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight. Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.</p>						
	SPACE:	169 - BREAK ROOM				SUBJECT:	1/15/25 at 12:31 PM
	CATEGORY:	Linoleum				REFERENCE:	096543

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-065	<p>Linoleum flooring installation in progress. Install linoleum flooring per part 3 execution specification section 096543. Provide cleaning and protection per specification section 096543 3.5.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight. Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.</p>		
	SPACE: 169 - BREAK ROOM	SUBJECT:	1/15/25 at 12:31 PM
	CATEGORY: Linoleum	REFERENCE:	096543

Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS		DISCUSSION		PHOTO
031-066	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.				
	SPACE:	174 - IMAGE ROOM	SUBJECT:	1/15/25 at 12:32 PM	
	CATEGORY:	Interior Painting	REFERENCE:	099123	

ITEM	REMARKS		DISCUSSION		PHOTO
031-067	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.				
	SPACE:	174 - IMAGE ROOM	SUBJECT:	1/15/25 at 12:32 PM	
CATEGORY:	Interior Painting	REFERENCE:	099123		

ITEM	REMARKS		DISCUSSION		PHOTO
031-068	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.				
	SPACE:	174 - IMAGE ROOM	SUBJECT:	1/15/25 at 12:32 PM	
CATEGORY:	Interior Painting	REFERENCE:	099123		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-069	Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.			
	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.			
	SPACE:			
CATEGORY:	Pipe and Tube Railings / Interior Painting	REFERENCE:	055213 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-070	Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.		
	Interior painting in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
SPACE:	183 - WAREHOUSE	SUBJECT:	1/15/25 at 12:33 PM
CATEGORY:	Pipe and Tube Railings / Interior Painting	REFERENCE:	055213 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO								
031-071	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.</p>										
	<table> <tr> <td>SPACE:</td><td>173 - BUG ROOM 2</td><td>SUBJECT:</td><td>1/15/25 at 12:34 PM</td></tr> <tr> <td>CATEGORY:</td><td>Acoustical Panel Ceilings / Interior Painting</td><td>REFERENCE:</td><td>095113 / 099123</td></tr> </table>	SPACE:	173 - BUG ROOM 2	SUBJECT:	1/15/25 at 12:34 PM	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123		
SPACE:	173 - BUG ROOM 2	SUBJECT:	1/15/25 at 12:34 PM								
CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123								


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-072	Interior painting in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.				
	SPACE:	170 - NETWORK OPERATIONS	SUBJECT:	1/15/25 at 12:34 PM	
	CATEGORY:	Interior Painting	REFERENCE:	099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-073	Storefront installation in progress.				
	Interior painting in progress.				
	Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations.				
	Bug holes in CMU block finish will not be acceptable.				
	Remove dirt and stains from concrete floor.				
Prepare concrete floor for concrete sealer.					
	SPACE:	170 - NETWORK OPERATIONS	SUBJECT:	1/15/25 at 12:35 PM	
	CATEGORY:	Storefront Framing / Interior Painting	REFERENCE:	084113 / 099123	

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-074	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	171 - CONFERENCE ROOM	SUBJECT:	1/15/25 at 12:35 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-075	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	171 - CONFERENCE ROOM	SUBJECT:	1/15/25 at 12:35 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-076	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	171 - CONFERENCE ROOM	SUBJECT:	1/15/25 at 12:36 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-077	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	171 - CONFERENCE ROOM	SUBJECT:	1/15/25 at 12:37 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

ITEM	REMARKS	DISCUSSION	PHOTO
031-078	Tile carpeting adhesive stored on site is the approved submittal adhesive.		
	SPACE:	171 - CONFERENCE ROOM	SUBJECT: 1/15/25 at 12:37 PM
	CATEGORY:	Tile Carpeting	REFERENCE: 096813

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-079	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction
 Progress Site Visit
 REPORT NO: 031

Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	172 - CIRCULATION	SUBJECT:	1/15/25 at 12:37 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-080	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	162 - CIRCULATION	SUBJECT:	1/15/25 at 12:37 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

ITEM	REMARKS	DISCUSSION	PHOTO
031-081	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	106 - PUBLIC FEMALE RESTROOM	SUBJECT: 1/15/25 at 12:38 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-082	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	106 - PUBLIC FEMALE RESTROOM	SUBJECT: 1/15/25 at 12:38 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

ITEM	REMARKS	DISCUSSION	PHOTO
031-083	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	106 - PUBLIC FEMALE RESTROOM	SUBJECT: 1/15/25 at 12:39 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-084	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	104 - PUBLIC MALE RESTROOM	SUBJECT: 1/15/25 at 12:39 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

ITEM	REMARKS	DISCUSSION	PHOTO
031-085	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	104 - PUBLIC MALE RESTROOM	SUBJECT: 1/15/25 at 12:40 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-086	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	104 - PUBLIC MALE RESTROOM	SUBJECT: 1/15/25 at 12:40 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

ITEM	REMARKS	DISCUSSION	PHOTO
031-087	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	105 - JANITOR	SUBJECT: 1/15/25 at 12:41 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-088	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 105 - JANITOR	SUBJECT: 1/15/25 at 12:41 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

ITEM	REMARKS	DISCUSSION	PHOTO
031-089	Fire extinguisher cabinet installation in progress. Install fire protection cabinet per part 3 execution specification section 104413. Provide adjusting and cleaning per specification section 104413 3.4. Ensure all cabinet corners are properly sealed.		
	SPACE: 103 - CIRCULATION	SUBJECT: 1/15/25 at 12:41 PM	
	CATEGORY: Fire Protection Cabinets	REFERENCE: 104413	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-090	Fire extinguisher cabinet installation in progress. Install fire protection cabinet per part 3 execution specification section 104413. Provide adjusting and cleaning per specification section 104413 3.4. Ensure all cabinet corners are properly sealed.				
	SPACE:	103 - CIRCULATION	SUBJECT:	1/15/25 at 12:42 PM	
	CATEGORY:	Fire Protection Cabinets	REFERENCE:	104413	

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-091	<p>Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Light cove ceiling and outer perimeter gypsum board to be painted SW 7620 Seaworthy. Prepare concrete floor for polished concrete finishing.</p>		
	<p>SPACE: 103 - CIRCULATION</p> <p>CATEGORY: Gypsum Board / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:42 PM</p> <p>REFERENCE: 092900 / 099123</p>	

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-092	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	<p>SPACE: 128 - GARAGE MANAGER OFFICE</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:43 PM</p> <p>REFERENCE: 095113 / 099123</p>	

Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-093	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	<p>SPACE: 129 - ADMIN. ASSISTANT OFFICE</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:43 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-094	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	<p>SPACE: 130 - MECHANIC BREAK ROOM</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:43 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-095	<p>Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Light cove ceiling and outer perimeter gypsum board to be painted SW 7620 Seaworthy. Prepare concrete floor for polished concrete finishing.</p>		
	<p>SPACE: 103 - CIRCULATION</p> <p>CATEGORY: Gypsum Board / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:44 PM</p> <p>REFERENCE: 092900 / 099123</p>	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-096	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.		
	SPACE: 109 - SHARED LOADING DOCK	SUBJECT: 1/15/25 at 12:44 PM	
	CATEGORY: Gypsum Board / Interior Painting	REFERENCE: 092900 / 099123	

ITEM	REMARKS	DISCUSSION	PHOTO
031-097	Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish. Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for polished concrete finishing.		
	SPACE: 111 - STAIR B	SUBJECT: 1/15/25 at 12:44 PM	
	CATEGORY: Pipe and Tube Railings / Interior Painting	REFERENCE: 055213 / 099123	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-098	Hydraulic service elevator installation in progress.		
	SPACE: 112 - SERVICE ELEVATOR	SUBJECT: 1/15/25 at 12:44 PM	
	CATEGORY: Hydraulic Service Elevator	REFERENCE: 142413	

ITEM	REMARKS	DISCUSSION	PHOTO
031-099	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.		
	SPACE: 110 - CIRCULATION	SUBJECT: 1/15/25 at 12:44 PM	
	CATEGORY: Gypsum Board / Interior Painting	REFERENCE: 092900 / 099123	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-100	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.		
	SPACE:	115 - VENDER RECEIVING AREA	SUBJECT: 1/15/25 at 12:44 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-101	Hollow metal door installation in progress.		
	SPACE:	116 - FIRE PROTECTION / DOMESTIC WATER CLOSET	SUBJECT: 1/15/25 at 12:45 PM
	CATEGORY:	Hollow Metal Frame	REFERENCE: 081113


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-102	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation.			
	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.			
	SPACE:	114 - SHARED LOADING DOCK	SUBJECT:	1/15/25 at 12:45 PM
	CATEGORY:	Overhead Coiling Door / Interior Painting	REFERENCE:	083323 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-103	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation.			
	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.			
	SPACE:			
	CATEGORY:	Overhead Coiling Door / Interior Painting	REFERENCE:	083323 / 099123


Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-104	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Linoleum flooring installation in progress. Install linoleum flooring per part 3 execution specification section 096543. Provide cleaning and protection per specification section 096543 3.5.</p>		
	<div>SPACE:</div> <div>119 - DRIVERS BREAK ROOM</div>	<div>SUBJECT:</div> <div>1/15/25 at 12:46 PM</div>	
	<div>CATEGORY:</div> <div>Acoustical Panel Ceilings / Linoleum</div>	<div>REFERENCE:</div> <div>095113 / 096543</div>	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-105	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.		
	SPACE:	110 - CIRCULATION	SUBJECT: 1/15/25 at 12:46 PM
	CATEGORY:	Gypsum Board / Interior Painting	REFERENCE: 092900 / 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-106	Hydraulic service elevator installation in progress.		
	SPACE:	113 - ELEVATOR MECHANICAL	SUBJECT: 1/15/25 at 12:47 PM
	CATEGORY:	Hydraulic Service Elevator	REFERENCE: 142413

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-107	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for concrete sealer.		
	SPACE: 117 - DRY FOOD STORAGE	SUBJECT: 1/15/25 at 12:47 PM	
	CATEGORY: Interior Painting	REFERENCE: 099123	


ITEM	REMARKS	DISCUSSION	PHOTO
031-108	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.		
	SPACE: 117 - DRY FOOD STORAGE	SUBJECT: 1/15/25 at 12:47 PM	
	CATEGORY: Overhead Coiling Door / Interior Painting	REFERENCE: 083323 / 099123	

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-109	Food service equipment installation in progress.		
	SPACE:	109 - SHARED LOADING DOCK	SUBJECT: 1/15/25 at 12:48 PM
	CATEGORY:	Food Service Equipment	REFERENCE: 114000


ITEM	REMARKS	DISCUSSION	PHOTO
031-110	Food service equipment installation in progress.		
	SPACE:	118 - FREEZER STORAGE	SUBJECT: 1/15/25 at 12:48 PM
	CATEGORY:	Food Service Equipment	REFERENCE: 114000

ITEM	REMARKS	DISCUSSION	PHOTO
031-111	Food service equipment installation in progress.		
	SPACE:	118 - FREEZER STORAGE	SUBJECT: 1/15/25 at 12:48 PM
	CATEGORY:	Food Service Equipment	REFERENCE: 114000

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-112	Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.		
	SPACE: 107 - CIRCULATION	SUBJECT: 1/15/25 at 12:49 PM	
	CATEGORY: Gypsum Board / Interior Painting	REFERENCE: 092900 / 099123	

ITEM	REMARKS	DISCUSSION	PHOTO
031-113	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 125 - MALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:50 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-114	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 125 - MALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:50 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

ITEM	REMARKS	DISCUSSION	PHOTO
031-115	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8. Verify waterproof membrane has been installed at showers		
	SPACE: 127 - SHOWER 2	SUBJECT: 1/15/25 at 12:50 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-116	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	125 - MALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:51 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

ITEM	REMARKS	DISCUSSION	PHOTO
031-117	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	125 - MALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:51 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-118	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 122 - FEMALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:52 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

ITEM	REMARKS	DISCUSSION	PHOTO
031-119	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 122 - FEMALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:53 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-120	<p>Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8. Verify waterproof membrane has been installed at showers</p>		
	SPACE:	123 - SHOWER 1	SUBJECT: 1/15/25 at 12:53 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

ITEM	REMARKS	DISCUSSION	PHOTO
031-121	<p>Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.</p>		
	SPACE:	122 - FEMALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:54 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-122	<p>Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.</p>		
	SPACE: 122 - FEMALE LOCKER ROOM	SUBJECT: 1/15/25 at 12:54 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

ITEM	REMARKS	DISCUSSION	PHOTO
031-123	<p>Gypsum board installation in progress. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable. Prepare concrete floor for polished concrete finishing.</p>		
	SPACE: 108 - CIRCULATION	SUBJECT: 1/15/25 at 12:54 PM	
	CATEGORY: Gypsum Board / Interior Painting	REFERENCE: 092900 / 099123	

Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-124	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>			
	SPACE:	158 - TRAINING ROOM	SUBJECT:	1/15/25 at 12:55 PM
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123

Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-125	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>			
	SPACE:	159 - PLAN AND O+M ROOM	SUBJECT:	1/15/25 at 12:55 PM
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123


Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-126	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	<p>SPACE: 160 - RECORDS AND PLAN ARCHIVE</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 12:55 PM</p> <p>REFERENCE: 095113 / 099123</p>	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-127	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE:	157 - WORK SPACE CARPENTRY	SUBJECT: 1/15/25 at 12:56 PM
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-128	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE:	156 - WORK SPACE HVAC	SUBJECT: 1/15/25 at 12:56 PM
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-129	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE:	155 - WORK SPACE ELECTRICIAN	SUBJECT: 1/15/25 at 12:57 PM
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-130	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE:	154 - WORK SPACE PLUMBING	SUBJECT: 1/15/25 at 12:57 PM
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-131	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE:	154 - WORK SPACE PLUMBING	SUBJECT: 1/15/25 at 12:57 PM
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523

ITEM	REMARKS	DISCUSSION	PHOTO
031-132	Sectional door installation in progress. Adjust sectional doors for smooth operation. Radiant heater installation in progress.		
	SPACE:	157 - WORK SPACE CARPENTRY	SUBJECT: 1/15/25 at 12:58 PM
	CATEGORY:	Sectional Doors / Radiant Heaters	REFERENCE: 083613 / 235523

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-133	<p>Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.</p> <p>Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.</p>		
	SPACE:	226 - MEZZANINE	SUBJECT: 1/15/25 at 12:59 PM
	CATEGORY:	Pipe and Tube Railings	REFERENCE: 055213

ITEM	REMARKS	DISCUSSION	PHOTO
031-134	<p>Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.</p> <p>Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.</p>		
	SPACE:	226 - MEZZANINE	SUBJECT: 1/15/25 at 12:59 PM
	CATEGORY:	Pipe and Tube Railings	REFERENCE: 055213

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-135	<p>Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.</p> <p>Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.</p>		
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT: 1/15/25 at 12:59 PM
	CATEGORY:	Pipe and Tube Railings / Interior Painting	REFERENCE: 055213 / 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-136	Computer Room AC installation in progress.		
	SPACE:	229A - NOC MECHANICAL	SUBJECT: 1/15/25 at 1:01 PM
	CATEGORY:	Computer Room Air Conditioning Unit	REFERENCE: 238123

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-137	Computer Room AC installation in progress.		
	SPACE:	229A - NOC MECHANICAL	SUBJECT: 1/15/25 at 1:01 PM
	CATEGORY:	Computer Room Air Conditioning Unit	REFERENCE: 238123

ITEM	REMARKS	DISCUSSION	PHOTO
031-138	Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.		
	Interior painting in progress. Remove dirt and stains from concrete floor. Prepare concrete floor for concrete sealer.		
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT: 1/15/25 at 1:02 PM
	CATEGORY:	Pipe and Tube Railings	REFERENCE: 055213

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-139	Lighting installation in progress.		
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT: 1/15/25 at 1:02 PM
	CATEGORY:	Interior Lighting	REFERENCE: 265100

ITEM	REMARKS	DISCUSSION	PHOTO
031-140	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE:	216 - RESTROOM A	SUBJECT: 1/15/25 at 1:03 PM
	CATEGORY:	Ceramic Tiling	REFERENCE: 093013


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION			PHOTO
031-141	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.				
	SPACE:	216 - RESTROOM A	SUBJECT:	1/15/25 at 1:03 PM	
	CATEGORY:	Ceramic Tiling	REFERENCE:	093013	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-142	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>			
SPACE:		202 - CIRCULATION	SUBJECT:	1/15/25 at 1:04 PM
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION			PHOTO
031-143	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.				
	SPACE:	217 - JANITOR B	SUBJECT:	1/15/25 at 1:04 PM	
	CATEGORY:	Ceramic Tiling	REFERENCE:	093013	


Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-144	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>			
SPACE:		202 - CIRCULATION	SUBJECT:	1/15/25 at 1:04 PM
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-145	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 218 - RESTROOM B	SUBJECT: 1/15/25 at 1:05 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	

ITEM	REMARKS	DISCUSSION	PHOTO
031-146	Ceramic tiling installation in progress. Install ceramic tiling per part 3 execution specification section 093013. Provide adjusting and cleaning per specification section 093013 3.7. Provide protection per specification section 093013 3.8.		
	SPACE: 218 - RESTROOM B	SUBJECT: 1/15/25 at 1:05 PM	
	CATEGORY: Ceramic Tiling	REFERENCE: 093013	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-147	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>			
SPACE:		206 - WORK AREA	SUBJECT:	1/15/25 at 1:05 PM
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-148	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Storefront installation in progress.</p> <p>Interior painting in progress.</p>		
	SPACE: 213 - CONFERENCE ROOM	SUBJECT:	1/15/25 at 1:06 PM
	CATEGORY: Storefront Framing / Interior Painting	REFERENCE:	084113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-149	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.				
	SPACE:	212 - FILE STORAGE	SUBJECT:	1/15/25 at 1:06 PM	
CATEGORY:	Interior Painting		REFERENCE:	099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-150	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>				
SPACE:		211 - CLERICAL ASSISTANT 3	SUBJECT:	1/15/25 at 1:06 PM	
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-151	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>				
SPACE:		210 - CLERICAL ASSISTANT 2	SUBJECT:	1/15/25 at 1:06 PM	
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-152	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 209 - CLERICAL ASSISTANT 1</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 1:06 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-153	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>				
	SPACE:	208 - TRANSPORTATION DIRECTOR	SUBJECT:	1/15/25 at 1:07 PM	
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-154	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	SPACE:	207 - TRANSPORTATION ASSISTANT DIRECTOR	SUBJECT: 1/15/25 at 1:07 PM
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE: 095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-155	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 206 - WORK AREA</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 1:07 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-156	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 206 - WORK AREA</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 1:07 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-157	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	SPACE: 215 - AREA COORDINATOR 1	SUBJECT:	1/15/25 at 1:08 PM
	CATEGORY: Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-158	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<div>SPACE:</div> <div>214 - AREA COORDINATOR 2</div>	<div>SUBJECT:</div> <div>1/15/25 at 1:08 PM</div>	
	<div>CATEGORY:</div> <div>Acoustical Panel Ceilings / Interior Painting</div>	<div>REFERENCE:</div> <div>095113 / 099123</div>	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-159	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 205 - LARGE TRAINING ROOM</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 1:09 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-160	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 205 - LARGE TRAINING ROOM</p>	SUBJECT:	1/15/25 at 1:09 PM
	<p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	REFERENCE:	095113 / 099123


Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-161	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<div>SPACE:</div> <div>204 - KITCHEN</div>	<div>SUBJECT:</div> <div>1/15/25 at 1:09 PM</div>	
	<div>CATEGORY:</div> <div>Acoustical Panel Ceilings / Interior Painting</div>	<div>REFERENCE:</div> <div>095113 / 099123</div>	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-162	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	SPACE: 204 - KITCHEN	SUBJECT: 1/15/25 at 1:09 PM	
	CATEGORY: Acoustical Panel Ceilings / Interior Painting	REFERENCE: 095113 / 099123	

ITEM	REMARKS	DISCUSSION	PHOTO
031-163	<p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	SPACE: 102 - STAIR A	SUBJECT: 1/15/25 at 1:10 PM	
	CATEGORY: Interior Painting	REFERENCE: 099123	

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-164	Interior painting installation in progress.		
	SPACE:	201 - CIRCULATION	SUBJECT: 1/15/25 at 1:10 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-165	Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5. Interior painting in progress.		
	SPACE:	220 - OFFICE SUPPLIES	SUBJECT: 1/15/25 at 1:12 PM
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE: 095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-166	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>			
SPACE:		221 - OFFICE 1	SUBJECT:	1/15/25 at 1:12 PM
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-167	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>			
SPACE:		222 - OFFICE 2	SUBJECT:	1/15/25 at 1:12 PM
CATEGORY:		Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-168	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>				
	SPACE:	223 - LARGE OPEN OFFICE 3	SUBJECT:	1/15/25 at 1:12 PM	
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE:	095113 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-169	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	SPACE:	223 - LARGE OPEN OFFICE 3	SUBJECT: 1/15/25 at 1:12 PM
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE: 095113 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-170	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 224 - CONFERENCE ROOM</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 1:13 PM</p> <p>REFERENCE: 095113 / 099123</p>	


Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-171	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	<p>SPACE: 224 - CONFERENCE ROOM</p> <p>CATEGORY: Acoustical Panel Ceilings / Interior Painting</p>	<p>SUBJECT: 1/15/25 at 1:13 PM</p> <p>REFERENCE: 095113 / 099123</p>	

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-172	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Interior painting in progress.</p>		
	SPACE:	219 - WORK AREA	SUBJECT: 1/15/25 at 1:14 PM
	CATEGORY:	Acoustical Panel Ceilings / Interior Painting	REFERENCE: 095113 / 099123


ITEM	REMARKS	DISCUSSION	PHOTO
031-173	Mechanical / Electrical installation in progress		
	SPACE:	225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT: 1/15/25 at 1:14 PM
	CATEGORY:	Mechanical / Electrical	REFERENCE: 230000 / 260000

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-174	Mechanical / Electrical installation in progress		
	SPACE:	225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT: 1/15/25 at 1:15 PM
	CATEGORY:	Mechanical / Electrical	REFERENCE: 230000 / 260000

ITEM	REMARKS	DISCUSSION	PHOTO
031-175	Interior painting installation in progress.		
	SPACE:	201 - CIRCULATION	SUBJECT: 1/15/25 at 1:15 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-176	Interior painting installation in progress.		
	SPACE:	201 - CIRCULATION	SUBJECT: 1/15/25 at 1:16 PM
	CATEGORY:	Interior Painting	REFERENCE: 099123


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS		DISCUSSION		PHOTO
031-177	Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish. Interior painting in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.				
	SPACE:	111 - STAIR B	SUBJECT:	1/15/25 at 1:16 PM	
	CATEGORY:	Pipe and Tube Railings / Interior Painting	REFERENCE:	055213 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-178	Pipe and tube rail installation in progress. clean and prepare pipe and tube rail for paint finish.			
	Interior painting in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.			
SPACE:	111 - STAIR B	SUBJECT:	1/15/25 at 1:16 PM	
CATEGORY:	Pipe and Tube Railings / Interior Painting	REFERENCE:	055213 / 099123	

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-179	<p>Acoustical panel ceiling installation in progress. Install acoustical panel ceilings per part 3 execution specification section 095113. Ensure all acoustical panel ceilings are properly seated in the ceiling grid. Ensure all acoustical panel ceiling tiles are installed free of scratches or damage. Provide cleaning per specification section 095113 3.5.</p> <p>Tile carpeting installation in progress. Install tile carpeting per part 3 execution specification section 096813. Ensure tile carpeting is installed and properly secured to sub-straight such that the tile carpeting corners and edges are installed with a hairline seam. Provide cleaning and protection per specification section 096813 3.4.</p> <p>Resilient base and accessories installation in progress. Install resilient base and accessories per part 3 execution specification section 096513. Ensure resilient base is properly secured to sub-straight.</p>		

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


Resilient base shall be continuously adhered to sub-straight at top edge of base. Provide cleaning and protection per specification section 096513 3.5.			
SPACE:	172 - CIRCULATION	SUBJECT:	1/15/25 at 1:19 PM
CATEGORY:	Acoustical Panel Ceilings / Resilient Base / Tile Carpeting	REFERENCE:	095113 / 096513 / 096813

ITEM	REMARKS	DISCUSSION	PHOTO
031-180	Engine generator installation in progress.		
	SPACE:	008 - SITE - WEST	
	CATEGORY:	Engine Generators	
		SUBJECT:	1/15/25 at 1:21 PM
		REFERENCE:	263213

Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-181	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE: 004 - WEST ELEVATION	SUBJECT: 1/15/25 at 1:22 PM	
	CATEGORY: Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213	

ITEM	REMARKS	DISCUSSION	PHOTO
031-182	Aluminum curtain wall installation in progress. Ensure horizontal mullion is in line with bottom of masonry opening. Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.		
	SPACE: 184 - COVERED LOADING DOCK	SUBJECT: 1/15/25 at 1:23 PM	
	CATEGORY: Aluminum Curtain Walls / Interior Painting	REFERENCE: 084413 / 099123	


Site Visit - Construction Observation

DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-183	<p>Aluminum curtain wall installation in progress. Ensure horizontal mullion is in line with bottom of masonry opening.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	SPACE: 184 - COVERED LOADING DOCK		
	CATEGORY: Aluminum Curtain Walls / Interior Painting		
		SUBJECT:	1/15/25 at 1:23 PM
		REFERENCE:	084413 / 099123


Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION		PHOTO
031-184	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation.			
	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.			
	SPACE:	185 - OPERATIONS WAREHOUSE	SUBJECT:	1/15/25 at 1:24 PM
	CATEGORY:	Overhead Coiling Doors / Interior Painting	REFERENCE:	083323 / 099123


Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO					
031-185	Overhead coiling door installation in progress. Adjust overhead coiling door for smooth operation.							
	Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.							
	<table> <tr> <td>SPACE:</td><td>185 - OPERATIONS WAREHOUSE</td><td>SUBJECT:</td><td>1/15/25 at 1:25 PM</td></tr> <tr> <td>CATEGORY:</td><td>Overhead Coiling Doors / Interior Painting</td><td>REFERENCE:</td><td>083323 / 099123</td></tr> </table>			SPACE:	185 - OPERATIONS WAREHOUSE	SUBJECT:	1/15/25 at 1:25 PM	CATEGORY:
SPACE:	185 - OPERATIONS WAREHOUSE	SUBJECT:	1/15/25 at 1:25 PM					
CATEGORY:	Overhead Coiling Doors / Interior Painting	REFERENCE:	083323 / 099123					

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-186	<p>Hollow metal door and frame installation in progress.</p> <p>Interior painting installation in progress. Provide block filler to fill all bug holes in CMU per shop drawing submittal and manufacturers recommendations. Bug holes in CMU block finish will not be acceptable.</p>		
	SPACE:	185 - OPERATIONS WAREHOUSE	SUBJECT: 1/15/25 at 1:25 PM
	CATEGORY:	Hollow Metal Doors and Frames / Interior Painting	REFERENCE: 081113 / 099123

ITEM	REMARKS	DISCUSSION	PHOTO
031-187	<p>Aluminum curtain wall installation in progress. Ensure horizontal mullion is in line with bottom of masonry opening.</p>		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:26 PM
	CATEGORY:	Aluminum Curtain Walls	REFERENCE: 084413

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-188	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 1/15/25 at 1:27 PM
	CATEGORY:	Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213

ITEM	REMARKS	DISCUSSION	PHOTO
031-189	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE:	007 - SITE - EAST	SUBJECT: 1/15/25 at 1:27 PM
	CATEGORY:	Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213

Site Visit - Construction Observation


DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-190	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:27 PM
	CATEGORY:	Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213

ITEM	REMARKS	DISCUSSION	PHOTO
031-191	Aluminum curtain wall installation in progress.		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:28 PM
	CATEGORY:	Aluminum Curtain Walls	REFERENCE: 084413

Site Visit - Construction Observation


DATE: 1/15/2025
 VISIT NAME: Construction Progress Site Visit
 REPORT NO: 031


ITEM	REMARKS	DISCUSSION	PHOTO
031-192	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:28 PM
	CATEGORY:	Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213

ITEM	REMARKS	DISCUSSION	PHOTO
031-193	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:29 PM
	CATEGORY:	Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213

Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031

ITEM	REMARKS	DISCUSSION	PHOTO
031-194	Column cover installation in progress. Weather barrier installation in progress. Metal wall panel installation in progress.		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:30 PM
	CATEGORY:	Column Covers / Weather Barriers / Metal Wall Panels	REFERENCE: 055813 / 072500 / 074213

ITEM	REMARKS	DISCUSSION	PHOTO
031-195	Joint sealant installation in progress. See joint sealant color selections for sealant color at brick and sealant color at stone wainscot.		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 1/15/25 at 1:36 PM
	CATEGORY:	Joint Sealants	REFERENCE: 079200

TO:

Carrie Hooten	Kenton County School District
Kevin Pfefferman	Kenton County School District
Matthew Rigg	Kenton County School District
Brian Vanover	Kenton County School District

COPIES:

Seth Mittle	GRW
David Vaught	GRW
Todd Cantrell	GRW
Mike McReynolds	GRW
Jon Sheppard	GRW
Jim Adams	Facility Commissioning Group
Adolph Zell	Morel Construction
Anthony Berkemeier	Morel Construction

Site Visit - Construction Observation

DATE: 1/15/2025
VISIT NAME: Construction
Progress Site Visit
REPORT NO: 031