

Appendix F

Periodic Surveillance of ACBM - 6 Month ReassessmentReassessed By : Heather RiveraDate of Reassessment : 5/16/2025

Functional Area Description	ACBM Type and Quantity	Homogeneous Material	Notes
Homogenous Area 28		ACM Paper under Overhead flooring	No visible change
Homogenous Area 10		12 " Ceiling Tiles 112 / 113	No visible change
Homogenous Area 10		12" Ceiling Tiles hallway by 213	No visible change
Homogenous Area 49		Floor tile mastic under cabinets	No visible change
Homogenous Area 43		Mastic under sinks Rm: 102,114,116	No visible change
Homogenous Area 43		Mastic under sinks Rm: 228	No visible change
Homogenous Area 5		Firedoor Core - First Floor area	No visible change
Homogenous Area 5		Firedoor Core - Second Floor area	No visible change
Homogenous Area 55		Presumed ACM Gaskets boiler area	No visible change
Homogenous Area 59		1st floor area with Presumed ACM Mastic behind Activity boards	No visible change
Homogenous Area 59		2nd floor area with Presumed ACM Mastic behind Activity boards	No visible change