| | CHIEF OPERATIONS OFFICER | | | | | | | |
|-------------------------|---|--|---|-------------------|----------------------------------|--|--|--|
| | FROM: MICHAEL A. MULHEIRN, DIRECTOR FACILITIES AND ENVIRONMENTAL SERVICES | | | | | | | |
| | SUBJECT: | | | | | | | |
| | DATE: | OCTOBER 26, 2015 | | | | | | |
| BG# 15-297 14-108 | | CONTRACTOR Flynn Brothers David Construction | SCHOOL/PROJECT Bowen ES-New Road Dunn ES-HVAC Renovation Phase I/Media Center | C.O.# 01 06 | AMOUNT 5,040.00 62,957.00 | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | Secreta | ry, Board of Education | Chairman, Board of Education | | | | | |
| | | | out the question of the adoption of this resolution before ctober 26, 2015 and the following voted: | e the Jeffe | erson | | | |
| | VOTING A | YE: | | | | | | |
| | VOTING N | JAY: | | | | | | |
| | PASSED A | ND APPROVED: | | | | | | |

TO:

DR. MICHAEL RAISOR

BOARD OF EDUCATION MEETING OCTOBER 26, 2015

| New Road @ Bowen E | | | | |
|--------------------|---------------------|----------------------|-----------------------|-----------------------|
| Original Contract | Previous Approved | Current Change Order | Total Contract Amount | Total Project Cost to |
| Amount | Change Order Amount | Amount | to Date | Date |
| 99,361.00 | 0.00 | 5,040.00 | 104,401.00 | 103,778 |

 Undercut 72 cubic yards of unsuitable material and dispose offsite. Provide and install stone backfill wrapped in geotextile fabric to stabilize existing subgrade conditions. Justification: Found conditions.

| | HVAC Renovation Ph | ase I/Media Center @ D | unn ES | Change Ord | der #06 | |
|-------------------|---------------------------|------------------------|----------------------|------------|------------------------------|-----------------------|
| Original Contract | | Previous Approved | Current Change Order | | Total Contract Amount | Total Project Cost to |
| Amount | | Change Order Amount | Amount | | to Date | Date |
| | 6,513,400.00 | -34,410.00 | | 62,957.00 | 6,541,947.00 | 6,664,522 |

- 1. Substitute "C" channel roof framing for steel joists at exterior Patio Canopy. Justification: Found conditions.
- 2. Change boiler motors to 208v, 3 phase power. Justification: Found conditions.
- 3. Install one fixture type K1 (exit sign) over interior corridor pair of doors. Justification: Owner requested.
- 4. Re-route canopy roof drain and add CMU pipe chase at Media Center Addition. Justification: Found conditions.
- 5. Remove asbestos insulation in Boiler Room and mastic in Resource Room 137 and Kitchen. Justification: Found conditions.
- 6. Fill in roof deck low spots at school building roof. Justification: Found conditions.
- 7. Electrical and data outlet revisions at Media Room #204. Justification: Owner requested.
- 8. CMU jamb and head revisions at Opening #202B. Justification: Found conditions.
- 9. Asphalt patching at school circulation roadway. Justification: Found conditions.
- 10. Mechanical yard fencing modifications. Justification: Owner requested.
- 11. CMU wall patching. Justification: Owner requested.
- 12. Drill hole at Media Center foundation wall. Justification: Owner requested.
- 13. Credit for roof deck allowance work. Justification: Owner requested.
- 14. Additional asphalt patching and raising storm drain. Justification: Found conditions.
- 15. Concrete walk revision. Justification: Owner requested.
- 16. Water line relocation. Justification: Found conditions.