

## **Bullitt County Public Schools**

1040 Highway 44 East Shepherdsville, Kentucky 40165

502-869-8000 Fax 502-543-3608 www.bullittschools.org

**MEMO** 

TO:

**Keith Davis** 

FROM:

DATE:

February 7, 2018

RE:

Board Agenda Item - Room 11 Modifications - North Bullitt

**High School** 

Presented for Board approval is a request from Mr. Chris Verdow for minor modifications to room 11 at North Bullitt High School.

The first part of the request is to remove the countertop and sink from room 12. This sink hasn't been used for years and is in the way. The second part involves removing the power poles. There will be some floor repair needed as tile will need to be added where the cabinets are currently located and where the power poles are located. Currently, the classroom is set up as a computer lab. This set up is obsolete now that the school uses Chromebooks and is better suited for a functional classroom.

The modifications are estimated to cost around \$250.00 and will be funded by North Bullitt High School via Fund 22. Work will be performed by maintenance employees and will be completed during the summer break.

I recommend the Board approve the request from Mr. Chris Verdow for modifications in room 11 at North Bullitt High School.

Attachment:

Memo from Mr. Chris Verdow



## North Bullitt High School

The Home of the Eagles

Chris VerDow, Principal Joni Britt, Assistant Principal Nick Sutherlan , Assistant Principal Lindsey Wegley, Assistant Principal



Soaring to New Heights

Ashley Poore, Counselor Chelsea Mullennex, Counselor Amy Rogers, Counselor

To: Board of Education

From: Chris VerDow

Re: Minor Building Modifications.

Rooms 11, 12 and 13 are the old, business classrooms. They used to have computer labs, but the use of Chromebooks has eliminated the need for these labs. This year, maintenance removed old desks, cabinets and power poles from rooms 12 and 13. Both are now open and bright rooms that are flexible, learning classrooms. Room 11 is the last room to be modified so that we can use it for a classroom. The current condition makes it difficult to use. North Bullitt is requesting that maintenance perform the following modifications to Room 11. We would like to have the work done prior summer break. The room is currenlty not being used so access won't be an issue.

- 1. Remove the cabinets, wall shelves and sink. Cap existing plumbing and repair the wall and replace the floor tiles where necessary.
- 2. Remove the power poles and replace the needed ceiling tiles.
- 3. Build an insulated wall to create a short hallway in room 12. Currently, students going in and out of 11 have to walk through room 12. This is a disruption to student learning.

Thank you for your time and consideration.

Chris VerDow Principal

North Bullitt High School

3200 East Hebron Lane • Shepherdsville, KY 40165 Phone: (502) 869-6200 • Fax: (502) 957-6762