FIELD OBSERVATION REPORT 01



PCA ARCHITECTURE

TO:	Rob Haney Kenton County Schools	DATE:	10/22/21
	1055 Eaton Drive		
	Fort Wright, Ky 41017		
ATTENTION:			
FROM:	Jim Kaiser	■ PROJECT:	Addition & renovation to
	jkaiser@pca-arch.com		Ryland Heights Elementary
	1881 Dixie Highway, Suite 130		
	Ft. Wright, KY 41011		
COPIES TO:	Mr. Chad Atchley, Ms. Carrie Hooten	PROJECT NO.:	2021-001
■ WE TRANSMIT THE ATTACHED ITEMS VIA: EMAIL			
PURPOSE	☐ For your use	DISPOSITION	No exceptions noted
	☐ As requested		Exceptions noted,
	☐ For review and comment		Revise as indicated.
	☐ For information		REJECTED:
	☐ For record		REVISE AND RESUBMIT
	☐ For approval		
COPIES DATE DESCRIPTION PAGES			
1 10/	22/22 Field Observation Report 01		
■ REMARKS: Division 01: General Requirements 01.01: — Temporary construction wall has been constructed except at rear classroom wing. 01.02 — Modular classrooms have been relocated to opposite of gym.			
Division 02: Existing Conditions-Selective Demolition 02.01: - Ramp/walkway at former modular classrooms have been removed. 02.02 — New door opening at north side of cafeteria has been cut in and temporary gravel walkway has been installed. Additional waterproofing measures to prevent water infiltration into the cafeteria remain to be completed until the door can be installed.			
Division 03: Concrete 03.01: Drilled piers have been excavated and poured.			
Division 04: Masonry 04.01:			
Division 05: Metals 05.01:			
Division 06: Woods and Plastics 06.01:			

Division 08: Doors and Windows

07.01:

Division 07: Thermal and Moisture Protection

08.01:

Division 09: Finishes

09.01:

Division 10: Specialties

10.01:

Division 11: Equipment

11.01

Division 12: Furnishings

12.01:

Division 14: Conveying Systems

14.01:

Division 20-28: MEP

20-28.01: - Gas line servicing the kitchen was cut during drilling for piers. Temporary propane service has been installed. Permanent resolution is in process, possibly to combine with gas service for boiler. Gas line for building still must be relocated around the addition.

20-28:02 – Electric service to rear classroom wing addition was cut on 10/14 during drilling for piers. Electric service repairs and relocation around remaining piers was completed on 10.16.

Division 31: Earthwork

31.01: - Site at rear stair/elevator addition has been cleared for new piers

Division 32: Exterior Improvements

32.01:

CONSTRUCTION PHOTOS



STAIR-ELEVATOR ADDITION
Drilled piers/rerouted electric service
Temporary propane tanks in background



STAIR/ELEVATOR ADDITION Drilled piers

☐ Please acknowledge receipt of transmitted items.

☐ Return transmitted items to PCA ARCHITECTURE PSC.

END