

Jefferson County Public Schools															
<i>Bid Tabulation</i>															
Event Name: Pump Parts (Various Types)															
Event ID: JCP5-8295															
Approval Date: December 5, 2023															
Date Bids Received: November 6, 2023															
Contract Period: January 18, 2024 through January 17, 2025															
Renewals: No renewal option															
Comments: Award status indicates an award															
Item Number	Item/Service	Description	Commodity Code	UOM	Quantity	Vendor Name	No Bid	Manufacturer / Provider	Manufacturer Part Number	Unit Bid Price	Total Price	Vendor Response Item Notes	Supplier Notes	Award Status	Award Notes
1	Bearing assembly. Armstrong #810119MF-001 or Bell & Gossett #189034LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661925	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 189034LF	\$122.0000	\$122.0000			Awarded	
1	Bearing assembly. Armstrong #810119MF-001 or Bell & Gossett #189034LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661925	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 189034LF	\$144.4800	\$144.4800				
1	Bearing assembly. Armstrong #810119MF-001 or Bell & Gossett #189034LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661925	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 818254-003K	\$144.5700	\$144.5700				
2	Bearing assembly. Armstrong #818404K-000K or Bell & Gossett #189105LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661927	1 Each Purchase	1	CAPP INC	No	ARMSTRONG	ARMSTRONG 818404-000K	\$268.0000	\$268.0000			Awarded	
2	Bearing assembly. Armstrong #818404K-000K or Bell & Gossett #189105LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661927	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 818404-000K	\$280.3800	\$280.3800				
2	Bearing assembly. Armstrong #818404K-000K or Bell & Gossett #189105LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661927	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 189105LF	\$376.3200	\$376.3200				
3	Bearing assembly. Armstrong #818504-000K or Bell & Gossett #186863LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1665742	1 Each Purchase	1	CAPP INC	No	ARMSTRONG	ARMSTRONG 818504-000K	\$359.0000	\$359.0000			Awarded	
3	Bearing assembly. Armstrong #818504-000K or Bell & Gossett #186863LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1665742	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 818504-000K	\$375.1200	\$375.1200				
3	Bearing assembly. Armstrong #818504-000K or Bell & Gossett #186863LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1665742	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 186863LF	\$557.7600	\$557.7600				
4	Bearing assembly. Armstrong #816549MF-091 or Bell & Gossett #189163LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661926	1 Each Purchase	1	CAPP INC	No	ARMSTRONG	ARMSTRONG 816549MF-091	\$213.0000	\$213.0000			Awarded	
4	Bearing assembly. Armstrong #816549MF-091 or Bell & Gossett #189163LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661926	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 816549-091	\$222.3300	\$222.3300				
4	Bearing assembly. Armstrong #816549MF-091 or Bell & Gossett #189163LF.	Must be bronze fitted. NO SUBSTITUTE.	6200050-1661926	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 189163LF	\$292.3200	\$292.3200				
5	Coupler assembly, 1/2" x 1/2" spring type. Armstrong #810120-003 or Bell & Gossett #118473.	NO SUBSTITUTE.	6200300-1404797	1 Each Purchase	2	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 118473	\$51.0000	\$102.0000			Awarded	
5	Coupler assembly, 1/2" x 1/2" spring type. Armstrong #810120-003 or Bell & Gossett #118473.	NO SUBSTITUTE.	6200300-1404797	1 Each Purchase	2	Masters Supply	No	Bell & Gossett	Bell & Gossett 118473	\$60.4800	\$120.9600				
5	Coupler assembly, 1/2" x 1/2" spring type. Armstrong #810120-003 or Bell & Gossett #118473.	NO SUBSTITUTE.	6200300-1404797	1 Each Purchase	2	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 810120-003	\$84.2400	\$168.4800				
6	Coupler assembly, 1/2" x 1/2". Armstrong #806026-001 or Bell & Gossett #118723.	NO SUBSTITUTE.	6200300-1407169	1 Each Purchase	3	CAPP INC	No	ARMSTRONG	ARMSTRONG 806026-001K	\$27.0000	\$81.0000			Awarded	
6	Coupler assembly, 1/2" x 1/2". Armstrong #806026-001 or Bell & Gossett #118723.	NO SUBSTITUTE.	6200300-1407169	1 Each Purchase	3	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 806026-001K	\$28.2700	\$84.8100				

6	Coupler assembly, 1/2" x 1/2". Armstrong #806026-001 or Bell & Gossett #118723.	NO SUBSTITUTE.	6200300-1407169	1 Each Purchase	3	Masters Supply	No	Bell & Gossett	Bell & Gossett 118723	\$39.6000	\$118.8000				
7	Coupler assembly, 5/8" x 1/2". Armstrong #810120-006 or Bell & Gossett #118709.	NO SUBSTITUTE.	6200300-1495798	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 118709	\$58.0000	\$58.0000				Awarded
7	Coupler assembly, 5/8" x 1/2". Armstrong #810120-006 or Bell & Gossett #118709.	NO SUBSTITUTE.	6200300-1495798	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 118709	\$68.3200	\$68.3200				
7	Coupler assembly, 5/8" x 1/2". Armstrong #810120-006 or Bell & Gossett #118709.	NO SUBSTITUTE.	6200300-1495798	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 810120-006	\$70.3900	\$70.3900				
8	Gasket, for Bearing Assembly #818504-000K. Armstrong #106158-000 or Bell & Gossett #P57410.	NO SUBSTITUTE.	4510400-2010898	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT P57410	\$2.6000	\$2.6000				Awarded
8	Gasket, for Bearing Assembly #818504-000K. Armstrong #106158-000 or Bell & Gossett #P57410.	NO SUBSTITUTE.	4510400-2010898	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 118373	\$3.3600	\$3.3600				
8	Gasket, for Bearing Assembly #818504-000K. Armstrong #106158-000 or Bell & Gossett #P57410.	NO SUBSTITUTE.	4510400-2010898	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 818504-000K	\$375.1200	\$375.1200				
9	Gasket Kit, Flange. Armstrong #804034-000 or Bell & Gossett #118373.	NO SUBSTITUTE.	4510380-1726156	1 Each Purchase	1	CAPP INC	No	ARMSTRONG	ARMSTRONG 804034-000	\$8.0000	\$8.0000				Awarded
9	Gasket Kit, Flange. Armstrong #804034-000 or Bell & Gossett #118373.	NO SUBSTITUTE.	4510380-1726156	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 804034-000	\$8.3100	\$8.3100				
9	Gasket Kit, Flange. Armstrong #804034-000 or Bell & Gossett #118373.	NO SUBSTITUTE.	4510380-1726156	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 118373	\$17.9200	\$17.9200				
10	Gasket, Pump. Armstrong #106592-000.	NO SUBSTITUTE.	4510400-1716748	1 Each Purchase	1	Masters Supply	Yes								
10	Gasket, Pump. Armstrong #106592-000.	NO SUBSTITUTE.	4510400-1716748	1 Each Purchase	1	CAPP INC	No	ARMSTRONG	ARMSTRONG 106592-000	\$4.7500	\$4.7500				Awarded
10	Gasket, Pump. Armstrong #106592-000.	NO SUBSTITUTE.	4510400-1716748	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 106592-000	\$5.2400	\$5.2400				
11	Impeller. Armstrong #812961-041 or Bell & Gossett #1184311F.	NO SUBSTITUTE.	6200500-1020184	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 1184311F	\$57.0000	\$57.0000				Awarded
11	Impeller. Armstrong #812961-041 or Bell & Gossett #1184311F.	NO SUBSTITUTE.	6200500-1020184	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 1184311F	\$67.2000	\$67.2000				
11	Impeller. Armstrong #812961-041 or Bell & Gossett #1184311F.	NO SUBSTITUTE.	6200500-1020184	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 812961-041	\$80.7800	\$80.7800				
12	Impeller. Armstrong #816556-041 or Bell & Gossett #1184361F.	NO SUBSTITUTE.	6200500-1020077	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 1184361F	\$139.0000	\$139.0000				Awarded
12	Impeller. Armstrong #816556-041 or Bell & Gossett #1184361F.	NO SUBSTITUTE.	6200500-1020077	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 1184361F	\$164.6400	\$164.6400				
12	Impeller. Armstrong #816556-041 or Bell & Gossett #1184361F.	NO SUBSTITUTE.	6200500-1020077	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 816556-041	\$171.1900	\$171.1900				
13	Impeller. Armstrong #816301-055 or Bell & Gossett #1186121F.	NO SUBSTITUTE.	6200500-1020040	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 118612	\$300.0000	\$300.0000				Awarded
13	Impeller. Armstrong #816301-055 or Bell & Gossett #1186121F.	NO SUBSTITUTE.	6200500-1020040	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 1186121F	\$356.1600	\$356.1600				

13	Impeller. Armstrong #816301-055 or Bell & Gossett #118612LF.	NO SUBSTITUTE.	6200500-1020040	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 816301-055	\$778.7100	\$778.7100				
14	Impeller. Armstrong #816302-047 or Bell & Gossett #186359LF.	NO SUBSTITUTE.	6200500-1662597	1 Each Purchase	1	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 186359	\$323.0000	\$323.0000			Awarded	
14	Impeller. Armstrong #816302-047 or Bell & Gossett #186359LF.	NO SUBSTITUTE.	6200500-1662597	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 816302-047K	\$368.5600	\$368.5600				
14	Impeller. Armstrong #816302-047 or Bell & Gossett #186359LF.	NO SUBSTITUTE.	6200500-1662597	1 Each Purchase	1	Masters Supply	No	Bell & Gossett	Bell & Gossett 186359LF	\$383.0400	\$383.0400				
15	Seal kit. Armstrong #825458-001 or Bell & Gossett #186862LF.	NO SUBSTITUTE.	4510880-1311799	1 Each Purchase	2	Masters Supply	Yes								
15	Seal kit. Armstrong #825458-001 or Bell & Gossett #186862LF.	NO SUBSTITUTE.	4510880-1311799	1 Each Purchase	2	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 825458-001	\$147.8600	\$295.7200			Awarded	
15	Seal kit. Armstrong #825458-001 or Bell & Gossett #186862LF.	NO SUBSTITUTE.	4510880-1311799	1 Each Purchase	2	CAPP INC	No	BELL & GOSSETT	BELL & GOSSETT 186862LF	\$181.0000	\$362.0000				
16	Sleeve, shaft. Armstrong #810150-251.	NO SUBSTITUTE.	6200300-2000708	1 Each Purchase	1	Masters Supply	Yes								
16	Sleeve, shaft. Armstrong #810150-251.	NO SUBSTITUTE.	6200300-2000708	1 Each Purchase	1	CAPP INC	No	ARMSTRONG	ARMSTRONG 810150-251	\$243.0000	\$243.0000			Awarded	
16	Sleeve, shaft. Armstrong #810150-251.	NO SUBSTITUTE.	6200300-2000708	1 Each Purchase	1	Plumbers Supply Co. Inc.	No	ARMSTRONG	ARMSTRONG 810150-251	\$253.5500	\$253.5500				
17	Cartridge, Bearing. Taco #1600-160RP-2.	NO SUBSTITUTE.	6200650-1612544	1 Each Purchase	2	Plumbers Supply Co. Inc.	Yes								
17	Cartridge, Bearing. Taco #1600-160RP-2.	NO SUBSTITUTE.	6200650-1612544	1 Each Purchase	2	Bluegrass Hydronics & Pump	No	TACO	TACO 1600-160RP	\$489.0000	\$978.0000			Awarded	
17	Cartridge, Bearing. Taco #1600-160RP-2.	NO SUBSTITUTE.	6200650-1612544	1 Each Purchase	2	Masters Supply	No	Taco	Taco 1600-160RP-2	\$564.9600	\$1,129.9200				
17	Cartridge, Bearing. Taco #1600-160RP-2.	NO SUBSTITUTE.	6200650-1612544	1 Each Purchase	2	CAPP INC	No	TACO	TACO 1600-160RP-2	\$718.0000	\$1,436.0000				
18	Cartridge, Bearing. Taco #0011-010RP.	NO SUBSTITUTE.	6200650-2012215	1 Each Purchase	2	Plumbers Supply Co. Inc.	Yes								
18	Cartridge, Bearing. Taco #0011-010RP.	NO SUBSTITUTE.	6200650-2012215	1 Each Purchase	2	CAPP INC	No	TACO	TACO 0011-010RP	\$274.0000	\$548.0000			Awarded	
18	Cartridge, Bearing. Taco #0011-010RP.	NO SUBSTITUTE.	6200650-2012215	1 Each Purchase	2	Bluegrass Hydronics & Pump	No	TACO	TACO 0011-010RP	\$276.0000	\$552.0000				
18	Cartridge, Bearing. Taco #0011-010RP.	NO SUBSTITUTE.	6200650-2012215	1 Each Purchase	2	Masters Supply	No	Taco	Taco 0011-010RP	\$302.2900	\$604.5800				
19	Flange Kit, 3/4". Taco #110-251SF.	NO SUBSTITUTE.	6200650-2011632	1 Each Purchase	1	Plumbers Supply Co. Inc.	Yes								
19	Flange Kit, 3/4". Taco #110-251SF.	NO SUBSTITUTE.	6200650-2011632	1 Each Purchase	1	Masters Supply	No	Taco	Taco 110-251SF	\$46.7700	\$46.7700			Awarded	
19	Flange Kit, 3/4". Taco #110-251SF.	NO SUBSTITUTE.	6200650-2011632	1 Each Purchase	1	CAPP INC	No	TACO	TACO 110-251SF	\$53.0000	\$53.0000				

19	Flange Kit, 3/4". Taco #110-251SF.	NO SUBSTITUTE.	6200650-2011632	1 Each Purchase	1	Bluegrass Hydronics & Pump	No	TACO	TACO 110-251SF	\$73.0000	\$73.0000					
20	Flange Kit, 1". Taco #110-252SF.	NO SUBSTITUTE.	6200650-2011631	1 Each Purchase	3	Plumbers Supply Co. Inc.	Yes									
20	Flange Kit, 1". Taco #110-252SF.	NO SUBSTITUTE.	6200650-2011631	1 Each Purchase	3	Masters Supply	No	Taco	Taco 110-252SF	\$46.7700	\$140.3100				Awarded	
20	Flange Kit, 1". Taco #110-252SF.	NO SUBSTITUTE.	6200650-2011631	1 Each Purchase	3	CAPP INC	No	TACO	TACO 110-252SF	\$53.0000	\$159.0000					
20	Flange Kit, 1". Taco #110-252SF.	NO SUBSTITUTE.	6200650-2011631	1 Each Purchase	3	Bluegrass Hydronics & Pump	No	TACO	TACO 110-252SF	\$73.0000	\$219.0000					
21	Motor, 1/2 HP, 1725 RPM, 115/230 volt, 48 Frame. Taco #132-096RP.	NO SUBSTITUTE.	6100002-1728641	1 Each Purchase	1	Plumbers Supply Co. Inc.	Yes									
21	Motor, 1/2 HP, 1725 RPM, 115/230 volt, 48 Frame. Taco #132-096RP.	NO SUBSTITUTE.	6100002-1728641	1 Each Purchase	1	CAPP INC	Yes									
21	Motor, 1/2 HP, 1725 RPM, 115/230 volt, 48 Frame. Taco #132-096RP.	NO SUBSTITUTE.	6100002-1728641	1 Each Purchase	1	Bluegrass Hydronics & Pump	No	TACO	TACO 132-096RP	\$583.0000	\$583.0000				Awarded	
21	Motor, 1/2 HP, 1725 RPM, 115/230 volt, 48 Frame. Taco #132-096RP.	NO SUBSTITUTE.	6100002-1728641	1 Each Purchase	1	Masters Supply	No	Taco	Taco 132-096RP	\$680.1600	\$680.1600					
22	Pump, Lead Free Stainless Steel. Taco #007-SF5.	NO SUBSTITUTE.	6225550-1721801	1 Each Purchase	2	Plumbers Supply Co. Inc.	Yes									
22	Pump, Lead Free Stainless Steel. Taco #007-SF5.	NO SUBSTITUTE.	6225550-1721801	1 Each Purchase	2	Masters Supply	No	Taco	Taco 007-SF5	\$340.1000	\$680.2000				Awarded	
22	Pump, Lead Free Stainless Steel. Taco #007-SF5.	NO SUBSTITUTE.	6225550-1721801	1 Each Purchase	2	Bluegrass Hydronics & Pump	No	TACO	TACO 007-SF5	\$406.0000	\$812.0000					
22	Pump, Lead Free Stainless Steel. Taco #007-SF5.	NO SUBSTITUTE.	6225550-1721801	1 Each Purchase	2	CAPP INC	No	TACO	TACO 007-SF5	\$475.0000	\$950.0000					
23	Pump, Circulating Lead Free Stainless Steel. Taco #0011-SF4.	NO SUBSTITUTE.	6225550-2011629	1 Each Purchase	6	Plumbers Supply Co. Inc.	Yes									
23	Pump, Circulating Lead Free Stainless Steel. Taco #0011-SF4.	NO SUBSTITUTE.	6225550-2011629	1 Each Purchase	6	Bluegrass Hydronics & Pump	No	TACO	TACO 0011-SF4	\$556.0000	\$3,336.0000				Awarded	
23	Pump, Circulating Lead Free Stainless Steel. Taco #0011-SF4.	NO SUBSTITUTE.	6225550-2011629	1 Each Purchase	6	Masters Supply	No	Taco	Taco 0011-SF4	\$613.4700	\$3,680.8200					
23	Pump, Circulating Lead Free Stainless Steel. Taco #0011-SF4.	NO SUBSTITUTE.	6225550-2011629	1 Each Purchase	6	CAPP INC	No	TACO	TACO 0011-SF4	\$665.0000	\$3,990.0000					
24	Pump, Circulating Lead Free Stainless Steel. Taco #0013-SF3.	NO SUBSTITUTE.	6225550-2012810	1 Each Purchase	6	Plumbers Supply Co. Inc.	Yes									
24	Pump, Circulating Lead Free Stainless Steel. Taco #0013-SF3.	NO SUBSTITUTE.	6225550-2012810	1 Each Purchase	6	Masters Supply	No	Taco	Taco 0013-SF3	\$542.6800	\$3,256.0800				Awarded	
24	Pump, Circulating Lead Free Stainless Steel. Taco #0013-SF3.	NO SUBSTITUTE.	6225550-2012810	1 Each Purchase	6	Bluegrass Hydronics & Pump	No	TACO	TACO 0013-SF3	\$619.0000	\$3,714.0000					
24	Pump, Circulating Lead Free Stainless Steel. Taco #0013-SF3.	NO SUBSTITUTE.	6225550-2012810	1 Each Purchase	6	CAPP INC	No	TACO	TACO 0013-SF3	\$740.0000	\$4,440.0000					

Award Totals		
Vendor	Bid Amount	Award Amount
Bluegrass Hydronics & Pump	\$11,612.00	\$6,139.00
CAPP INC	\$16,207.35	\$2,828.35
Masters Supply	\$14,399.46	\$4,222.96
Plumbers Supply Co. Inc.	\$3,683.26	\$295.72