## **FACPAC Contract Change Order Supplemental Information Form (Ref#** 62570)

Form Status: Saved

Tier 1 Project: New Child Nutrition Facility

BG Number: 23-070

District: Hardin County (HB678) (231)

Status: Active

Phase: Project Initiation (View Checklist)

Contract: Wehr Constructors, Inc., 0030, Concrete Type: CM Bid Package

Proposed

Change Order Number

Time Extension Required

No

Date Of Change Order

6/12/2025

Change Order Amount To Date

## **Construction Contingency**

Calculations below are project wide. Remaining negative Construction Contingency may require the submission of a revised BG1.

**Current Approved Amount** 

\$442,000.00

Net Approved COs

\$0.00

Remaining After Approved COs

\$442,000.00

Net All COs

\$6,459.09

Remaining After All COs

\$435,540.91

This Requested Change Order Amount \$10,673.94

Change In A/E Fee This Change Order

+/-

Change In CM Fee This Change Order \$1,601.09

+/-

Remaining Construction Contingency

Balance

Contract Change Requested By

Construction Manager

Contract Change Reason Code

**Found Condition** 

Change Order Description And Justification

Unsuitable soils found in the preparation for installation of new dock walls in front of the building and grounds building. Overexcavation and backfill with flowable fill required by owner special inspector. 46 yards at a unit price of 197.80 plus bond, insurance, and fee.

Cost Benefit To Owner

Contract unit prices have been utilized Yes to support the cost associated with this change order.

## **Detailed Cost Breakdown**

Contract unit prices have not been utilized, provide a detailed cost breakdown which separates labor, material, profit and overhead.

|                       |             | The state of the s |
|-----------------------|-------------|--|
| Detail Item           | Amount      | Percent of Total   |
| Labor                 | \$9,098.80  | 85.24%   |
| Materials             |             | 0.00%  |
| Profit and Overhead   | \$1,392.25  | 13.04%   |
| Bond Insurance        | \$182.89    | 1.71%  |
| Cost Breakdown Total: | \$10,673.94 |  |

Cost for this Change Order supported No by an alternate bid or competitive price quote

Explain Why

This is a unit price number from the bid.

Attachments

25-117 Hardin Co. FSC 250602 R,C.pdf

Unsuitable Soils.pdf

## Change Order Supplemental Information Form Signature Page (Online Form Ref# 62570)

Architect Date Construction Manager Finance Officer Date Local Board of Education Designee Date