

## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 1999 District: Nelson County  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Vehicle Identification Number (VIN): 1HVBBAAL3XH217596  
☒ International  
\_\_\_\_ Other List Passenger Capacity: 20

Body Type: Tire Sizes: Tire Quality (Check One):  
\_\_\_\_ Ward Good Fair Poor  
\_\_\_\_ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
\_\_\_\_ Carpenter  
☒ Other Amtran Rear: 265/75R22.5 ☐ ☒ ☐

Engine Type: Bus Mileage: 250629  
\_\_\_\_ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 9902  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet  
☒ International Bus Operating Condition:  
\_\_\_\_ Other ☒ Operable  
\_\_\_\_ ☐ Inoperable

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None  
Explain:

Dents in Roof

List any mechanical defects you are currently aware of the drivetrain: ☒ None  
Explain:

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 2000 District: Nelson County  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Vehicle Identification Number (VIN): 1HVBBAAN6YH323897  
☒ International  
\_\_\_\_ Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: Tire Sizes: Tire Quality (Check One):  
\_\_\_\_ Ward Good Fair Poor  
\_\_\_\_ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
\_\_\_\_ Carpenter Rear: 265/75R22.5 ☐ ☒ ☐  
☒ Other Amtran

Engine Type: Bus Mileage: 272987  
\_\_\_\_ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 2047  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Bus Operating Condition:  
☒ Operable  
☐ Inoperable  
☒ International  
\_\_\_\_ Other \_\_\_\_\_

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:  
Explain:

☒ None

List any mechanical defects you are currently aware of the drivetrain:  
Explain:

☒ None

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 2000 District: Nelson County  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Vehicle Identification Number (VIN): 1HVBBAAN84H323898  
☒ International  
\_\_\_\_ Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: Tire Sizes: Tire Quality (Check One):  
\_\_\_\_ Ward Good Fair Poor  
\_\_\_\_ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
\_\_\_\_ Carpenter Rear: 265/75R22.5 ☐ ☒ ☐  
☒ Other Amtran

Engine Type: Bus Mileage: 199250  
\_\_\_\_ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 2048  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Bus Operating Condition:  
☒ Operable  
☐ Inoperable  
☒ International  
\_\_\_\_ Other \_\_\_\_\_

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:  
Explain:

☒ None

List any mechanical defects you are currently aware of the drivetrain:  
Explain:

☒ None

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 2000 District: Nelson County  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Vehicle Identification Number (VIN): 1HVBBAANXYH323899  
☒ International  
\_\_\_\_ Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: Tire Sizes: Tire Quality (Check One):  
\_\_\_\_ Ward Good Fair Poor  
\_\_\_\_ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
\_\_\_\_ Carpenter Rear: 265/75R22.5 ☐ ☒ ☐  
☒ Other Amtran

Engine Type: Bus Mileage: 190717  
\_\_\_\_ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 2049  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Bus Operating Condition:  
☒ Operable  
☐ Inoperable  
☒ International  
\_\_\_\_ Other \_\_\_\_\_

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:  
Explain: \_\_\_\_\_

☒ None

List any mechanical defects you are currently aware of the drivetrain:  
Explain: \_\_\_\_\_

☒ None

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.



## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 2000 District: Nelson County  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Vehicle Identification Number (VIN): 1HVBBAANXYH323900  
☒ International  
\_\_\_\_ Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: Tire Sizes: Tire Quality (Check One):  
\_\_\_\_ Ward Good Fair Poor  
\_\_\_\_ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
\_\_\_\_ Carpenter Rear: 265/75R22.5 ☐ ☒ ☐  
☒ Other Amtran

Engine Type: Bus Mileage: 224775  
\_\_\_\_ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 2050  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet  
☒ International Bus Operating Condition:  
\_\_\_\_ Other \_\_\_\_\_ ☒ Operable  
\_\_\_\_ Inoperable

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 \_\_\_\_\_ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None  
Explain: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

List any mechanical defects you are currently aware of the drivetrain: ☒ None  
Explain: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 2000 District: Nelson County  
☐ Ford  
☐ Chevrolet Vehicle Identification Number (VIN): 1HVBBAAN3YA930415  
☒ International  
☐ Other \_\_\_\_\_ Passenger Capacity: 78

Body Type: Tire Sizes: Tire Quality (Check One):  
☐ Ward Good Fair Poor  
☐ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
☐ Carpenter Rear: 265/75R22.5 ☐ ☒ ☐  
☒ Other Amtran

Engine Type: Bus Mileage: 192600  
☐ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 2051  
☐ Ford  
☐ Chevrolet  
☒ International Bus Operating Condition:  
☒ Operable  
☐ Inoperable  
☐ Other \_\_\_\_\_

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None

Explain:

Dents in Roof (minor)

List any mechanical defects you are currently aware of the drivetrain: ☒ None

Explain:

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2017 Used School Bus Inventory Form

Model: Year: 2000 District: Nelson County  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Vehicle Identification Number (VIN): 1HVBGAANSY93D416  
☒ International  
\_\_\_\_ Other \_\_\_\_\_ Passenger Capacity: 78

Body Type: Tire Sizes: Tire Quality (Check One):  
\_\_\_\_ Ward Good Fair Poor  
\_\_\_\_ Blue Bird Front: 265/75R22.5 ☐ ☒ ☐  
\_\_\_\_ Carpenter Rear: 265/75R22.5 ☐ ☒ ☐  
☒ Other Amtran

Engine Type: Bus Mileage: 238800  
\_\_\_\_ Gasoline  
☒ Diesel

Engine Make: Brake Type: AIR Bus Side Number: 2052  
\_\_\_\_ Ford  
\_\_\_\_ Chevrolet Bus Operating Condition:  
☒ Operable  
☐ Inoperable  
☒ International  
\_\_\_\_ Other \_\_\_\_\_

Engine Size: Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): 466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None  
Explain: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

List any mechanical defects you are currently aware of the drivetrain: ☒ None  
Explain: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

This bus can be inspected by calling:

Name: JEFF MARCHESI

Telephone: (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.