FIELD OBSERVATION REPORT

2018-09 (Twenhofel)

District se 1
se 1
Т
AGES
3

Division 01: General Requirements

01.01: 2018.09.10 - A punchlist was issued to the contractor.

Division 02: Existing Conditions

02.01: 2018.09.17 – The contractor needs to restore the fence at the upper temporary access to Taylor Mill Road.

02.02: 2018.09.17 – Several small piles of debris were observed and will need to be removed from the site.

Division 31: Earthwork


31.01: 2018.09.17 – Seeded areas had substantially germinated, with the exception of surface/diversion drains which had their seed washed away in recent rain events.

Division 32: Exterior Improvements

32.01: 2018.09.17 - Surface course of asphalt had been installed and parking areas were striped.

CONSTRUCTION PHOTOS





2018.09.17 - View towards upper temporary access.



2018.09.17 - Debris to be removed.



2018.09.17 - Grass growing on former building site.



 $2018.09.17-Grass\ growing\ on\ former\ building\ site.$



2018.09.17 - Upper parking lot.



2018.09.17 - Walk from parking to bus lot.

PCA ARCHITECTURE







2018.09.17 - Grass growing on former building site.

END

[☐] Please acknowledge receipt of transmitted items.

 $^{\ \}square$ Return transmitted items to PCA ARCHITECTURE PSC.