

## KISTA - 2019 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 2001 District: Simpson Co  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet Vehicle Identification Number (VIN): 1HBVGAA114912842  
☒ International  
\_\_\_\_\_  
Other \_\_\_\_\_ Passenger Capacity: 74

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward \_\_\_\_\_ Good ☒ Fair ☐ Poor ☐  
\_\_\_\_\_  
Blue Bird Front: 22.5  
\_\_\_\_\_  
Carpenter \_\_\_\_\_  
☒ Other International Rear: 22.5 ☒ ☐ ☐

Engine Type: \_\_\_\_\_ Bus Mileage: 180651  
\_\_\_\_\_  
Gasoline  
☒ Diesel

Engine Make: Brake Type: Air Bus Side Number: 2301  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
International  
☒ Other Max Force Bus Operating Condition:  
\_\_\_\_\_  
☒ Operable  
\_\_\_\_\_  
☐ Inoperable

Engine Size: \_\_\_\_\_ Transmission Type: \_\_\_\_\_  
Number Cylinders: 6 Cylinder ☒ Automatic  
Size (Cubic Inches or Liters): 13 Liter \_\_\_\_\_  
\_\_\_\_\_  
Standard

**Check the statement which generally best describes this bus unit:**

- ☒ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:  
Explain: \_\_\_\_\_

☒ None

List any mechanical defects you are currently aware of the drivetrain:  
Explain: \_\_\_\_\_

☒ None

**This bus can be inspected by calling:**

Name: Steven

Telephone: 220 586-3757

**PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.**

**If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.**

## KISTA - 2019 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 2004 District: Simpson Co  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet Vehicle Identification Number (VIN) 1T88T3C2241137545  
\_\_\_\_\_  
International  
☒ Other Thomas Passenger Capacity: 74

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward \_\_\_\_\_ Good ☐ Fair ☐ Poor  
\_\_\_\_\_  
Blue Bird Front: 22.5 ☒ ☐ ☐  
\_\_\_\_\_  
Carpenter Rear: 22.5 ☒ ☐ ☐  
☒ Other Thomas

Engine Type: \_\_\_\_\_ Bus Mileage: 173689  
☒ Gasoline  
☒ Diesel

Engine Make: Brake Type: Air Bus Side Number: 2904  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
International  
☒ Other Caterpillar Bus Operating Condition:  
\_\_\_\_\_  
Operable  
☒ Inoperable

Engine Size: \_\_\_\_\_ Transmission Type: \_\_\_\_\_  
Number Cylinders: 6 cylinder ☒ Automatic  
Size (Cubic Inches or Liters): 7.2 Liter \_\_\_\_\_ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☒ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:  
Explain: \_\_\_\_\_

☒ None

List any mechanical defects you are currently aware of the drivetrain: ☐ None  
Explain: \_\_\_\_\_

Needs a Hvi pump and it  
has been used for parts.

This bus can be inspected by calling:

Name: Steven

Telephone: (270) 586-3757

**PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.**

**If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.**

## KISTA - 2019 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 2005 District: Simpson CO  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet Vehicle Identification Number (VIN): 4DRBVAAARX6A186450  
☒ International  
\_\_\_\_\_  
Other \_\_\_\_\_ Passenger Capacity: 74

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward Good Fair Poor  
\_\_\_\_\_  
Blue Bird Front: 22.5 ☒ ☐ ☐  
\_\_\_\_\_  
Carpenter Rear: 22.5 ☒ ☐ ☐  
☒ Other International

Engine Type: \_\_\_\_\_ Bus Mileage: 152267  
\_\_\_\_\_  
Gasoline  
☒ Diesel

Engine Make: Brake Type: Air Bus Side Number: 3305  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
International  
☒ Other Max Force Bus Operating Condition:  
\_\_\_\_\_  
Operable  
\_\_\_\_\_  
Inoperable

Engine Size: \_\_\_\_\_ Transmission Type: \_\_\_\_\_  
Number Cylinders: 6 cylinder ☒ Automatic  
Size (Cubic Inches or Liters): 13 liter \_\_\_\_\_  
Standard

**Check the statement which generally best describes this bus unit:**

- ☒ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:

☒ None

Explain:

List any mechanical defects you are currently aware of the drivetrain:

☐ None

Explain:

Front oil cover leaks some.  
push Button Shift Selector IS going Bad.

This bus can be inspected by calling:

Name: Steven

Telephone: 220 586-3757

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.