

KISTA - 2019 Used School Bus Inventory Form

Model: _____ Year: 1996 District: Hopkins County

Ford

Chevrolet Vehicle Identification Number (VIN): 1HYBBAAN7TH378772
☒ International

Other _____ Passenger Capacity: 66

Body Type: _____ Tire Sizes: _____ Tire Quality (Check One):

Ward _____ Good ☐ Fair ☒ Poor ☐

Blue Bird Front: 265/80 22.5 ☐ ☒ ☐

Carpenter _____

Other TH Rear: 255/80 22.5 ☐ ☒ ☐

Engine Type: _____ Bus Mileage: 200,931

Gasoline
☒ Diesel

Engine Make: Brake Type: Air Brakes Bus Side Number: 251

Ford

Chevrolet
☒ International Bus Operating Condition:

Other _____ ☒ Operable

Inoperable

Engine Size: _____ Transmission Type:
Number Cylinders: 6 ☒ Automatic
Size (Cubic Inches or Liters): DT 466 _____
Standard

Check the statement which generally best describes this bus unit:

- ☒ Bus is well maintained and is in good operating condition.
- ☐ Bus is well maintained and is in fair operating condition.
- ☐ Bus is well maintained, but is in poor operating condition.
- ☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None
Explain: _____

List any mechanical defects you are currently aware of the drivetrain: ☒ None
Explain: _____

This bus can be inspected by calling:

Name: David Durham

Telephone: (270) 825-6151

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

KISTA - 2019 Used School Bus Inventory Form

Model: _____ Year: 2001 District: Hopkins County

☒ Other F365 Passenger Capacity: 66

Body Type: _____ Tire Sizes: _____ Tire Quality (Check One):

☒ Other Thomas Front: 255/80 R22.5 Good Fair Poor
Rear: 255/80 R22.5 ☐ ☒ ☐

Engine Type: _____ Bus Mileage: 276,047

☒ Diesel

Engine Make: Brake Type: Air Brake Bus Side Number: 261

☒ Other Cat Bus Operating Condition:
☒ Operable
☐ Inoperable

Engine Size: _____ Transmission Type: _____
Number Cylinders: 6 ☒ Automatic
Size (Cubic Inches or Liters): Cat 3126 ☐ Standard

Check the statement which generally best describes this bus unit:

- ☒ Bus is well maintained and is in good operating condition.
☐ Bus is well maintained and is in fair operating condition.
☐ Bus is well maintained, but is in poor operating condition.
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None
Explain: _____

List any mechanical defects you are currently aware of the drivetrain: ☒ None
Explain: _____

This bus can be inspected by calling:

Name: DAVID DURHAM

Telephone: 270 825-6151

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

KISTA - 2019 Used School Bus Inventory Form

Model: Year: 2004 District: Hopkins County
☐ Ford
☐ Chevrolet Vehicle Identification Number (VIN): 4U2AAXK24CM17453
☐ International
☒ Other F365 Passenger Capacity: 66

Body Type: Tire Sizes: Tire Quality (Check One):
☐ Ward
☐ Blue Bird Front: 255/80 R22.5 ☒ Good ☐ Fair ☐ Poor
☐ Carpenter
☒ Other Thomas Rear: 255/80 R22.5 ☐ ☒ ☐

Engine Type: Bus Mileage: 167,016
☐ Gasoline
☒ Diesel

Engine Make: Brake Type: Air Brakes Bus Side Number: 307
☐ Ford
☐ Chevrolet Bus Operating Condition:
☒ Operable
☐ Inoperable
☒ Other Cat

Engine Size: Transmission Type:
Number Cylinders: 6 ☒ Automatic
Size (Cubic Inches or Liters): Cat 3126 ☐ Standard

Check the statement which generally best describes this bus unit:

- ☐ Bus is well maintained and is in good operating condition.
☒ Bus is well maintained and is in fair operating condition.
☐ Bus is well maintained, but is in poor operating condition.
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None
Explain:

List any mechanical defects you are currently aware of the drivetrain: ☐ None
Explain:

Bus Hard Start, Has Blow By, TRANSMISSION Good

This bus can be inspected by calling:

Name: DAVID DURHAM

Telephone: (270) 825-6151

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

KISTA - 2019 Used School Bus Inventory Form

Model: _____ Year: 2006 District: Hopkins County

Ford

Chevrolet Vehicle Identification Number (VIN): 1T88R3C2661168198

International
☒ Other MVP-EF Passenger Capacity: 70

Body Type: _____ Tire Sizes: _____ Tire Quality (Check One):

Ward _____ Good ☐ Fair ☒ Poor ☐

Blue Bird Front: 275/80R 22.5 ☐ ☒ ☐

Carpenter Rear: 275/80 R 22.5 ☐ ☒ ☐
☒ Other Cat

Engine Type: _____ Bus Mileage: Around 150,000

Gasoline
☒ Diesel

Engine Make: Brake Type: Air Brakes Bus Side Number: 507

Ford

Chevrolet Bus Operating Condition:

International ☒ Operable
☒ Other Cat ☐ Inoperable

Engine Size: _____ Transmission Type: _____
Number Cylinders: 6 ☒ Automatic
Size (Cubic Inches or Liters): C7 ☐ Standard

Check the statement which generally best describes this bus unit:

- ☐ Bus is well maintained and is in good operating condition.
☒ Bus is well maintained and is in fair operating condition.
☐ Bus is well maintained, but is in poor operating condition.
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None
Explain: _____

List any mechanical defects you are currently aware of the drivetrain: ☐ None
Explain: _____
Bus has Transmission Problem
Bus has Hard Down Shift.

This bus can be inspected by calling:

Name: David Durham

Telephone: (270) 825-6151

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.