

## KISTA - 2020 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 1999 District: Hopkins County  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
International  
\_\_\_\_\_  
Other \_\_\_\_\_ Vehicle Identification Number (VIN): 1HVBBAAANXXH 221159  
\_\_\_\_\_  
Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward  
\_\_\_\_\_  
Blue Bird  
\_\_\_\_\_  
Carpenter  
\_\_\_\_\_  
Other Am Team Front: 255/80R22.5 ☒ Good ☐ Fair ☐ Poor  
Rear: 255/80R22.5 ☒ Good ☐ Fair ☐ Poor

Engine Type: \_\_\_\_\_ Bus Mileage: 147,738  
\_\_\_\_\_  
Gasoline  
\_\_\_\_\_  
Diesel

Engine Make: Brake Type: Air / Drums Bus Side Number: 256  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
International  
\_\_\_\_\_  
Other \_\_\_\_\_ Bus Operating Condition:  
\_\_\_\_\_  
Operable  
\_\_\_\_\_  
Inoperable

Engine Size: \_\_\_\_\_ Transmission Type: \_\_\_\_\_  
Number Cylinders: 6 \_\_\_\_\_  
Size (Cubic Inches or Liters): DT466E \_\_\_\_\_  
Automatic  
Standard

**Check the statement which generally best describes this bus unit:**

- ☒ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None  
Explain: \_\_\_\_\_

Normal Body Wear

List any mechanical defects you are currently aware of the drivetrain: ☒ None  
Explain: \_\_\_\_\_

Nothing

This bus can be inspected by calling:

Name: David Dueham

Telephone: (270) 825-6150

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2020 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 1999 District: Hopkins County  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet Vehicle Identification Number (VIN): 1HYBBAAN8XH 221161  
☒ International  
\_\_\_\_\_  
Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward \_\_\_\_\_ Good ☐ Fair ☒ Poor ☐  
\_\_\_\_\_  
Blue Bird Front: 255/80 22.5 ☐ ☒ ☐  
\_\_\_\_\_  
Carpenter Rear: 255/80 22.5 ☐ ☒ ☐  
☒ Other Am Team

Engine Type: \_\_\_\_\_ Bus Mileage: 196,441  
\_\_\_\_\_  
Gasoline  
☒ Diesel

Engine Make: Brake Type: Air / Drums Bus Side Number: 257  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
☒ International Bus Operating Condition:  
\_\_\_\_\_  
Other \_\_\_\_\_ ☒ Operable  
\_\_\_\_\_  
Inoperable

Engine Size: \_\_\_\_\_ Transmission Type: \_\_\_\_\_  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): DT466E \_\_\_\_\_  
Standard

**Check the statement which generally best describes this bus unit:**

- ☒ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None  
Explain: \_\_\_\_\_

Normal Body Wear

List any mechanical defects you are currently aware of the drivetrain: ☒ None  
Explain: \_\_\_\_\_

Nothing

This bus can be inspected by calling:

Name: David Durham

Telephone: (270) 825-6150

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2020 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 2001 District: Hopkins County  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet Vehicle Identification Number (VIN): 1HVBRAAN11A912561  
☒ International  
\_\_\_\_\_  
Other \_\_\_\_\_ Passenger Capacity: 66

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward \_\_\_\_\_ Good ☒ Fair ☐ Poor ☐  
\_\_\_\_\_  
Blue Bird Front: 255/80R22.5  
\_\_\_\_\_  
Carpenter \_\_\_\_\_  
☒ Other International Rear: 255/80R22.5 ☐ ☒ ☐

Engine Type: \_\_\_\_\_ Bus Mileage: 167,794  
\_\_\_\_\_  
Gasoline  
☒ Diesel

Engine Make: Brake Type: Air/Drums Bus Side Number: 266  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
☒ International Bus Operating Condition:  
\_\_\_\_\_  
Other \_\_\_\_\_ ☒ Operable  
\_\_\_\_\_  
Inoperable

Engine Size: \_\_\_\_\_ Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): DT466E \_\_\_\_\_  
Standard

Check the statement which generally best describes this bus unit:

- ☒ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None

Explain:

Very Little Dint on Right Rear Top Chence  
Normal Body Wear

List any mechanical defects you are currently aware of the drivetrain: ☒ None

Explain:

Nothing

This bus can be inspected by calling:

Name: David Durham

Telephone: (270) 825-6150

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

## KISTA - 2020 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 2005 District: Hopkins County  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
☒ Other Thomas Built Vehicle Identification Number (VIN): 1T88R3C2051152772  
Passenger Capacity: 70

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
☒ Other Thomas Front: 295/75R22.5 Good Fair Poor  
Rear: 295/75R22.5 ☒ ☐ ☐

Engine Type: \_\_\_\_\_ Bus Mileage: 215,017  
\_\_\_\_\_  
☒ Diesel

Engine Make: Brake Type: Air / Drums Bus Side Number: 402  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
☒ Other Catipillar Bus Operating Condition:  
\_\_\_\_\_  
\_\_\_\_\_ Operable  
\_\_\_\_\_ Inoperable

Engine Size: \_\_\_\_\_ Transmission Type: \_\_\_\_\_  
Number Cylinders: 6 \_\_\_\_\_ Automatic  
Size (Cubic Inches or Liters): Cat 47 \_\_\_\_\_ Standard

Check the statement which generally best describes this bus unit:

- ☒ Bus is well maintained and is in good operating condition.  
☐ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None  
Explain: \_\_\_\_\_

Normal Body Wear

List any mechanical defects you are currently aware of the drivetrain: ☐ None  
Explain: \_\_\_\_\_

Hard to start if Not Plugged up in the  
Winter.

This bus can be inspected by calling:

Name: David Doeham

Telephone: (270) 825-6150

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.

**If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.**

**If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.**