/*/\\

COM*check* Software Version 4.1.1.0

Interior Lighting Compliance Certificate

Project Information

Energy Code: 2012 IECC

Project Title: Elizabethtown High School Restroom Renovation

Project Type: Alteration

Construction Site: 620 N Mulberry St Elizabethtown, KY 42701 Owner/Agent:

Elizabethtown Independent School

District

620 N Mulberry St Elizabethtown, KY 42701 Designer/Contractor:

CMTA Inc

2429 Members Way Lexington, KY 40504

Page

1 of 6

Allowed Interior Lighting Power

A Area Category	B Floor Area (ft2)	C Allowed Watts / ft2	D Allowed Watts (B X C)
1-Common Space Types:Restroom	1934	1.00	1934
		Total Allowed Watts =	= 1934

Proposed Interior Lighting Power

A Fixture ID : Description / Lamp / Wattage Per Lamp / Ballast	B Lamps/ Fixture	C # of Fixtures	D Fixture Watt.	E (C X D)
Common Space Types:Restroom (1934 sq.ft.)				
A1: Other:	1	28	31	868
B1: Other:	1	2	29	58
B2: Other:	1	4	29	116
D2: Other:	1	8	19	152
EM6: Other:	1	17	3	51
		Total Propos	sed Watts =	1245

Interior Lighting PASSES

Interior Lighting Compliance Statement

Compliance Statement: The proposed interior lighting alteration project represented in this document is consistent with the building plans, specifications, and other calculations submitted with this permit application. The proposed interior lighting systems have been designed to meet the 2012 IECC requirements in COMcheck Version 4.1.1.0 and to comply with any applicable mandatory requirements listed in the Inspection Checklist.

Konstantin Levitsky	Konstantin Levitsky	9/14/21	
Name - Title	Signature	Date	

Project Title: Elizabethtown High School Restroom Renovation Report date: 09/14/21

Data filename: X:\Projects\XETR21\2. Design\11. ComCheck\etown electrical comcheck.cck

COM*check* Software Version 4.1.1.0 **Inspection Checklist**

Energy Code: 2012 IECC

Requirements: 100.0% were addressed directly in the COMcheck software

Text in the "Comments/Assumptions" column is provided by the user in the COMcheck Requirements screen. For each requirement, the user certifies that a code requirement will be met and how that is documented, or that an exception is being claimed. Where compliance is itemized in a separate table, a reference to that table is provided.

Section # & Req.ID	Plan Review	Complies?	Comments/Assumptions
C103.2 [PR4] ¹	Plans, specifications, and/or calculations provide all information with which compliance can be determined for the interior lighting and electrical systems and equipment and document where exceptions to the standard are claimed. Information provided should include interior lighting power calculations, wattage of bulbs and ballasts, transformers and control devices.	□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.

Additional Comments/Assumptions:

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Project Title: Elizabethtown High School Restroom Renovation Data filename: X:\Projects\XETR21\2. Design\11. ComCheck\etown electrical comcheck.cck

Page

2 of 6

Section # & Req.ID	Rough-In Electrical Inspection	Complies?	Comments/Assumptions
C405.2.2. 1 [EL22] ²	Automatic controls to shut off all building lighting installed in all buildings.	□Complies □Does Not	Exception: Lighting controlled by occupancy sensors.
		□Not Observable □Not Applicable	
C405.2.1. 1 [EL23] ²	Independent lighting controls installed per approved lighting plans and all manual controls readily accessible and	□Complies □Does Not	Requirement will be met.
	visible to occupants.	□Not Observable □Not Applicable	
C405.2.1. 2 [EL15] ¹	Lighting controls installed to uniformly reduce the lighting load by at least 50%.	□Complies □Does Not	Requirement will be met.
[ELI3]-	30%.	□Not Observable □Not Applicable	
C405.2.2.	individual controls that control the	□Complies □Does Not	Exception: Requirement does not apply.
[EL16] ²	lights independent of general area lighting.	□Not Observable □Not Applicable	
C405.2.3 [EL17] ³	master switch at the main entry door	□Complies □Does Not	Exception: Requirement does not apply.
	that controls wired luminaires and switched receptacles.	□Not Observable □Not Applicable	
C405.2.2. 2	Occupancy sensors installed in required spaces.	□Complies □Does Not	Requirement will be met.
[EL18] ¹		□Not Observable □Not Applicable	
C405.2.2.	Primary sidelighted areas are equipped with required lighting	□Complies □Does Not	Requirement will be met.
[EL20] ¹	controls.	□Not Observable □Not Applicable	
C405.2.2.	under skylights and rooftop monitors	□Complies □Does Not	Exception: Requirement does not apply.
[EL21] ¹	are equipped with required lighting controls.	□Not Observable □Not Applicable	
C405.2.3 [EL4] ¹	Separate lighting control devices for specific uses installed per approved	□Complies □Does Not	Requirement will be met.
	lighting plans.	□Not Observable □Not Applicable	
C405.3 [EL19] ³	Fluorescent luminaires with odd numbered lamp configurations that	☐Complies ☐Does Not	Exception: Requirement does not apply.
	are within 10 feet center to center (if recess mounted) or are within 1 foot edge to edge (if pendant or surface mounted) shall be tandem wired.	□Not Observable □Not Applicable	
C405.4 [EL6] ¹	Exit signs do not exceed 5 watts per face.	□Complies □Does Not	Exception: Requirement does not apply.
		□Not Observable □Not Applicable	
C405.2.3 [EL8] ¹	Additional interior lighting power allowed for special functions per the	□Complies □Does Not	Requirement will be met.
	approved lighting plans and is automatically controlled and separated from general lighting.	□Not Observable □Not Applicable	

Additional Comments/Assumptions:

	1	High Impact (Tier 1)	2	Medium Impact (Tier 2)	3	Low Impact (Tier 3)
--	---	----------------------	---	------------------------	---	---------------------

Project Title: Elizabethtown High School Restroom Renovation

Data filename: X:\Projects\XETR21\2. Design\11. ComCheck\etown electrical comcheck.cck

Report date: 09/14/21

Page 3 of 6

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Project Title: Elizabethtown High School Restroom Renovation

Data filename: X:\Projects\XETR21\2. Design\11. ComCheck\etown electrical comcheck.cck

Report date: 09/14/21 Page 4 of 6

Section # & Req.ID	Final Inspection	Complies?	Comments/Assumptions
C408.2.5. 1 [FI16] ³	Furnished as-built drawings for electric power systems within 30 days of system acceptance.	☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
C303.3, C408.2.5. 2 [FI17] ³	Furnished O&M instructions for systems and equipment to the building owner or designated representative.	☐Complies ☐Does Not ☐Not Observable ☐Not Applicable	Requirement will be met.
C405.5.2 [FI18] ¹	Interior installed lamp and fixture lighting power is consistent with what is shown on the approved lighting plans, demonstrating proposed watts are less than or equal to allowed watts.	□Complies □Does Not □Not Observable □Not Applicable	See the Interior Lighting fixture schedule for values.
C408.3 [FI33] ¹	Lighting systems have been tested to ensure proper calibration, adjustment, programming, and operation.	□Complies □Does Not □Not Observable □Not Applicable	Requirement will be met.

Additional Comments/Assumptions:

1 High Impact (Tier 1) 2 Medium Impact (Tier 2) 3 Low Impact (Tier 3)

Project Title: Elizabethtown High School Restroom Renovation

Data filename: X:\Projects\XETR21\2. Design\11. ComCheck\etown electrical comcheck.cck

Report date: 09/14/21

Page 5 of 6

Project Title: Elizabethtown High School Restroom Renovation Report date: 09/14/21 6 of 6 Page

Data filename: X:\Projects\XETR21\2. Design\11. ComCheck\etown electrical comcheck.cck