FIELD OBSERVATION REPORT 04



PCA ARCHITECTURE

■то:	Ken 105	Haney ton County Schools 5 Eaton Drive Wright, Ky 41017	■ DATE:		1/21/22
ATTENTION:					
FROM:	Jim Kaiser		PROJECT:		Addition & renovation to
	jkais	er@pca-arch.com			Ryland Heights Elementary
	188	1 Dixie Highway, Suite 130			
	Ft. Wright, KY 41011				
COPIES TO:	ro: Mr. Chad Atchley, Ms. Carrie Hooten		PROJECT NO.:		2021-001
WE TRANSMIT THE ATTACHED ITEMS VIA: EMAIL					
PURPOSE		For your use	DISPOSITION		No exceptions noted
		As requested			Exceptions noted,
		For review and comment			Revise as indicated.
		For information		П	REJECTED:
		For record			REVISE AND RESUBMIT
		For approval		П	
	$\overline{\Box}$			_	
COPIES DA	ATE	DESCRIPTION			PAGES
1 1/3	21/22	Field Observation Report 04			
■ REMARKS: Division 01: General Requirements 01.01:					

Division 02: Existing Conditions-Selective Demolition

02.01: Concrete structure of former electrical vault and asbestos containing materials has removed

02.02: Preliminary demolition has begun in the kitchen

02.03: Door canopy and brick veneer on west wall of existing cafeteria has been removed in preparation for removal of remaining cmu wall.

Division 03: Concrete

03.01: Foundations and slab on grade for stair/elevator addition and rear classroom wing are complete.

03.02: Foundations for cafeteria addition are complete

03.03: Perimeter insulation and granular base for cafeteria addition slab are installed in preparation for slab pour

Division 04: Masonry

04.01: Exterior cmu walls for stair/elevator addition are approximately 75% complete. CMU walls for elevator equipment room are complete.

Division 05: Metals

05.01:

Division 06: Woods and Plastics

06.01:

Division 07: Thermal and Moisture Protection

07.01:

Division 08: Doors and Windows

08.01:

Division 09: Finishes

09.01:

Division 10: Specialties

10.01:

Division 11: Equipment

11.01

Division 12: Furnishings

12.01:

Division 14: Conveying Systems

14.01:

Division 20-28: MEP

20-28.01:

Division 31: Earthwork

31.01:

Division 32: Exterior Improvements


32.01: Relocation of gas lines is complete.

CONSTRUCTION PHOTOS



Cafeteria addition – completed foundations & slab Stair/elevator addition exterior cmu walls prep. Wall demolition started





Demolished former electrical vault



Elevator equipment room



Interior view of new stairwell



New gas piping at building

- ☐ Please acknowledge receipt of transmitted items.

END