

FIELD OBSERVATION REPORT

PROJECT

Woodford Co. HS Emergency Structural Rep

RTA 2133

VISIT NAME

FOR220412 AUTHOR

FAYE BAHRAMI

DATE 5/11/2022

REPORT NO

01

STATUS FINAL

VISIT DETAILS

IN ATTENDANCE

Faye Bahrami - RossTarrant Architects

WEATHER

Sunny, 80 degrees

GENERAL COMMENTS

Two people were working on fastening the channels during the site visit.

OBSERVATIONS

ITEM: 001-001

REMARKS: South Locker Room: The footings are completed and the structural steel framing is underway. The supporting beams have been installed. The columns are in place. The channel installation is nearly complete. Fasteners were not completed at the time of site visit.







ITEM: 001-002

REMARKS: North Locker Room: The footings are completed and the structural steel framing is underway. The supporting beams have been installed. The columns are in place. The channel installation is nearly complete. Fasteners were completed. The reinforcing steel and steel plates are in place and still require final welds. Concrete placement from above has not begun.







RossTarrant Architects 101 old lafayette avenue lexington, kentucky 40502 p 859.254.4018 f 859.231.5046 www.rosstarrant.com