9244

KISTA - 2010 Used School Bus Inventory Form

Model: **Year:** 1992   **District:** Nelson Co
_____ Ford
_____ Chevrolet   **Vehicle Identification Number (VIN):** 1HVBBPLL4NH 433194
__X__ International
_____ Other _____   **Passenger Capacity:** 52

Body Type: **Tire Sizes:**   **Tire Quality (Check One):**
__X__ Ward   Good   Fair   Poor
_____ Blue Bird   Front: 265/75R 22.5 ☐   ☒   ☐
_____ Carpenter
_____ Other _____   Rear: 265/75R 22.5   ☐   ☒   ☐

Engine Type: **Bus Mileage:** 146795
_____ Gasoline
__X__ Diesel

Engine Make: **Brake Type:** AiR   **Bus Side Number:** 9244
_____ Ford
_____ Chevrolet   **Bus Operating Condition:**
__X__ International   __X__ Operable
_____ Other _____   _____ Inoperable

Engine Size:
Number Cylinders: 6   **Transmission Type:**
Size (Cubic Inches or Liters): DTA-360   __X__ Automatic
                                         _____ Standard

Check the statement which generally best describes this bus unit:
☒ Bus is well maintained and is in good operating condition.
☐ Bus is well maintained and is in fair operating condition.
☐ Bus is well maintained, but is in poor operating condition.
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None
Explain: Minor Dents and Scratches _____
_____

List any mechanical defects you are currently aware of the drivetrain: ☐ None
Explain: _____
_____

This bus can be inspected by calling: Name: JEFF MARCHESE _____

Telephone: (502) 249-1390   (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

KISTA - 2009 Used School Bus Inventory Form

Model: **Year:** 1992   **District:** NELSON CO
_____ Ford
_____ Chevrolet   **Vehicle Identification Number (VIN):** 1 HVBBPLL6NH433195
__X__ International
_____ Other _____   **Passenger Capacity:** 52

Body Type: **Tire Sizes:**   **Tire Quality (Check One):**

		Good	Fair	Poor
__X__ Ward				
_____ Blue Bird	Front: 265/75R22.5 ☐	☒	☐	
_____ Carpenter				
_____ Other _____	Rear: 265/75R22.5	☒	☐	☐

Engine Type: **Bus Mileage:** 143918
_____ Gasoline
__X__ Diesel

Engine Make: **Brake Type:** AIR   **Bus Side Number:** 9245
_____ Ford
_____ Chevrolet   **Bus Operating Condition:**
__X__ International   __X__ Operable
_____ Other _____   _____ Inoperable

Engine Size: **Transmission Type:**
Number Cylinders: 6   __X__ Automatic
Size (Cubic Inches or Liters): DTA-360   _____ Standard

Check the statement which generally best describes this bus unit:
☒ Bus is well maintained and is in good operating condition.
☐ Bus is well maintained and is in fair operating condition.
☐ Bus is well maintained, but is in poor operating condition.
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None
Explain: MINOR DENTS AND SCRATCHES

List any mechanical defects you are currently aware of the drivetrain: ☐ None
Explain: _____

This bus can be inspected by calling: Name: JEFF MARCHESE

Telephone: (502) 249-1390   (502) 349-7019

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

KISTA - 2010 Used School Bus Inventory Form

Model: **Year:** _1994_   **District:** _NELSON CO_
_____ Ford
_____ Chevrolet   **Vehicle Identification Number (VIN):** _4DRGSAAN3RA062424_
_X_ International
_____ Other _____   **Passenger Capacity:** _78_

Body Type: **Tire Sizes:**   **Tire Quality (Check One):**
_X_ Ward   Good   Fair   Poor
_____ Blue Bird   Front: _295/75R22.5_ ☐   ☒   ☐
_____ Carpenter
_____ Other _____   Rear: _295/75R22.5_   ☒   ☐   ☐

Engine Type: **Bus Mileage:** _189976_
_____ Gasoline
_X_ Diesel

Engine Make: **Brake Type:** _AIR_   **Bus Side Number:** _94-15_
_____ Ford
_____ Chevrolet   **Bus Operating Condition:**
_____ International   _X_ Operable
_____ Other _____   _____ Inoperable

Engine Size: **Transmission Type:**
Number Cylinders: _6_   _X_ Automatic
Size (Cubic Inches or Liters): _DT-466_   _____ Standard

Check the statement which generally best describes this bus unit:
☐ Bus is well maintained and is in good operating condition.
☒ Bus is well maintained and is in fair operating condition.
☐ Bus is well maintained, but is in poor operating condition.
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None
Explain: _MINOR DENTS AND SCRATCHES_

List any mechanical defects you are currently aware of the drivetrain: ☐ None
Explain: _ENGINE LACKS POWER_

This bus can be inspected by calling: Name: _JEFF MARCHESE_

Telephone: _(502) 249-1390_   _(502) 349-7019_

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.