

FIELD OBSERVATION REPORT

2023-02 (Scott Phase V)

■ TO:	Kenton County Board of Education 1055 Eaton Drive Ft. Wright, KY 41017	■ DATE:	2023.02.21
ATTENTION:	Mr. Rob Haney		
FROM:	Mark Perry mperry@pca-arch.com 906 Monmouth Street Newport, KY 41071	■ PROJECT:	Kenton County School District Scott Phase V
COPIES TO:	V: 859.431.8612 • D: 859.578.6013 Mr. Kevin Pfefferman; Ms. Carrie Hooten	PROJECT NO.:	20-032
■ WE TRANSMIT THE ATTACHED ITEMS VIA: eComm			
PURPOSE	 ➢ For your use ☐ As requested ☐ For review and comment ☐ For information ➢ For record ☐ For approval 	DISPOSITION	No exceptions noted Exceptions noted, Revise as indicated. REJECTED: REVISE AND RESUBMIT
COPIES DA	TE DESCRIPTION		PAGES
1 20	23-02 Field Observation Report		10

Division 01: General Requirements

01.01: 2023.02.03 – The pool consultant was on-site to review pool floor slab reinforcing in advance of the upcoming shallow end floor pour.

01.02: 2023.02.13 – A review of the baseball field playing surface occurred with the design team, Owner, and construction team.

01.03: 2023.02.15 – A meeting was held on-site to review fire suppression issues in the existing building yet to be renovated. Punch list was run on the fencing and netting at the baseball field. A meeting was held at the baseball field that included the baseball coach and athletic director to review hand-over, responsibilities, and issues.

Division 03: Concrete

03.01: 2023.01.25 – Concrete landings had recently been poured at the monumental stair. The area was tented. The north stair landings had cured and were available for use.

03.02: 2023.02.03 – The monumental stair landings had cured and were available for use. House keeping pads had been poured in Electric #2610.

Division 04: Masonry

04.01: 2023.01.25 – Masons were actively working to enclose the space under the north stair.

04.02: 2023.02.03 – Under stair enclosure at the north stair was complete. Masons were actively working at the second floor near the monumental stair.

Division 05: Metals

05.01: 2023.02.15 – Review of the monumental stair riser height issue occurred.



Division 07: Thermal and Moisture Protection

07.01: 2023.02.03 - Roofing was in progress over the pool space.

Division 09: Finishes

09.01: 2023.02.03 – Hard ceiling framing was in progress at restrooms and locker rooms where ductwork had already been installed.

09.02: 2023.02.03 - Some second floor spaces had been block sealed and painted.

Division 11: Equipment

11.01: 2023.02.03 – Netting had been installed at the baseball field. Work was about 90% complete.

11.02: 2023.02.15 – Team benches were being installed at the baseball dugouts.

Division 13: Special Construction

13.01: 2023.01.25 – Work was proceeding with constructing a ramp from the excavation spoils to allow removal of material as deep end excavation work had concluded.

13.02: 2023.02.03 – Pool floor reinforcing was apx 99% complete in the shallow end. The pool consultant requested additional bars at slab thickness transitions at the perimeter of the slab.

13.03: 2023.02.15 - Shallow end wall reinforcing was actively occurring.

Division 20-28: MEP

20-28.01: 2023.01.25 – Cable tray had been run through portions of first floor corridors in the addition. Electric wire pulling was progressing on the 1st floor.

20-28.02: 2023.01.25 – Ductwork was staged at the spectator seating area for installation in the corridor outside of that space. Heat pumps were staged in Mechanical #2940.

20-28.03: 2023.02.03 – Ductwork was staged for installation in the locker rooms below Mechanical #2940. Upper tier return ductwork had been installed in Corridor #2900.

20-28.04: 2023.02.03 – Light fixtures had been hung in the Practice Gym.

20-28.05: 2023.02.15 – Ductwork at the second floor outside of the under the dehumidification unit was apx. 75% complete.

Division 32: Exterior Improvements

32.01: 2023.02.15 – The baseball field subcontractor was spreading additional drying agent in the infield and was in the process of cutting the sod.

CONSTRUCTION PHOTOS



2023.01.25 - Monumental stair



2023.01.25 - Corridor 1800B





2023.01.25 - Gym Storage 1871



2023.01.25 - Pool deep end



2023.01.25 - Pool shallow end



2023.01.25 - North stair



2023.01.25 - Corridor 2900 looking South



2023.01.25 – Pool spectator seating staged with duct






2023.01.25 - VHP's in Mechanical 2940



2023.01.25 - Weight room looking East



2023.01.25 - Weight room looking West



2023.02.03 - Monumental stair



2023.02.03 - Gym Storage 1031



2023.02.03 - Practice Gym





2023.02.03 - Ceiling framing in Locker Room 1881



2023.02.03 - Ceiling framing in Locker Room 1891



2023.02.03 - Corridor 1900C looking South



2023.02.03 - Corridor 1900C looking North



2023.02.03 - Pool shallow end



2023.02.03 - Pool deep end






2023.02.03 - North stair



2023.02.03 - Corridor 2900 looking South



2023.02.03 - Pool shallow end from 2nd floor



2023.02.03 - Corridor 2800C



2023.02.03 - Weight 2860 looking East



2023.02.03 - Mechanical 2940





2023.02.03 - Mechanical 2940



2023.02.03 - Electric 2810



2023.02.03 - Corridor 1800C



2023.02.03 - Restroom 1842 ceiling framing



2023.02.03 - Metal roof at baseball shade structure




2023.02.03 - Baseball netting





2023.02.03 - Baseball press box



2023.02.08 - Pool shallow end



2023.02.08 - Pool shallow end



2023.02.15 - Visitor dugout



2023.02.15 - Home dugout




2023.02.15 - Grandstands



PCA ARCHITECTURE



2023.02.15 - Cutting the infield



2023.02.15 - Infield from home plate



2023.02.15 - Duct staged in Cardio 2850



2023.02.15 - Weight 2860 looking East



2023.02.15 - Weight 2860 Looking West



2023.02.15 - Corridor 2800C






2023.02.15 - Corridor 2900 looking North



2023.02.15 - Corridor 2900 looking South



2023.02.15 - Pool shallow end



2023.02.15 - Pool shallow end

END

[☐] Please acknowledge receipt of transmitted items.

 $[\]square$ Return transmitted items to PCA ARCHITECTURE PSC.