

PROJECT:	5056-01 Trans District Sup Fac 5056-01	DATE:	7/17/2024
VISIT NAME:	Construction Progress Site Visit	REPORT NO:	024
AUTHOR:	David Vaught	STATUS:	Final

VISIT DETAILS

WEATHER:	Mostly Sunny High in the upper 80's	START TIME:	11:30 AM
		END TIME:	2:00 PM


GENERAL COMMENTS: A construction progress site visit was conducted on July 17th, 2024. The following items were noted.

PARTICIPANT NAME	COMPANY	TITLE	EMAIL
David Vaught	GRW	Project Manager	DVaught@grwinc.com

OBSERVATIONS


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-001	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.            Rough carpentry installation complete.</p>			
	SPACE:	001 - NORTH ELEVATION	SUBJECT:	7/17/24 at 11:39 AM
	CATEGORY:	UNit Masonry / Stone Masonry	REFERENCE:	042000 / 047323


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-002	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.            Rough carpentry installation complete.</p>		
	SPACE:	004 - WEST ELEVATION	SUBJECT: 7/17/24 at 11:40 AM
	CATEGORY:	UNit Masonry / Stone Masonry	REFERENCE: 042000 / 047323


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-003	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.            Rough carpentry installation complete.</p>			
	SPACE:	003 - EAST ELEVATION	SUBJECT:	7/17/24 at 11:41 AM
	CATEGORY:	UNit Masonry / Stone Masonry	REFERENCE:	042000 / 047323


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-004	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 35%;">143 - AUTOMATIC WASH BAY</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 15%;">7/17/24 at 11:41 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	7/17/24 at 11:41 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	7/17/24 at 11:41 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-005	<p>Unit masonry installation complete.            Unit masonry stored on site.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">143 - AUTOMATIC WASH BAY</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 11:42 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	7/17/24 at 11:42 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	7/17/24 at 11:42 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-006	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Masonry opening prepared for storefront framing. Field verify masonry opening.</p>		
	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT: 7/17/24 at 11:42 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-007	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Masonry opening prepared for storefront framing. Field verify masonry opening.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 35%;">143 - AUTOMATIC WASH BAY</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 15%;">7/17/24 at 11:43 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	7/17/24 at 11:43 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	143 - AUTOMATIC WASH BAY	SUBJECT:	7/17/24 at 11:43 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-008	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Storm drain plumbing piping installation complete.		
SPACE:	145 - CIRCULATION	SUBJECT:	7/17/24 at 11:44 AM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-009	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Storm drain plumbing piping installation complete.</p>		
	SPACE:	145 - CIRCULATION	SUBJECT: 7/17/24 at 11:44 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-010	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Storm drain plumbing piping installation complete.		
	SPACE:	144 - STORAGE ROOM	SUBJECT: 7/17/24 at 11:45 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-011	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Storm drain plumbing piping installation complete.			
SPACE:		144 - STORAGE ROOM	SUBJECT:	7/17/24 at 11:45 AM
CATEGORY:		Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-012	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 7/17/24 at 11:45 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-013	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	142 - TIRE STORAGE	SUBJECT: 7/17/24 at 11:46 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-014	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
SPACE:	142 - TIRE STORAGE	SUBJECT:	7/17/24 at 11:46 AM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-015	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Verify roof access ladder location through the roof deck?</p>			
	SPACE:	142 - TIRE STORAGE	SUBJECT:	7/17/24 at 11:46 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-016	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	146 - CIRCULATION	SUBJECT: 7/17/24 at 11:47 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-017	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	146 - CIRCULATION	SUBJECT: 7/17/24 at 11:47 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-018	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">147 - POL STORAGE ROOM</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 11:47 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	147 - POL STORAGE ROOM	SUBJECT:	7/17/24 at 11:47 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	147 - POL STORAGE ROOM	SUBJECT:	7/17/24 at 11:47 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-019	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 35%;">147 - POL STORAGE ROOM</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 15%;">7/17/24 at 11:48 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	147 - POL STORAGE ROOM	SUBJECT:	7/17/24 at 11:48 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	147 - POL STORAGE ROOM	SUBJECT:	7/17/24 at 11:48 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-020	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 149 - BATTERY STORAGE / CHARGING	SUBJECT: 7/17/24 at 11:48 AM	
	CATEGORY: Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100	

ITEM	REMARKS	DISCUSSION	PHOTO
024-021	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule		
	SPACE: 149 - BATTERY STORAGE / CHARGING	SUBJECT: 7/17/24 at 11:48 AM	
	CATEGORY: Unit Masonry / Hollow Metal Door Frame	REFERENCE: 042000 / 081113	


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-022	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 40%;">150 - FLAMMABLE STORAGE AREA</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 10%;">7/17/24 at 11:49 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	150 - FLAMMABLE STORAGE AREA	SUBJECT:	7/17/24 at 11:49 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	150 - FLAMMABLE STORAGE AREA	SUBJECT:	7/17/24 at 11:49 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-023	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	150 - FLAMMABLE STORAGE AREA	SUBJECT: 7/17/24 at 11:49 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-024	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	151 - ELECTRICAL CLOSET	SUBJECT: 7/17/24 at 11:49 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-025	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	152 - COMM. CLOSET	SUBJECT: 7/17/24 at 11:50 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-026	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">SPACE:</td> <td style="width: 35%;">153 - END OF BAY STORAGE</td> <td style="width: 20%;">SUBJECT:</td> <td style="width: 25%;">7/17/24 at 11:50 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	153 - END OF BAY STORAGE	SUBJECT:	7/17/24 at 11:50 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	153 - END OF BAY STORAGE	SUBJECT:	7/17/24 at 11:50 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-027	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	153 - END OF BAY STORAGE	SUBJECT:	7/17/24 at 11:51 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-028	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td>141 - PARTS / INVENTORY</td> <td style="width: 25%;">SUBJECT:</td> <td>7/17/24 at 11:51 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	141 - PARTS / INVENTORY	SUBJECT:	7/17/24 at 11:51 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	141 - PARTS / INVENTORY	SUBJECT:	7/17/24 at 11:51 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-029	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Adjust metal wall clip for 8" CMU. Clip has been installed for 12" CMU.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 50%;">141 - PARTS / INVENTORY</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 11:51 AM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	141 - PARTS / INVENTORY	SUBJECT:	7/17/24 at 11:51 AM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	141 - PARTS / INVENTORY	SUBJECT:	7/17/24 at 11:51 AM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-030	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Adjust metal wall clip for 8" CMU. Clip has been installed for 12" CMU.</p>		
	SPACE:	141 - PARTS / INVENTORY	SUBJECT: 7/17/24 at 11:52 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-031	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	140 - PARTS STORAGE	SUBJECT: 7/17/24 at 11:52 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-032	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	140 - PARTS STORAGE	SUBJECT: 7/17/24 at 11:52 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE: 042000 / 052100 / 053100




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-033	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	140 - PARTS STORAGE	SUBJECT:	7/17/24 at 11:53 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-034	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	131 - CIRCULATION	SUBJECT: 7/17/24 at 11:53 AM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO				
024-035	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.						
				SPACE:	131 - CIRCULATION	SUBJECT:	7/17/24 at 11:53 AM
				CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO				
024-036	Unit masonry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule						
				SPACE:	138 - INSPECTION BAY 1	SUBJECT:	7/17/24 at 11:53 AM
				CATEGORY:	Unit Masonry	REFERENCE:	042000

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-037	Unit masonry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule		
	SPACE: 139 - INSPECTION BAY 2	SUBJECT: 7/17/24 at 11:54 AM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	

ITEM	REMARKS	DISCUSSION	PHOTO
024-038	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 138 - INSPECTION BAY 1	SUBJECT: 7/17/24 at 11:54 AM	
	CATEGORY: Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO				
024-039	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.						
				SPACE:	139 - INSPECTION BAY 2	SUBJECT:	7/17/24 at 11:55 AM
				CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO				
024-040	Unit masonry installation in progress. Hollow metal door frame installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule						
				SPACE:	139 - INSPECTION BAY 2	SUBJECT:	7/17/24 at 11:55 AM
				CATEGORY:	Unit Masonry / Hollow Metal Door Frame	REFERENCE:	042000 / 081113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-041	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	139 - INSPECTION BAY 2	SUBJECT:	7/17/24 at 11:55 AM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE:	042000 / 033000 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-042	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Rough carpentry installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	138 - INSPECTION BAY 1	SUBJECT:	7/17/24 at 11:56 AM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-043	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress. Cast in place concrete installation complete. Rough carpentry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 25%;">132 - MAINTENANCE BAY 1</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 25%;">7/17/24 at 12:02 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry</td> <td>REFERENCE:</td> <td>042000 / 033000 / 051200 / 061053</td> </tr> </table>	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:02 PM	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053		
SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:02 PM								
CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053								




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-044	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Rough carpentry installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">132 - MAINTENANCE BAY 1</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:04 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry</td> <td>REFERENCE:</td> <td>042000 / 033000 / 051200 / 061053</td> </tr> </table>	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:04 PM	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053		
SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:04 PM								
CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053								


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-045	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	131 - CIRCULATION	SUBJECT: 7/17/24 at 12:04 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-046	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Rough carpentry installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	131 - CIRCULATION	SUBJECT: 7/17/24 at 12:05 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE: 042000 / 033000 / 051200 / 061053


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-047	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Rough carpentry installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	138 - INSPECTION BAY 1	SUBJECT:	7/17/24 at 12:05 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-048	<p>Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Rough carpentry installation in progress.            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	136 - MAINTENANCE BAY 5	SUBJECT: 7/17/24 at 12:05 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE: 033000 / 051200 / 061053


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-049	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress. Cast in place concrete installation complete. Rough carpentry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	134 - MAINTENANCE BAY 3	SUBJECT:	7/17/24 at 12:05 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-050	Unit masonry installation in progress. Steel joist framing installation in progress. Steel framing in progress. Cast in place concrete installation complete. Rough carpentry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:06 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-051	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	139 - INSPECTION BAY 2	SUBJECT:	7/17/24 at 12:06 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-052	Cast in place concrete installation complete. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	137 - MAINTENANCE BAY 6	SUBJECT: 7/17/24 at 12:06 PM
	CATEGORY:	Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-053	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">SPACE:</td> <td style="width: 30%;">135 - MAINTENANCE BAY 4</td> <td style="width: 20%;">SUBJECT:</td> <td style="width: 30%;">7/17/24 at 12:07 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 033000 / 052100 / 051200</td> </tr> </table>	SPACE:	135 - MAINTENANCE BAY 4	SUBJECT:	7/17/24 at 12:07 PM	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200		
SPACE:	135 - MAINTENANCE BAY 4	SUBJECT:	7/17/24 at 12:07 PM								
CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200								


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-054	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required</p>		
	<p>SPACE: 133 - MAINTENANCE BAY 2</p>	SUBJECT:	7/17/24 at 12:07 PM
	<p>CATEGORY: Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing</p>	REFERENCE:	042000 / 033000 / 052100 / 051200


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-055	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 50%;">132 - MAINTENANCE BAY 1</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:08 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 033000 / 052100 / 051200</td> </tr> </table>	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:08 PM	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200		
SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:08 PM								
CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200								


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-056	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:08 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-057	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:08 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-058	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	131 - CIRCULATION	SUBJECT: 7/17/24 at 12:08 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-059	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT:	7/17/24 at 12:08 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-060	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	<p>SPACE: 133 - MAINTENANCE BAY 2</p>	SUBJECT:	7/17/24 at 12:09 PM
	<p>CATEGORY: Unit Masonry / Steel Joist Framing / Steel Framing</p>	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-061	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
SPACE:		133 - MAINTENANCE BAY 2	SUBJECT:	7/17/24 at 12:09 PM
CATEGORY:		Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-062	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:09 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-063	<p>Masonry installation in progress            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">SPACE:</td> <td style="width: 30%;">101 - RECEPTION / GREETING AREA</td> <td style="width: 20%;">SUBJECT:</td> <td style="width: 30%;">7/17/24 at 12:09 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 047323</td> </tr> </table>	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:09 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 047323		
SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:09 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 047323								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-064	Unit masonry installation in progress. Provide backer rod and / or sealant at all masonry control joints. Provide sealant color samples for initial color selection. Steel joist framing installation in progress. Steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT: 7/17/24 at 12:10 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO
024-065	Structural steel framing stored on site. Provide delivery storage and handling per specification section 051200 1.8.		
	SPACE:	007 - SITE - EAST	SUBJECT: 7/17/24 at 12:10 PM
	CATEGORY:	Steel Framing	REFERENCE: 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-066	Structural steel framing stored on site. Provide delivery storage and handling per specification section 051200 1.8.			
SPACE:		007 - SITE - EAST	SUBJECT:	7/17/24 at 12:11 PM
CATEGORY:		Steel Framing	REFERENCE:	051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-067	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
SPACE:		003 - EAST ELEVATION	SUBJECT:	7/17/24 at 12:11 PM
CATEGORY:		Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-068	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	003 - EAST ELEVATION	SUBJECT:	7/17/24 at 12:11 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 033000 / 052100 / 051200




# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-069	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Structural steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT: 7/17/24 at 12:12 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 033000 / 052100 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-070	Structural steel framing stored on site. Provide delivery storage and handling per specification section 051200 1.8.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 12:13 PM
	CATEGORY:	Steel Framing	REFERENCE: 051200

ITEM	REMARKS	DISCUSSION	PHOTO
024-071	Structural steel framing stored on site. Provide delivery storage and handling per specification section 051200 1.8.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 12:13 PM
	CATEGORY:	Steel Framing	REFERENCE: 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-072	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Cast in place concrete installation complete. Rough carpentry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	004 - WEST ELEVATION	SUBJECT:	7/17/24 at 12:14 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-073	Concrete column installation in progress. Structural steel installation in progress.		
	SPACE:	004 - WEST ELEVATION	SUBJECT: 7/17/24 at 12:15 PM
	CATEGORY:	Cast in Place Concrete / Steel Framing	REFERENCE: 033000 / 051200


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-074	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.            Rough carpentry installation in progress.</p>			
	SPACE:	001 - NORTH ELEVATION	SUBJECT:	7/17/24 at 12:15 PM
	CATEGORY:	UNit Masonry / Stone Masonry	REFERENCE:	042000 / 047323


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-075	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Structural steel framing in progress.            Cast in place concrete installation complete.            Rough carpentry installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	001 - NORTH ELEVATION	SUBJECT:	7/17/24 at 12:15 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-076	<p>Unit masonry installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Hollow metal door frame installation complete.</p>		
	SPACE: 111 - STAIR B	SUBJECT: 7/17/24 at 12:16 PM	
	CATEGORY: Unit Masonry / Hollow Metal Door Frame	REFERENCE: 042000 / 081113	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-077	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Remove stains from CMU and clean before paint finish.</p>		
	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT: 7/17/24 at 12:16 PM
	CATEGORY:	Unit Masonry	REFERENCE: 042000




## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-078	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Steel joist framing installation in progress.            Steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            General: Remove dirt from steel joist before paint finish.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">132 - MAINTENANCE BAY 1</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:16 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 052100 / 051200</td> </tr> </table>	SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:16 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200		
SPACE:	132 - MAINTENANCE BAY 1	SUBJECT:	7/17/24 at 12:16 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200								

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-079	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule</p>		
	SPACE: 131 - CIRCULATION	SUBJECT: 7/17/24 at 12:17 PM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	

ITEM	REMARKS	DISCUSSION	PHOTO
024-080	<p>Unit masonry installation in progress.            Provide backer rod and / or sealant at all masonry control joints.            Provide sealant color samples for initial color selection.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule</p>		
	SPACE: 133 - MAINTENANCE BAY 2	SUBJECT: 7/17/24 at 12:17 PM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-081	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Structural steel framing in progress.            Cast in place concrete installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 35%;">133 - MAINTENANCE BAY 2</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 15%;">7/17/24 at 12:18 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Cast in Place Concrete / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 033000 / 051200</td> </tr> </table>	SPACE:	133 - MAINTENANCE BAY 2	SUBJECT:	7/17/24 at 12:18 PM	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE:	042000 / 033000 / 051200		
SPACE:	133 - MAINTENANCE BAY 2	SUBJECT:	7/17/24 at 12:18 PM								
CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE:	042000 / 033000 / 051200								


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-082	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress</p>			
	SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:19 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Ductwork	REFERENCE:	042000 / 052100 / 053100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-083	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress            Fire protection installation in progress.</p>			
	SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:20 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-084	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress			
SPACE:		109 - SHARED LOADING DOCK	SUBJECT:	7/17/24 at 12:20 PM
CATEGORY:		Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-085	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress			
	SPACE:	110 - CIRCULATION	SUBJECT:	7/17/24 at 12:22 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-086	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Cast in place concrete installation complete. Rough carpentry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	004 - WEST ELEVATION	SUBJECT:	7/17/24 at 12:22 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing / Rough Carpentry	REFERENCE:	042000 / 033000 / 051200 / 061053



## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-087	Unit masonry installation complete. Cast in place concrete installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule		
	SPACE: 111 - STAIR B	SUBJECT: 7/17/24 at 12:22 PM	
	CATEGORY: Unit Masonry / Cast in Place Concrete	REFERENCE: 042000 / 033000	

ITEM	REMARKS	DISCUSSION	PHOTO
024-088	Unit masonry installation complete. Cast in place concrete installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Hollow metal door frame installation complete.		
	SPACE: 111 - STAIR B	SUBJECT: 7/17/24 at 12:23 PM	
	CATEGORY: Unit Masonry / Cast in Place Concrete / Hollow Metal Frames	REFERENCE: 042000 / 033000 / 081113	


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-089	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT:	7/17/24 at 12:23 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-090	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT:	7/17/24 at 12:23 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100

ITEM	REMARKS	DISCUSSION	PHOTO	
024-091	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.			
	SPACE:	121 - MALE RESTROOM	SUBJECT:	7/17/24 at 12:24 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-092	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.			
SPACE:		120 - FEMALE RESTROOM	SUBJECT:	7/17/24 at 12:24 PM
CATEGORY:		Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-093	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Plumbing piping installation in progress.										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">119 - DRIVERS BREAK ROOM</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:24 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100 / 221000</td> </tr> </table>	SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT:	7/17/24 at 12:24 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000		
SPACE:	119 - DRIVERS BREAK ROOM	SUBJECT:	7/17/24 at 12:24 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-094	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Fire extinguisher cabinet installation in progress.			
	SPACE:	110 - CIRCULATION	SUBJECT:	7/17/24 at 12:25 PM
	CATEGORY:	Unit Masonry / Fire Protection Cabinets	REFERENCE:	042000 / 104413

ITEM	REMARKS	DISCUSSION	PHOTO	
024-095	Cast in place concrete installation in progress.			
	SPACE:	114 - SHARED LOADING DOCK	SUBJECT:	7/17/24 at 12:25 PM
	CATEGORY:	Cast in Place Concrete	REFERENCE:	033000


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-096	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">114 - SHARED LOADING DOCK</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:26 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100</td> </tr> </table>	SPACE:	114 - SHARED LOADING DOCK	SUBJECT:	7/17/24 at 12:26 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100		
SPACE:	114 - SHARED LOADING DOCK	SUBJECT:	7/17/24 at 12:26 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking	REFERENCE:	042000 / 052100 / 053100								

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-097	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Fire protection installation in progress.		
SPACE:	115 - VENDER RECEIVING AREA	SUBJECT:	7/17/24 at 12:26 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression	REFERENCE:	042000 / 052100 / 211000




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-098	Steel joist framing installation in progress. Structural steel framing in progress. Cast in place concrete installation complete. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
SPACE:		004 - WEST ELEVATION	SUBJECT:	7/17/24 at 12:26 PM
CATEGORY:		Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	033000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-099	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress</p>		
	<p>SPACE: 117 - DRY FOOD STORAGE</p>	SUBJECT: 7/17/24 at 12:26 PM	
	<p>CATEGORY: Unit Masonry / Steel Joist Framing / Ductwork</p>	REFERENCE: 042000 / 052100 / 233113	


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-100	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ductwork material stored on site.</p>		
	SPACE:	117 - DRY FOOD STORAGE	SUBJECT: 7/17/24 at 12:27 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-101	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress.			
	SPACE:	109 - SHARED LOADING DOCK	SUBJECT:	7/17/24 at 12:27 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-102	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress			
	SPACE:	118 - FREEZER STORAGE	SUBJECT:	7/17/24 at 12:27 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-103	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress			
	SPACE:	118 - FREEZER STORAGE	SUBJECT:	7/17/24 at 12:28 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-104	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress            Fire protection installation in progress.</p>			
	SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:28 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-105	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress.		
SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:28 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-106	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress</p>		
	SPACE:	130 - MECHANIC BREAK ROOM	SUBJECT: 7/17/24 at 12:29 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-107	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress		
	SPACE:	129 - ADMIN. ASSISTANT OFFICE	SUBJECT: 7/17/24 at 12:29 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-108	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress.		
SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:29 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-109	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress.		
	SPACE:	107 - CIRCULATION	SUBJECT: 7/17/24 at 12:29 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE: 042000 / 052100 / 211000 / 233113

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-110	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress            Fire protection installation in progress.</p>			
	SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:35 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-111	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>		
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT: 7/17/24 at 12:36 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-112	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>		
	SPACE:	102 - STAIR A	SUBJECT: 7/17/24 at 12:36 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-113	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">101 - RECEPTION / GREETING AREA</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:37 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 052100 / 051200</td> </tr> </table>	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:37 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200		
SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:37 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200								




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-114	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>			
	SPACE:	102 - STAIR A	SUBJECT:	7/17/24 at 12:37 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-115	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">101 - RECEPTION / GREETING AREA</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:37 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 052100 / 051200</td> </tr> </table>	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:37 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200		
SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:37 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-116	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	101 - RECEPTION / GREETING AREA	SUBJECT:	7/17/24 at 12:37 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO	
024-117	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.			
	SPACE:	103 - CIRCULATION	SUBJECT:	7/17/24 at 12:38 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-118	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress. Fire protection installation in progress.			
	SPACE:	104 - PUBLIC MALE RESTROOM	SUBJECT:	7/17/24 at 12:38 PM
	CATEGORY:	Unit Masonry / Plumbing Piping / Fire Suppression	REFERENCE:	042000 / 221000 / 211000

ITEM	REMARKS	DISCUSSION	PHOTO	
024-119	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.			
	SPACE:	104 - PUBLIC MALE RESTROOM	SUBJECT:	7/17/24 at 12:38 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-120	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.			
	SPACE:	105 - JANITOR	SUBJECT:	7/17/24 at 12:39 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000

ITEM	REMARKS	DISCUSSION	PHOTO	
024-121	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress. Ensure the flush valve for the toilet fixture is on the open side of the toilet stall.			
	SPACE:	106 - PUBLIC FEMALE RESTROOM	SUBJECT:	7/17/24 at 12:39 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-122	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.		
	SPACE:	106 - PUBLIC FEMALE RESTROOM	SUBJECT: 7/17/24 at 12:39 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE: 042000 / 221000


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-123	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	162 - CIRCULATION	SUBJECT:	7/17/24 at 12:39 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-124	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td>163 - STORAGE</td> <td style="width: 25%;">SUBJECT:</td> <td>7/17/24 at 12:40 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing</td> <td>REFERENCE:</td> <td>042000 / 052100</td> </tr> </table>	SPACE:	163 - STORAGE	SUBJECT:	7/17/24 at 12:40 PM	CATEGORY:	Unit Masonry / Steel Joist Framing	REFERENCE:	042000 / 052100		
SPACE:	163 - STORAGE	SUBJECT:	7/17/24 at 12:40 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing	REFERENCE:	042000 / 052100								




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-125	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>		
	SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT: 7/17/24 at 12:40 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-126	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>		
	SPACE:	164 - TECHNOLOGY DIRECTOR	SUBJECT: 7/17/24 at 12:40 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-127	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	165 - WAR ROOM	SUBJECT:	7/17/24 at 12:40 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-128	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	165 - WAR ROOM	SUBJECT:	7/17/24 at 12:40 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-129	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>		
	SPACE:	166 - NETWORK ADMINISTRATOR	SUBJECT: 7/17/24 at 12:41 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-130	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>		
	SPACE:	166 - NETWORK ADMINISTRATOR	SUBJECT: 7/17/24 at 12:41 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-131	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress. Ensure duct work elevation is coordinated with finish ceiling elevation.		
	SPACE:	162 - CIRCULATION	SUBJECT: 7/17/24 at 12:41 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-132	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	172 - CIRCULATION	SUBJECT:	7/17/24 at 12:41 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-133	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>		
	SPACE:	162 - CIRCULATION	SUBJECT: 7/17/24 at 12:42 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-134	<p>Unit masonry installation in progress.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>		
	SPACE:	170 - NETWORK OPERATIONS	SUBJECT: 7/17/24 at 12:42 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-135	<p>Unit masonry installation in progress.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	170 - NETWORK OPERATIONS	SUBJECT: 7/17/24 at 12:42 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing	REFERENCE: 042000 / 052100

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-136	<p>Unit masonry installation in progress.                      Steel joist framing installation complete.                      Steel decking installation complete.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	<p>SPACE: 171 - CONFERENCE ROOM</p>		<p>SUBJECT: 7/17/24 at 12:43 PM</p>
	<p>CATEGORY: Unit Masonry / Steel Joist Framing</p>		<p>REFERENCE: 042000 / 052100</p>

ITEM	REMARKS	DISCUSSION	PHOTO
024-137	<p>Unit masonry installation in progress.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule</p>		
	<p>SPACE: 003 - EAST ELEVATION</p>		<p>SUBJECT: 7/17/24 at 12:43 PM</p>
	<p>CATEGORY: Unit Masonry</p>		<p>REFERENCE: 042000</p>


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-138	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	167 - DATA LEADER	SUBJECT:	7/17/24 at 12:43 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-139	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	167 - DATA LEADER	SUBJECT:	7/17/24 at 12:43 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-140	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with finish ceiling elevation.</p>			
	SPACE:	169 - BREAK ROOM	SUBJECT:	7/17/24 at 12:44 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-141	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Plumbing piping installation in progress.		
SPACE:	169 - BREAK ROOM	SUBJECT:	7/17/24 at 12:44 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Plumbing Piping	REFERENCE:	042000 / 052100 / 221000



## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-142	<p>Unit masonry installation complete.                      Steel joist framing installation complete.                      Steel decking installation complete.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.                      Ductwork installation in progress.</p>		
	SPACE:	174 - IMAGE ROOM	SUBJECT: 7/17/24 at 12:44 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE: 042000 / 052100 / 233113

ITEM	REMARKS	DISCUSSION	PHOTO
024-143	<p>Unit masonry installation complete.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      Hollow metal door frame installation complete.</p>		
	SPACE:	173 - BUG ROOM 2	SUBJECT: 7/17/24 at 12:45 PM
	CATEGORY:	Unit Masonry / Hollow Metal Door Frame	REFERENCE: 042000 / 081113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-144	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.            Ensure duct work elevation is coordinated with overhead door housing clearance requirements.</p>			
	SPACE:	173 - BUG ROOM 2	SUBJECT:	7/17/24 at 12:45 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-145	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
SPACE:	173 - BUG ROOM 2	SUBJECT:	7/17/24 at 12:45 PM
CATEGORY:	Unit Masonry / Steel Joist Framing	REFERENCE:	042000 / 052100


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-146	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress.		
SPACE:	174 - IMAGE ROOM	SUBJECT:	7/17/24 at 12:46 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-147	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.</p>			
	SPACE:	174 - IMAGE ROOM	SUBJECT:	7/17/24 at 12:46 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-148	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">183 - WAREHOUSE</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 12:46 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 052100 / 051200</td> </tr> </table>	SPACE:	183 - WAREHOUSE	SUBJECT:	7/17/24 at 12:46 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200		
SPACE:	183 - WAREHOUSE	SUBJECT:	7/17/24 at 12:46 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200								


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-149	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>			
	SPACE:	183 - WAREHOUSE	SUBJECT:	7/17/24 at 12:47 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-150	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>		
SPACE:	183 - WAREHOUSE	SUBJECT:	7/17/24 at 12:47 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-151	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>			
	SPACE:	183 - WAREHOUSE	SUBJECT:	7/17/24 at 12:47 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-152	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>			
	SPACE:	183 - WAREHOUSE	SUBJECT:	7/17/24 at 12:48 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-153	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	003 - EAST ELEVATION	SUBJECT:	7/17/24 at 12:48 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-154	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
SPACE:		003 - EAST ELEVATION	SUBJECT:	7/17/24 at 12:49 PM
CATEGORY:		Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-155	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	003 - EAST ELEVATION	SUBJECT: 7/17/24 at 12:49 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-156	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 003 - EAST ELEVATION	SUBJECT: 7/17/24 at 12:50 PM	
	CATEGORY: Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200	

ITEM	REMARKS	DISCUSSION	PHOTO
024-157	Cast in place concrete installation complete. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 171 - CONFERENCE ROOM	SUBJECT: 7/17/24 at 12:50 PM	
	CATEGORY: Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-158	Cast in place concrete installation complete. Installation of underground storm sewer system in progress.			
	SPACE:	171 - CONFERENCE ROOM	SUBJECT:	7/17/24 at 12:51 PM
	CATEGORY:	Cast in Place Concrete / Storm Sewer System	REFERENCE:	033000 / 334113

ITEM	REMARKS	DISCUSSION	PHOTO	
024-159	Cast in place concrete installation complete. Steel joist framing installation in progress. Structural steel framing in progress. Remove rust from structural steel and clean. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	172 - CIRCULATION	SUBJECT:	7/17/24 at 12:51 PM
	CATEGORY:	Cast in Place Concrete / Steel Framing	REFERENCE:	033000 / 051200

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-160	Cast in place concrete installation complete. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	174 - IMAGE ROOM	SUBJECT:	7/17/24 at 12:52 PM
	CATEGORY:	Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE:	033000 / 052100 / 051200


ITEM	REMARKS	DISCUSSION	PHOTO	
024-161	Cast in place concrete installation complete. Installation of underground storm sewer system in progress.			
	SPACE:	174 - IMAGE ROOM	SUBJECT:	7/17/24 at 12:53 PM
	CATEGORY:	Cast in Place Concrete / Storm Sewage System	REFERENCE:	033000 / 334113



## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-162	Cast in place concrete installation complete. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 003 - EAST ELEVATION	SUBJECT: 7/17/24 at 12:54 PM	
	CATEGORY: Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200	

ITEM	REMARKS	DISCUSSION	PHOTO
024-163	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 184 - COVERED LOADING DOCK	SUBJECT: 7/17/24 at 12:54 PM	
	CATEGORY: Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200	

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-164	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	007 - SITE - EAST	SUBJECT: 7/17/24 at 12:54 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

ITEM	REMARKS	DISCUSSION	PHOTO
024-165	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	007 - SITE - EAST	SUBJECT: 7/17/24 at 12:55 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-166	<p>Unit masonry installation in progress.                      Cast in place concrete installation complete.                      Steel joist framing installation in progress.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	002 - SOUTH ELEVATION	SUBJECT: 7/17/24 at 12:55 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE: 042000 / 033000 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO
024-167	<p>Unit masonry installation in progress.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      Modular block wall installation complete.</p>		
	SPACE:	185 - OPERATIONS WAREHOUSE	SUBJECT: 7/17/24 at 12:56 PM
	CATEGORY:	Unit Masonry / Modular Block Retaining Wall	REFERENCE: 042000 / 323223


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-168	Unit masonry installation in progress. Cast in place concrete installation complete. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	002 - SOUTH ELEVATION	SUBJECT: 7/17/24 at 12:56 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE: 042000 / 033000 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-169	<p>Unit masonry installation in progress.                      Cast in place concrete installation complete.                      Steel joist framing installation in progress.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE: 002 - SOUTH ELEVATION	SUBJECT: 7/17/24 at 12:56 PM	
	CATEGORY: Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE: 042000 / 033000 / 051200	

ITEM	REMARKS	DISCUSSION	PHOTO
024-170	<p>Unit masonry installation in progress.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule</p>		
	SPACE: 184 - COVERED LOADING DOCK	SUBJECT: 7/17/24 at 12:57 PM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-171	Unit masonry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule		
	SPACE: 184 - COVERED LOADING DOCK	SUBJECT: 7/17/24 at 12:57 PM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	

ITEM	REMARKS	DISCUSSION	PHOTO
024-172	Unit masonry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Domestic plumbing fixture installation in progress.		
	SPACE: 002 - SOUTH ELEVATION	SUBJECT: 7/17/24 at 12:58 PM	
	CATEGORY: Unit Masonry / Domestic Water Plumbing Specialties	REFERENCE: 042000 / 221119	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-173	Unit masonry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule		
	SPACE: 185 - OPERATIONS WAREHOUSE	SUBJECT: 7/17/24 at 12:58 PM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	

ITEM	REMARKS	DISCUSSION	PHOTO
024-174	Unit masonry installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule		
	SPACE: 185 - OPERATIONS WAREHOUSE	SUBJECT: 7/17/24 at 12:59 PM	
	CATEGORY: Unit Masonry	REFERENCE: 042000	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-175	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress.		
	SPACE:	108 - CIRCULATION	SUBJECT: 7/17/24 at 12:59 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE: 042000 / 052100 / 211000 / 233113




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-176	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress.			
SPACE:		158 - TRAINING ROOM	SUBJECT:	7/17/24 at 12:59 PM
CATEGORY:		Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-177	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress.		
SPACE:	159 - PLAN AND O+M ROOM	SUBJECT:	7/17/24 at 1:00 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-178	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Ductwork installation in progress.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">SPACE:</td> <td style="width: 35%;">160 - RECORDS AND PLAN ARCHIVE</td> <td style="width: 20%;">SUBJECT:</td> <td style="width: 25%;">7/17/24 at 1:00 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Ductwork</td> <td>REFERENCE:</td> <td>042000 / 052100 / 233113</td> </tr> </table>	SPACE:	160 - RECORDS AND PLAN ARCHIVE	SUBJECT:	7/17/24 at 1:00 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113		
SPACE:	160 - RECORDS AND PLAN ARCHIVE	SUBJECT:	7/17/24 at 1:00 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Ductwork	REFERENCE:	042000 / 052100 / 233113								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-179	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Plumbing piping installation in progress.			
	SPACE:	122 - FEMALE LOCKER ROOM	SUBJECT:	7/17/24 at 1:01 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000

ITEM	REMARKS	DISCUSSION	PHOTO	
024-180	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress. Ensure the flush valve for the toilet fixture is on the open side of the toilet stall.			
	SPACE:	122 - FEMALE LOCKER ROOM	SUBJECT:	7/17/24 at 1:01 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE:	042000 / 221000

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-181	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.		
	SPACE:	122 - FEMALE LOCKER ROOM	SUBJECT: 7/17/24 at 1:01 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE: 042000 / 221000

ITEM	REMARKS	DISCUSSION	PHOTO
024-182	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.		
	SPACE:	125 - MALE LOCKER ROOM	SUBJECT: 7/17/24 at 1:02 PM
	CATEGORY:	Unit Masonry / Plumbing Piping	REFERENCE: 042000 / 221000

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-183	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress. Ensure the flush valve for the toilet fixture is on the open side of the toilet stall.		
	SPACE: 125 - MALE LOCKER ROOM	SUBJECT: 7/17/24 at 1:02 PM	
	CATEGORY: Unit Masonry / Plumbing Piping	REFERENCE: 042000 / 221000	

ITEM	REMARKS	DISCUSSION	PHOTO
024-184	Unit masonry installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule. Plumbing piping installation in progress.		
	SPACE: 125 - MALE LOCKER ROOM	SUBJECT: 7/17/24 at 1:02 PM	
	CATEGORY: Unit Masonry / Plumbing Piping	REFERENCE: 042000 / 221000	


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-185	<p>Unit masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            Hollow metal door frame installation complete.            Masonry control joint installed.            Align drywall ceiling control joint with masonry control joint.            See RFI #091</p>		
	SPACE:	108 - CIRCULATION	SUBJECT: 7/17/24 at 1:03 PM
	CATEGORY:	Unit Masonry / Hollow Metal Door Frame	REFERENCE: 042000 / 081113

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-186	<p>Unit masonry installation complete.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      Hollow metal door frame installation complete.                      Masonry control joint installed.                      Align drywall ceiling control joint with masonry control joint.                      See RFI #091</p>		
	SPACE:	108 - CIRCULATION	SUBJECT: 7/17/24 at 1:03 PM
	CATEGORY:	Unit Masonry / Hollow Metal Door Frame	REFERENCE: 042000 / 081113

ITEM	REMARKS	DISCUSSION	PHOTO
024-187	<p>Unit masonry installation complete.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule                      Hollow metal door frame installation complete.                      Fire extinguisher cabinet installation in progress.</p>		
	SPACE:	108 - CIRCULATION	SUBJECT: 7/17/24 at 1:03 PM
	CATEGORY:	Unit Masonry / Fire Protection Cabinets	REFERENCE: 042000 / 104413




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-188	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Ductwork installation in progress Fire protection installation in progress.		
SPACE:	108 - CIRCULATION	SUBJECT:	7/17/24 at 1:04 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Fire Suppression / Ductwork	REFERENCE:	042000 / 052100 / 211000 / 233113


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-189	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	154 - WORK SPACE PLUMBING	SUBJECT:	7/17/24 at 1:04 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-190	<p>Masonry installation complete.                      Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.                      Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.                      Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.                      Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.                      Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.                      Provide sealant color samples for initial color selection.</p>			
	SPACE:	002 - SOUTH ELEVATION	SUBJECT:	7/17/24 at 1:05 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-191	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.</p>			
	SPACE:	002 - SOUTH ELEVATION	SUBJECT:	7/17/24 at 1:05 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-192	Cast in place concrete installation complete. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 154 - WORK SPACE PLUMBING	SUBJECT: 7/17/24 at 1:06 PM	
	CATEGORY: Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200	

ITEM	REMARKS	DISCUSSION	PHOTO
024-193	Cast in place concrete installation in progress. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 185 - OPERATIONS WAREHOUSE	SUBJECT: 7/17/24 at 1:06 PM	
	CATEGORY: Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200	


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-194	<p>Cast in place concrete installation complete.            Steel joist framing installation in progress.            Steel framing in progress.            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	<p>SPACE: 155 - WORK SPACE ELECTRICIAN</p>	SUBJECT:		7/17/24 at 1:06 PM
	<p>CATEGORY: Cast in Place Concrete / Steel Joist Framing / Steel Framing</p>	REFERENCE:		033000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-195	Unit masonry installation in progress. Cast in place concrete installation complete. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	004 - WEST ELEVATION	SUBJECT: 7/17/24 at 1:07 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE: 042000 / 033000 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION		PHOTO
024-196	Unit masonry installation in progress. Cast in place concrete installation complete. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	109 - SHARED LOADING DOCK	SUBJECT:	7/17/24 at 1:07 PM
	CATEGORY:	Unit Masonry / Cast in Place Concrete / Steel Framing	REFERENCE:	042000 / 033000 / 051200



## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-197	Cast in place concrete installation in progress. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:08 PM
	CATEGORY:	Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO
024-198	Cast in place concrete installation in progress. Steel joist framing installation in progress. Steel framing in progress. General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:08 PM
	CATEGORY:	Cast in Place Concrete / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-199	<p>Masonry installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule.            Protect adjacent stone and non masonry surfaces from contact with cleaner per specification section 042000 3.14 D.            Provide building stone masonry adjusting and cleaning and protection per specification section 047323 Part 3 Execution adjusting and cleaning.            Cast stone masonry provide adjusting and cleaning per specification section 047200 3.5 at appropriate time in project schedule.            Provide backer rod and / or sealant at all masonry control joints and cast stone head joints.            Provide sealant color samples for initial color selection.            Rough carpentry installation complete.</p>		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:09 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-200	<p>Cast in place concrete installation in progress.            Steel joist framing installation in progress.            Steel framing in progress.            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Masonry materials stored on site.</p>		
	SPACE:	156 - WORK SPACE HVAC	SUBJECT: 7/17/24 at 1:10 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 033000 / 052100 / 051200


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-201	Unit masonry installation complete. Steel joist framing installation in progress. Structural steel framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	156 - WORK SPACE HVAC	SUBJECT: 7/17/24 at 1:10 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-202	Unit masonry installation complete. Steel joist framing installation in progress. Structural steel framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	154 - WORK SPACE PLUMBING	SUBJECT: 7/17/24 at 1:11 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO
024-203	Cast in place concrete installation in progress. Structural steel installation complete.		
	SPACE:	154 - WORK SPACE PLUMBING	SUBJECT: 7/17/24 at 1:11 PM
	CATEGORY:	Cast in Place Concrete / Steel Framing	REFERENCE: 033000 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-204	Cast in place concrete installation in progress. Structural steel installation complete.		
	SPACE:	155 - WORK SPACE ELECTRICIAN	SUBJECT: 7/17/24 at 1:11 PM
	CATEGORY:	Cast in Place Concrete / Steel Framing	REFERENCE: 033000 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO
024-205	Cast in place concrete installation in progress. Structural steel installation complete.		
	SPACE:	156 - WORK SPACE HVAC	SUBJECT: 7/17/24 at 1:11 PM
	CATEGORY:	Cast in Place Concrete / Steel Framing	REFERENCE: 033000 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-206	Cast in place concrete installation in progress. Structural steel installation complete.		
	SPACE: 157 - WORK SPACE CARPENTRY	SUBJECT: 7/17/24 at 1:11 PM	
	CATEGORY: Cast in Place Concrete / Steel Framing	REFERENCE: 033000 / 051200	

ITEM	REMARKS	DISCUSSION	PHOTO
024-207	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE: 226 - MEZZANINE	SUBJECT: 7/17/24 at 1:13 PM	
	CATEGORY: Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-208	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:13 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-209	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:14 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-210	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Structural steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:14 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-211	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Structural steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>		
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT: 7/17/24 at 1:14 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE: 042000 / 052100 / 051200


## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-212	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Structural steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 50%;">229 - MAINTENANCE STORAGE</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 1:15 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Framing</td> <td>REFERENCE:</td> <td>042000 / 052100 / 051200</td> </tr> </table>	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT:	7/17/24 at 1:15 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200		
SPACE:	229 - MAINTENANCE STORAGE	SUBJECT:	7/17/24 at 1:15 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-213	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT:	7/17/24 at 1:15 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200

ITEM	REMARKS	DISCUSSION	PHOTO	
024-214	Structural steel framing in progress.			
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT:	7/17/24 at 1:15 PM
	CATEGORY:	Steel Framing	REFERENCE:	051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-215	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
SPACE:	229 - MAINTENANCE STORAGE	SUBJECT:	7/17/24 at 1:16 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-216	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	229 - MAINTENANCE STORAGE	SUBJECT:	7/17/24 at 1:16 PM
	CATEGORY:	Unit Masonry / Steel Framing	REFERENCE:	042000 / 051200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-217	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:16 PM
	CATEGORY:	Unit Masonry / Steel Framing	REFERENCE:	042000 / 051200




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-218	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
	SPACE:	226 - MEZZANINE	SUBJECT: 7/17/24 at 1:17 PM
	CATEGORY:	Unit Masonry / Steel Framing	REFERENCE: 042000 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-219	Unit masonry installation in progress. Steel joist framing installation in progress. Structural steel framing in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.		
SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:17 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-220	<p>Unit masonry installation in progress.            Steel joist framing installation in progress.            Structural steel framing in progress.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.</p>			
	SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:18 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Framing	REFERENCE:	042000 / 052100 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-221	Unit masonry installation in progress. Steel joist framing installation in progress. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.			
	SPACE:	226 - MEZZANINE	SUBJECT:	7/17/24 at 1:18 PM
	CATEGORY:	Unit Masonry / Steel Framing	REFERENCE:	042000 / 051200


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-222	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>		
	SPACE:	203 - CIRCULATION	SUBJECT: 7/17/24 at 1:19 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE: 042000 / 052100 / 053100 / 221000


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-223	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>			
SPACE:		225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT:	7/17/24 at 1:19 PM
CATEGORY:		Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-224	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 30%;">225 - MECHANICAL / ELECTRICAL ROOM</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 1:20 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100 / 221000</td> </tr> </table>	SPACE:	225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT:	7/17/24 at 1:20 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000		
SPACE:	225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT:	7/17/24 at 1:20 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000								

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-225	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 45%;">223 - LARGE OPEN OFFICE 3</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 5%;">7/17/24 at 1:20 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100 / 221000</td> </tr> </table>	SPACE:	223 - LARGE OPEN OFFICE 3	SUBJECT:	7/17/24 at 1:20 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000		
SPACE:	223 - LARGE OPEN OFFICE 3	SUBJECT:	7/17/24 at 1:20 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000								




## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-226	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td style="width: 50%;">225 - MECHANICAL / ELECTRICAL ROOM</td> <td style="width: 25%;">SUBJECT:</td> <td style="width: 20%;">7/17/24 at 1:20 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100 / 221000</td> </tr> </table>	SPACE:	225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT:	7/17/24 at 1:20 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000		
SPACE:	225 - MECHANICAL / ELECTRICAL ROOM	SUBJECT:	7/17/24 at 1:20 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000								


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-227	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Plumbing piping for roof drain installation in progress.		
	SPACE:	203 - CIRCULATION	SUBJECT: 7/17/24 at 1:21 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE: 042000 / 052100 / 053100 / 221000


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO								
024-228	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Unit skylight roof curb installation in progress.</p>										
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">SPACE:</td> <td>201 - CIRCULATION</td> <td style="width: 25%;">SUBJECT:</td> <td>7/17/24 at 1:21 PM</td> </tr> <tr> <td>CATEGORY:</td> <td>Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights</td> <td>REFERENCE:</td> <td>042000 / 052100 / 053100 / 086200</td> </tr> </table>	SPACE:	201 - CIRCULATION	SUBJECT:	7/17/24 at 1:21 PM	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE:	042000 / 052100 / 053100 / 086200		
SPACE:	201 - CIRCULATION	SUBJECT:	7/17/24 at 1:21 PM								
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE:	042000 / 052100 / 053100 / 086200								


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-229	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Unit skylight roof curb installation in progress.		
SPACE:	201 - CIRCULATION	SUBJECT:	7/17/24 at 1:21 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE:	042000 / 052100 / 053100 / 086200


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-230	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Unit skylight roof curb installation in progress.		
	SPACE:	201 - CIRCULATION	SUBJECT: 7/17/24 at 1:22 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE: 042000 / 052100 / 053100 / 086200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-231	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Unit skylight roof curb installation in progress.</p>		
SPACE:	201 - CIRCULATION	SUBJECT:	7/17/24 at 1:22 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE:	042000 / 052100 / 053100 / 086200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-232	Unit masonry installation complete. Steel joist framing installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required. Unit skylight roof curb installation in progress.		
SPACE:	201 - CIRCULATION	SUBJECT:	7/17/24 at 1:22 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE:	042000 / 052100 / 053100 / 086200

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-233	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Unit skylight roof curb installation in progress.</p>		
	SPACE:	201 - CIRCULATION	SUBJECT: 7/17/24 at 1:23 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Unit Skylights	REFERENCE: 042000 / 052100 / 053100 / 086200




# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-234	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>			
	SPACE:	204 - KITCHEN	SUBJECT:	7/17/24 at 1:23 PM
	CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000


# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-235	<p>Unit masonry installation complete.            Steel joist framing installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.            Plumbing piping for roof drain installation in progress.</p>		
SPACE:	204 - KITCHEN	SUBJECT:	7/17/24 at 1:24 PM
CATEGORY:	Unit Masonry / Steel Joist Framing / Steel Decking / Plumbing Piping	REFERENCE:	042000 / 052100 / 053100 / 221000


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-236	<p>Unit masonry installation in progress.            Structural steel framing installation in progress.            Coordinate balcony tube steel location with approved stair shop drawing submittal.            Do not pour concrete floor slab until balcony tube steel is coordinated with approved stair shop drawings.</p>		
	SPACE:	201 - CIRCULATION	SUBJECT: 7/17/24 at 1:24 PM
	CATEGORY:	Unit Masonry / Steel Framing	REFERENCE: 042000 / 051200


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-237	<p>Unit masonry installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            Rough carpentry wood blocking installation in progress.            Ensure wood blocking is properly secured.            Steel decking fastener pattern appears to be installed in general compliance with construction documents.</p>			
	SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:27 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE:	042000 / 053100 / 061053


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-238	<p>Unit masonry installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            Rough carpentry wood blocking installation in progress.            Ensure wood blocking is properly secured.            Steel decking fastener pattern appears to be installed in general compliance with construction documents.            RTU curb installation is in progress.</p>			
SPACE:		009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:27 PM
CATEGORY:		Unit Masonry / Steel Decking / Rough Carpentry / Rooftop Air Conditioning	REFERENCE:	042000 / 053100 / 061053 / 237416


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-239	Unit masonry installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Steel decking fastener pattern appears to be installed in general compliance with construction documents. RTU curb installation is in progress.			
SPACE:		009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:28 PM
CATEGORY:		Unit Masonry / Steel Decking / Rooftop Air Conditioning	REFERENCE:	042000 / 053100 / 237416


## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION		PHOTO
024-240	Unit masonry installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Steel decking fastener pattern appears to be installed in general compliance with construction documents. RTU curb installation is in progress.			
SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:28 PM	
CATEGORY:	Unit Masonry / Steel Decking / Rooftop Air Conditioning	REFERENCE:	042000 / 053100 / 237416	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-241	<p>Unit masonry installation complete.            Steel roof decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            Steel decking fastener pattern appears to be installed in general compliance with construction documents.            Rough carpentry wood blocking installation in progress.            Ensure wood blocking is properly fastened.</p>		
SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:28 PM
CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE:	042000 / 053100 / 061053




# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-242	<p>Unit masonry installation complete.            Steel decking installation complete.            Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule            Steel decking fastener pattern appears to be installed in general compliance with construction documents.            Several fasteners at steel angle perimeter are loose. Ensure all fasteners are properly secured.</p>			
	SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:29 PM
	CATEGORY:	Unit Masonry / Steel Decking	REFERENCE:	042000 / 053100

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-243	Unit masonry installation complete. Steel decking installation complete. Provide unit masonry repairing, pointing, and cleaning per specification section 042000 at appropriate time in project schedule Steel decking fastener pattern appears to be installed in general compliance with construction documents. Several fasteners at steel angle perimeter are loose. Ensure all fasteners are properly secured.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:29 PM
	CATEGORY:	Unit Masonry / Steel Decking	REFERENCE: 042000 / 053100

ITEM	REMARKS	DISCUSSION	PHOTO
024-244	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:29 PM
	CATEGORY:	Steel Decking	REFERENCE: 053100

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-245	<p>Unit masonry installation complete.            Steel roof decking installation complete.            Steel decking fastener pattern appears to be installed in general compliance with construction documents.            Rough carpentry wood blocking installation in progress.            Ensure wood blocking is properly fastened.</p>		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:30 PM	
	CATEGORY: Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE: 042000 / 053100 / 061053	

ITEM	REMARKS	DISCUSSION	PHOTO
024-246	<p>Rough carpentry wood blocking installation in progress.            Ensure wood blocking is properly fastened.</p>		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:30 PM	
	CATEGORY: Rough Carpentry	REFERENCE: 061053	


# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO	
024-247	<p>Unit masonry installation complete.            Steel roof decking installation complete.            Steel decking fastener pattern appears to be installed in general compliance with construction documents.            Rough carpentry wood blocking installation in progress.            Ensure wood blocking is properly fastened.</p>			
	SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:31 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE:	042000 / 053100 / 061053

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-248	<p>Unit masonry installation complete.                      Steel roof decking installation complete.                      Steel decking fastener pattern appears to be installed in general compliance with construction documents.                      Rough carpentry wood blocking installation in progress.                      Ensure wood blocking is properly fastened.</p>		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:31 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE: 042000 / 053100 / 061053

ITEM	REMARKS	DISCUSSION	PHOTO
024-249	<p>Unit masonry installation complete.                      Steel joist framing installation complete.                      Steel decking installation complete.                      General: Provide touch up painting of steel joist framing per specification section 052100 3.3 B if or as required.                      Unit skylight roof curb installation in progress.</p>		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:32 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry / Unit Skylights	REFERENCE: 042000 / 053100 / 061053 / 086200

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-250	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Fasteners are missing at roof deck lap between skylight and parapet wall.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:32 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	

ITEM	REMARKS	DISCUSSION	PHOTO
024-251	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Fasteners are missing at roof deck lap between skylight and parapet wall. Ensure all roof deck panels are properly secured.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:33 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO				
024-252	Rough carpentry wood blocking installation in progress. Ensure wood blocking is properly fastened.						
				SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:33 PM
				CATEGORY:	Rough Carpentry	REFERENCE:	061053

ITEM	REMARKS	DISCUSSION	PHOTO				
024-253	Unit masonry installation complete. Rough carpentry wood blocking installation in progress. Ensure wood blocking is properly fastened.						
				SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:36 PM
				CATEGORY:	Unit Masonry / Rough Carpentry	REFERENCE:	042000 / 061053

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-254	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Ensure all roof deck panels are properly secured.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:37 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	


ITEM	REMARKS	DISCUSSION	PHOTO
024-255	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Ensure all roof deck panels are properly secured. Ensure all steel perimeter angle steel fasteners are properly secured.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:38 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	



# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-256	Unit masonry installation complete. Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Rough carpentry wood blocking installation in progress. Ensure wood blocking is properly fastened.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:39 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE: 042000 / 053100 / 061053

ITEM	REMARKS	DISCUSSION	PHOTO
024-257	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Roof drain installation in progress		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:39 PM
	CATEGORY:	Steel Decking / Storm Piping Specialties	REFERENCE: 053100 / 221319

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-258	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Roof drain installation in progress		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:40 PM	
	CATEGORY: Steel Decking / Storm Piping Specialties	REFERENCE: 053100 / 221319	

ITEM	REMARKS	DISCUSSION	PHOTO
024-259	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Ensure all roof deck panels are properly secured. Ensure all steel perimeter angle steel fasteners are properly secured. Roof deck appears to be bucking at a few locations.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:41 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-260	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Ensure all roof deck panels are properly secured.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:41 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	

ITEM	REMARKS	DISCUSSION	PHOTO
024-261	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Ensure all roof deck panels are properly secured.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:41 PM	
	CATEGORY: Steel Decking	REFERENCE: 053100	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-262	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Roof drain installation in progress		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:43 PM	
	CATEGORY: Steel Decking / Storm Piping Specialties	REFERENCE: 053100 / 221319	

ITEM	REMARKS	DISCUSSION	PHOTO
024-263	Unit masonry installation complete. Steel decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. RTU curb installation is in progress.		
	SPACE: 009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:44 PM	
	CATEGORY: Unit Masonry / Steel Decking / Rooftop Air Conditioning	REFERENCE: 042000 / 053100 / 238123	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO	
024-264	Unit masonry installation complete. Steel decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. RTU curb installation is in progress.			
	SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:44 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rooftop Air Conditioning	REFERENCE:	042000 / 053100 / 238123

ITEM	REMARKS	DISCUSSION	PHOTO	
024-265	RTU curb installation is in progress.			
	SPACE:	009 - ROOF - OFFICE	SUBJECT:	7/17/24 at 1:45 PM
	CATEGORY:	Rooftop Air Conditioning	REFERENCE:	238123

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-266	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Roof drain installation in progress		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:45 PM
	CATEGORY:	Steel Decking / Storm Piping Specialties	REFERENCE: 053100 / 221319

ITEM	REMARKS	DISCUSSION	PHOTO
024-267	Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Ensure all metal roof panels are properly secure. Roof panel next to sky light is missing fasteners.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:46 PM
	CATEGORY:	Steel Decking	REFERENCE: 053100

# Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-268	Unit masonry installation complete. Steel roof decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. Rough carpentry wood blocking installation in progress. Ensure wood blocking is properly fastened.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:47 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rough Carpentry	REFERENCE: 042000 / 053100 / 061053


ITEM	REMARKS	DISCUSSION	PHOTO
024-269	Unit masonry installation complete. Rough carpentry wood blocking installation in progress. Ensure wood blocking is properly fastened.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:47 PM
	CATEGORY:	Unit Masonry / Rough Carpentry	REFERENCE: 042000 / 0061053

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-270	Unit masonry installation complete. Steel decking installation complete. Steel decking fastener pattern appears to be installed in general compliance with construction documents. RTU curb installation is in progress.		
	SPACE:	009 - ROOF - OFFICE	SUBJECT: 7/17/24 at 1:48 PM
	CATEGORY:	Unit Masonry / Steel Decking / Rooftop Air Conditioning	REFERENCE: 042000 / 053100 / 237416


ITEM	REMARKS	DISCUSSION	PHOTO
024-271	Masonry materials stored on site.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:52 PM
	CATEGORY:	Unit Masonry	REFERENCE: 042000


ITEM	REMARKS	DISCUSSION	PHOTO
024-272	Cast in place concrete for transformer pad installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:52 PM
	CATEGORY:	Cast in Place Concrete	REFERENCE: 033000



## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-273	Structural steel stored on site. Modular block wall installation complete.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:53 PM
	CATEGORY:	Steel Framing / Modular Block Retaining Wall	REFERENCE: 051200 / 323223

ITEM	REMARKS	DISCUSSION	PHOTO
024-274	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Modular block retaining wall installation complete.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:54 PM
	CATEGORY:	Asphalt Paving / Modular Block Retaining Wall	REFERENCE: 321216 / 323223

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-275	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Modular block retaining wall installation complete.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:54 PM
	CATEGORY:	Asphalt Paving / Modular Block Retaining Wall	REFERENCE: 321216 / 323223


ITEM	REMARKS	DISCUSSION	PHOTO
024-276	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Modular block retaining wall installation complete.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:54 PM
	CATEGORY:	Asphalt Paving / Modular Block Retaining Wall	REFERENCE: 321216 / 323223

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-277	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Exterior lighting installation in progress.		
	SPACE: 006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:54 PM	
	CATEGORY: Asphalt Paving / Exterior Lighting	REFERENCE: 321216 / 265600	


ITEM	REMARKS	DISCUSSION	PHOTO
024-278	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:55 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	

ITEM	REMARKS	DISCUSSION	PHOTO
024-279	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:55 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-280	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Exterior lighting installation in progress. Modular block retaining wall installation complete.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:56 PM
	CATEGORY:	Asphalt Paving / Modular Block Retaining Wall / Exterior Lighting	REFERENCE: 321216 / 265600 / 323223


ITEM	REMARKS	DISCUSSION	PHOTO
024-281	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Exterior lighting installation in progress.		
	SPACE:	006 - SITE - SOUTH	SUBJECT: 7/17/24 at 1:56 PM
	CATEGORY:	Asphalt Paving / Exterior Lighting	REFERENCE: 321216 / 265600

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-282	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 1:56 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	


ITEM	REMARKS	DISCUSSION	PHOTO
024-283	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 1:57 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	


ITEM	REMARKS	DISCUSSION	PHOTO
024-284	Cast in place concrete at fueling island installation in progress.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 1:57 PM	
	CATEGORY: Cast in Place Concrete	REFERENCE: 033000	

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-285	Cast in place concrete at fueling island installation in progress.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:57 PM
	CATEGORY:	Cast in Place Concrete	REFERENCE: 033000


ITEM	REMARKS	DISCUSSION	PHOTO
024-286	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:57 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216


ITEM	REMARKS	DISCUSSION	PHOTO
024-287	Cast in place concrete at fueling island installation in progress. Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:58 PM
	CATEGORY:	Cast in Place Concrete / Asphalt Paving	REFERENCE: 033000 / 321216

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-288	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 1:58 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	


ITEM	REMARKS	DISCUSSION	PHOTO
024-289	Cast in place concrete at fueling tank area installation in progress. Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 1:59 PM	
	CATEGORY: Cast in Place Concrete	REFERENCE: 033000	


ITEM	REMARKS	DISCUSSION	PHOTO
024-290	Storm sewer detention pond installation complete.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 1:59 PM	
	CATEGORY: Storm Sewage System	REFERENCE: 334113	

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-291	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 1:59 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216


ITEM	REMARKS	DISCUSSION	PHOTO
024-292	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:00 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216


ITEM	REMARKS	DISCUSSION	PHOTO
024-293	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 2:00 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216




# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-294	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 2:01 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	


ITEM	REMARKS	DISCUSSION	PHOTO
024-295	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 2:01 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	


ITEM	REMARKS	DISCUSSION	PHOTO
024-296	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Exterior lighting installation in progress.		
	SPACE: 005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:02 PM	
	CATEGORY: Asphalt Paving / Exterior Lighting	REFERENCE: 321216 / 265600	

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-297	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 2:04 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	


ITEM	REMARKS	DISCUSSION	PHOTO
024-298	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 2:04 PM	
	CATEGORY: Asphalt Paving	REFERENCE: 321216	

ITEM	REMARKS	DISCUSSION	PHOTO
024-299	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Modular block retaining wall installation complete.		
	SPACE: 008 - SITE - WEST	SUBJECT: 7/17/24 at 2:05 PM	
	CATEGORY: Asphalt Paving / Modular Block Retaining Wall	REFERENCE: 321216 / 323223	

## Site Visit - Construction Observation


DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO				
024-300	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Exterior lighting installation in progress. Modular block retaining wall installation complete.						
				SPACE:	008 - SITE - WEST	SUBJECT:	7/17/24 at 2:05 PM
				CATEGORY:	Asphalt Paving / Modular Block Retaining Wall	REFERENCE:	321216 / 323223


ITEM	REMARKS	DISCUSSION	PHOTO				
024-301	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216. Exterior lighting installation in progress. Modular block retaining wall installation complete.						
				SPACE:	008 - SITE - WEST	SUBJECT:	7/17/24 at 2:05 PM
				CATEGORY:	Asphalt Paving / Modular Block Retaining Wall	REFERENCE:	321216 / 323223

# Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-302	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:06 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216


ITEM	REMARKS	DISCUSSION	PHOTO
024-303	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 2:06 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216


ITEM	REMARKS	DISCUSSION	PHOTO
024-304	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 2:06 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024


ITEM	REMARKS	DISCUSSION	PHOTO
024-305	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:06 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216


ITEM	REMARKS	DISCUSSION	PHOTO
024-306	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	008 - SITE - WEST	SUBJECT: 7/17/24 at 2:07 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

ITEM	REMARKS	DISCUSSION	PHOTO
024-307	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:10 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

## Site Visit - Construction Observation

DATE: 7/17/2024  
 VISIT NAME: Construction  
 Progress Site Visit  
 REPORT NO: 024

ITEM	REMARKS	DISCUSSION	PHOTO
024-308	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:11 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

ITEM	REMARKS	DISCUSSION	PHOTO
024-309	Asphalt installation in progress. Install asphalt paving per part 3 execution specification section 321216.		
	SPACE:	005 - SITE - NORTH	SUBJECT: 7/17/24 at 2:12 PM
	CATEGORY:	Asphalt Paving	REFERENCE: 321216

**TO:**

Carrie Hooten	Kenton County School District
Kevin Pfefferman	Kenton County School District
Matthew Rigg	Kenton County School District
Brian Vanover	Kenton County School District

**COPIES:**

Seth Mittle	GRW
David Vaught	GRW
Todd Cantrell	GRW
Mike McReynolds	GRW
Jon Sheppard	GRW
Jim Adams	Facility Commissioning Group
Adolph Zell	Morel Construction
Anthony Berkemeier	Morel Construction