

9242

**KISTA - 2011 Used School Bus Inventory Form**Model: Year: 1992 District: NELSON CO☐ Ford☐ Chevrolet☒ International☐ Other \_\_\_\_\_Vehicle Identification Number (VIN): 1HVBBNPN2NH435669Passenger Capacity: 66

Body Type:

☐ Ward☐ Blue Bird☐ Carpenter☒ Other WAYNE

Tire Sizes:

Front: 265/75R22.5Rear: 265/75R22.5

Tire Quality (Check One):

Good Fair Poor

☒ ☐ ☐☒ ☐ ☐

Engine Type:

☐ Gasoline☒ DieselBus Mileage: 217599

Engine Make:

☐ Ford☐ Chevrolet☒ International☐ Other \_\_\_\_\_Brake Type: AIRBus Side Number: 9242

Bus Operating Condition:

☒ Operable☐ Inoperable

Engine Size:

Number Cylinders: 6Size (Cubic Inches or Liters): DTA 360

Transmission Type:

☒ Automatic☐ Standard

Check the statement which generally best describes this bus unit:

☒ Bus is well maintained and is in good operating condition.☐ Bus is well maintained and is in fair operating condition.☐ Bus is well maintained, but is in poor operating condition.☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:

☐ NoneExplain: Sheet Metal Cut on Rt Side (Small Cut)

List any mechanical defects you are currently aware of the drivetrain:

☒ None

Explain: \_\_\_\_\_

This bus can be inspected by calling:

Name: Jeff MarcheseTelephone: (502) 249-1390

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

## KISTA - 2011 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 1992 District: Nelson Co  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
☒ International  
\_\_\_\_\_  
Other \_\_\_\_\_ Vehicle Identification Number (VIN): 1HVBBNPNONH 435668  
Passenger Capacity: 66

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward  
\_\_\_\_\_  
Blue Bird Front: 265/75R22.5 ☒ Good ☐ Fair ☐ Poor  
\_\_\_\_\_  
Carpenter  
☒ Other WAYNE Rear: 265/75R22.5 ☒ Good ☐ Fair ☐ Poor

Engine Type: \_\_\_\_\_ Bus Mileage: 123 736  
\_\_\_\_\_  
Gasoline  
☒ Diesel

Engine Make: \_\_\_\_\_ Brake Type: AIR Bus Side Number: 9243  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
☒ International Bus Operating Condition:  
\_\_\_\_\_  
Other \_\_\_\_\_ ☒ Operable  
Inoperable

Engine Size: \_\_\_\_\_ Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): DTA 360 \_\_\_\_\_ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

**List any physical damage to the body of the bus:**

Explain:

Left Rear Corner Smashed in (Top Side) ☐ None

**List any mechanical defects you are currently aware of the drivetrain:**

Explain:

☒ None

**This bus can be inspected by calling:**

Name: Jeff Marchese

Telephone: (502) 249-1390

**PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.**

# KISTA - 2011 Used School Bus Inventory Form

Model:

☐ Ford  
☐ Chevrolet  
☒ International  
☐ Other \_\_\_\_\_

Year: 1995 District: NELSON CO

Vehicle Identification Number (VIN): 1HVBBAAN 3SH 206477

Passenger Capacity: 66

Body Type:

☐ Ward  
☐ Blue Bird  
☒ Carpenter  
☐ Other \_\_\_\_\_

Tire Sizes:

Front: 265/75R22.5

Rear: 265/75R22.5

Tire Quality (Check One):

Good	Fair	Poor
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Engine Type:

☐ Gasoline  
☒ Diesel

Bus Mileage: 173321

Engine Make:

☐ Ford  
☐ Chevrolet  
☒ International  
☐ Other \_\_\_\_\_

Brake Type: AIR

Bus Side Number: 9563

Bus Operating Condition:

☒ Operable  
☐ Inoperable

Engine Size:

Number Cylinders: 6  
Size (Cubic Inches or Liters): DT466

Transmission Type:

☒ Automatic  
☐ Standard

Check the statement which generally best describes this bus unit:

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus:

Explain:

☐ None  
Right Rear Corner Smashed in (UPPER SIDE)

List any mechanical defects you are currently aware of the drivetrain:

Explain:

☒ None

This bus can be inspected by calling:

Name: Jeff Marchese

Telephone: (502) 249-1390

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.



## KISTA - 2011 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 1995 District: Nelson Co  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
☒ International  
\_\_\_\_\_  
Other \_\_\_\_\_ Vehicle Identification Number (VIN): 1HVBBAAN5SH206478  
\_\_\_\_\_  
Passenger Capacity: 66

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
\_\_\_\_\_  
Ward  
\_\_\_\_\_  
Blue Bird Front: 26/75R22.5 ☒ Good ☐ Fair ☐ Poor  
\_\_\_\_\_  
☒ Carpenter Rear: 26/75R22.5 ☒ ☐ ☐  
\_\_\_\_\_  
Other \_\_\_\_\_

Engine Type: \_\_\_\_\_ Bus Mileage: 239,000  
\_\_\_\_\_  
Gasoline  
\_\_\_\_\_  
☒ Diesel

Engine Make: \_\_\_\_\_ Brake Type: AIR Bus Side Number: 9562  
\_\_\_\_\_  
Ford  
\_\_\_\_\_  
Chevrolet  
\_\_\_\_\_  
☒ International Bus Operating Condition:  
\_\_\_\_\_  
Other \_\_\_\_\_ ☒ Operable  
\_\_\_\_\_  
Inoperable

Engine Size: \_\_\_\_\_ Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): DT466 \_\_\_\_\_  
Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☒ None  
Explain: \_\_\_\_\_

List any mechanical defects you are currently aware of the drivetrain: ☐ None  
Explain: \_\_\_\_\_

**This bus can be inspected by calling:**

Name: Jeff Marchese

Telephone: (502) 249-1390

**PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.**

# KISTA - 2011 Used School Bus Inventory Form

Model: \_\_\_\_\_ Year: 1995 District: Nelson County  
\_\_\_\_\_  
☐ Ford  
☐ Chevrolet  
☒ International  
☐ Other \_\_\_\_\_ Vehicle Identification Number (VIN): 1HVBBAAL35H224427  
Passenger Capacity: 20

Body Type: \_\_\_\_\_ Tire Sizes: \_\_\_\_\_ Tire Quality (Check One):  
☒ Ward  
\_\_\_\_\_  
☐ Blue Bird Front: 265/75R22.5 ☒ Good ☐ Fair ☐ Poor  
\_\_\_\_\_  
☐ Carpenter Rear: 265/75R22.5 ☒ Good ☐ Fair ☐ Poor  
\_\_\_\_\_  
☐ Other \_\_\_\_\_

Engine Type: \_\_\_\_\_ Bus Mileage: 222174  
\_\_\_\_\_  
☐ Gasoline  
☒ Diesel

Engine Make: \_\_\_\_\_ Brake Type: AIR Bus Side Number: 9507  
\_\_\_\_\_  
☐ Ford  
\_\_\_\_\_  
☐ Chevrolet  
☒ International Bus Operating Condition:  
\_\_\_\_\_  
☐ Other \_\_\_\_\_ ☒ Operable  
☐ Inoperable

Engine Size: \_\_\_\_\_ Transmission Type:  
Number Cylinders: 6 ☒ Automatic  
Size (Cubic Inches or Liters): D7466 ☐ Standard

**Check the statement which generally best describes this bus unit:**

- ☐ Bus is well maintained and is in good operating condition.  
☒ Bus is well maintained and is in fair operating condition.  
☐ Bus is well maintained, but is in poor operating condition.  
☐ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: ☐ None  
Explain: \_\_\_\_\_

List any mechanical defects you are currently aware of the drivetrain: ☐ None  
Explain: Transmission Front Pump Seal Leaking

This bus can be inspected by calling:

Name: Jeff Marchese

Telephone: (502) 249-1390

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.