

## KISTA - 2026 Used School Bus Inventory Form

**Model:** \_\_\_\_\_ **Year:** 2006 **District:** Dawson Springs Independent Schools  
\_\_\_\_\_  
\_\_\_\_\_  
 Ford  
 Chevrolet **Vehicle Identification Number (VIN):** AXDC66CV12007  
 International  
 Other Freightliner **Passenger Capacity:** 66

**Body Type:** \_\_\_\_\_ **Tire Sizes:** \_\_\_\_\_ **Tire Quality (Check One):**  
\_\_\_\_\_  
\_\_\_\_\_  
 Ward  
 Blue Bird Front: 295 / 75 / 22.5 Good Fair Poor  
 Carpenter  
 Other Thomas Rear: 295 / 75 / 22.5

**Engine Type:** \_\_\_\_\_ **Bus Mileage:** Unknown / Dash Cluster Inoperable  
 Gasoline  
 Diesel

**Engine Make:** Air **Brake Type:** \_\_\_\_\_ **Bus Side Number:** 0503  
\_\_\_\_\_  
\_\_\_\_\_  
 Ford  
 Chevrolet **Bus**

**Operating Condition:**  
 International  Operable  
 Other Caterpillar C7  Inoperable

**Engine Size:** \_\_\_\_\_ **Transmission Type:** \_\_\_\_\_  
Number Cylinders: 6  Automatic  
Size (Cubic Inches or Liters): 7.2  Standard

**Check the statement which generally best describes this bus unit:**

- Bus is well maintained and is in good operating condition.
- Bus is well maintained and is in fair operating condition.
- Bus is well maintained, but is in poor operating condition.
- Bus is inoperable and can be used for parts.

**List any physical damage to the body of the bus:**  None

Explain:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**List any mechanical defects you are currently aware of the drivetrain:**  None

Explain:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**This bus can be inspected by calling:**

Name: Leonard Whalen, Superintendent

Telephone: (270)797-3811

**PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.**

**If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.**