

KISTA - 2026 Used School Bus Inventory Form

Model: _____ **Year:** 2006 **District:** Dawson Springs Independent Schools

 Ford
 Chevrolet **Vehicle Identification Number (VIN):** AXDCX6CV12012
 International
 Other Freightliner **Passenger Capacity:** 66

Body Type: _____ **Tire Sizes:** _____ **Tire Quality (Check One):**

 Ward
 Blue Bird Front: 295 / 75 / 22.5 Good Fair Poor
 Carpenter
 Other Thomas Rear: 295 / 75 / 22.5

Engine Type: _____ **Bus Mileage:** 112,570

 Gasoline
 Diesel

Engine Make: Air **Brake Type:** _____ **Bus Side Number:** 0508

 Ford
 Chevrolet **Bus**

Operating Condition:
 International Operable
 Other Caterpillar C7 Inoperable

Engine Size: _____ **Transmission Type:**
Number Cylinders: 6 Automatic
Size (Cubic Inches or Liters): 7.2 Standard

Check the statement which generally best describes this bus unit:

- Bus is well maintained and is in good operating condition.
- Bus is well maintained and is in fair operating condition.
- Bus is well maintained, but is in poor operating condition.
- Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: None

Explain:

List any mechanical defects you are currently aware of the drivetrain: None

Explain:

This bus can be inspected by calling:

Name: Leonard Whalen, Superintendent

Telephone: (270)797-3811

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.

If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.