KISTA - 2026 Used School Bus Inventory Form

Model: **Year:** 2007 **District:** Dawson Springs Independent Schools

_____ Ford
_____ Chevrolet **Vehicle Identification Number (VIN):** AXDC77CX09950
_____ International
__X__ Other Freightliner **Passenger Capacity:** 66

Body Type:
_____ Ward
_____ Blue Bird
_____ Carpenter
__X__ Other Thomas

Tire Sizes:
Front: 295 / 75 / 22.5
Rear: 295 / 75 / 22.5

Tire Quality (Check One):

	Good	Fair	Poor
Front: 295 / 75 / 22.5	□	X	□
Rear: 295 / 75 / 22.5	□	X	□

Engine Type:
_____ Gasoline
__X__ Diesel

Bus Mileage: 103,867

Engine Make: **Brake Type:** Air **Bus Side Number:** 0610

_____ Ford
_____ Chevrolet
_____ International
__X__ Other Caterpillar C7

Bus Operating Condition:
_____ Operable
__X__ Inoperable

Engine Size:
Number Cylinders: 6
Size (Cubic Inches or Liters): 7.2

Transmission Type:
__X__ Automatic
_____ Standard

Check the statement which generally best describes this bus unit:

□ Bus is well maintained and is in good operating condition.
□ Bus is well maintained and is in fair operating condition.
X Bus is well maintained, but is in poor operating condition.
□ Bus is inoperable and can be used for parts.

List any physical damage to the body of the bus: □ None

Explain: Bottom step of stairway is broken; Door air valve removed; Hood is partially secured

List any mechanical defects you are currently aware of the drivetrain: X None

Explain:

This bus can be inspected by calling:

Name: Leonard Whalen, Superintendent

Telephone: (270)797-3811

PLEASE COMPLETE THIS FORM IN ITS ENTIRETY.
If you have questions about this form, please contact Lincoln Theinert at 800-255-0795.